	Schedule G- Sp	ecifications
	Description	Proposed
	1 FOUNDATION	Isolated/ Combined footing
	2 SUPER STRUCTURE	RCC Framed structure
	BLOCK WORK	solid concrete block work masonry walls
COMMON AREA:	4 FLOORING Waiting lounge /reception /GF Lobby /lift lobby	Marble/Granite
COMMON AREA:	Staircases	Cement step tiles/Vitrified tiles
	Other lift Lobby and corridors (upper)	Vitrified tiles 600 x600 mm
	Service lift lobby	vitrified tiles
	MEP rooms	IPS floor with smooth finish
	Terrace	clay tile with membrane water proofing
	Basement	VDF/IPS with smooth finish
RECREATION HOUSE (club):	Lobby	vitrified tiles/ restile or equivalent
	Gym	vinyl flooring
	Multi purpose hall	vitrified tiles
UNITS:	Living / Dining / Family / Foyer	Vitrified tiles 600 x600 mm
	Master Bed room	laminate wooden flooring
	Other Bed rooms	Vitrified tiles 600 x600 mm
	Balcony / deck	anti skid ceramic tiles
	Master Bed room toilet	anti skid ceramic tiles
	Other Toilets and powder room	anti skid ceramic tiles
	Kitchen	Vitrified tiles 600 x600 mm(same as living)
	Utility E WALL DADO	same as kitchen
	M.bedroom toilet	coramic tile cladding up to false soiling beight
	Other toilets and powder room	ceramic tile cladding up to false ceiling height.  ceramic tile cladding up to false ceiling height.
	Other tollets and powder room  6 KITCHEN	ceranne the clauding up to raise tennig height.
	a. Counter	provision for modular kitchen
	a. counter	<u>'</u>
	b. Plumbing/Electrical	Plumbing point provision for water purifier/sink, washing machine. Electrical point provision for water purifier point, refrigerator point, microwave point, washing machine point, electrical point for instant geyser, hob point, chimney
		point, mixer point.
	7 TOILETS:	pome, mixer pome.
,	CP Fittings	Jaguar/Ess Ess or equivalent
	Sanitary fixtures	Parryware or equivalent
	Accessories- Soap tray, robe hook, Toilet paper holder,	soap tray, concealed diverter, toilet paper holder, basin mixer, robe hook,
	towel rod	towel rod, health faucet
	Master Bathroom	Glass partition for shower at extra cost as per client request.
	EWC	Wall mounted WC of Hindware/ Parryware or equivalent
	False Ceiling	Calcium silicate/syntex
	DOORS:	
	Main entry door - to unit	Teakwood frame, Natural PU lacquer polish shutter and architrave
	Bedroom doors	Hardwood frame, enamel paint shutter and architrave
	Toilet door	Hardwood frame, enamel paint shutter and architrave
	Balcony door	UPVC/Aluminium with bug screen 3 track
	shaft door  RAILING	Powder coated MS door
	Balcony railing	MS railing
	IStair Railing (Common areas)	TIVIN PAILING
11	Stair Railing (Common areas)	MS railing UPVC/ Aluminium with bug screen and safety grill
	WINDOWS	UPVC/ Aluminium with bug screen and safety grill
	<u> </u>	
	WINDOWS 1 PAINTING & FINISHES	UPVC/ Aluminium with bug screen and safety grill
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish	UPVC/ Aluminium with bug screen and safety grill
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings	UPVC/ Aluminium with bug screen and safety grill  External texture paint
	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion
	WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint emulsion paint Oil bound distemper
	D WINDOWS 1 PAINTING & FINISHES 2 a) Exterior finish 3 b) Internal ceilings 3 common area 4 lift Lobby 5 staircase, utility area and service area 5 basement 6 unit ceiling 7 c) Internal walls	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  emulsion paint
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper  Cement paint
	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  Oil bound distemper  cement paint  acrylic emulsion paint
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper  Cement paint
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line b)Water supply	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  emulsion paint  Oil bound distemper  Cement paint  acrylic emulsion paint  synthetic enamel paint  UPVC  CPVC for water supply
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works 2 WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  oil bound distemper  cemulsion paint  oil bound distemper  Cement paint  acrylic emulsion paint  synthetic enamel paint  UPVC  CPVC for water supply  UPVC
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line b)Water supply	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint  Oil bound distemper  economy range emulsion  acrylic emulsion paint  emulsion paint  oil bound distemper  Cement paint  acrylic emulsion paint  synthetic enamel paint  UPVC  CPVC for water supply
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings  common area lift Lobby  staircase, utility area and service area basement unit ceiling c) Internal walls  common area lift Lobby  staircase, utility area and service area basement unit walls  d) steel works  WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint Oil bound distemper Cemulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings  common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint emulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water Treatment- STP
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works  2 WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage External piping	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water Treatment- STP PVC
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish  b) Internal ceilings  common area  lift Lobby  staircase, utility area and service area  basement  unit ceiling  c) Internal walls  common area  lift Lobby  staircase, utility area and service area  basement  unit walls  d) steel works  2 WATER SUPPLY/DRAINAGE  a) Sewage Line  b) Water supply  External piping  Internal piping  Flushing  c) Drainage  External piping  Internal piping  Internal piping  Internal piping	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint Oil bound distemper Cement paint oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water Treatment- STP PVC PVC
1:	D WINDOWS  1 PAINTING & FINISHES  a) Exterior finish  b) Internal ceilings  common area  lift Lobby  staircase, utility area and service area  basement  unit ceiling  c) Internal walls  common area  lift Lobby  staircase, utility area and service area  basement  unit walls  d) steel works  2 WATER SUPPLY/DRAINAGE  a) Sewage Line  b) Water supply  External piping  Internal piping  Flushing  c) Drainage  External piping  Internal piping	UPVC/ Aluminium with bug screen and safety grill  External texture paint  emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint Oil bound distemper Cement paint oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water Treatment- STP PVC PVC
1:	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works d) steel works d) WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage External piping Internal piping Internal piping Internal piping Internal piping AIR CONDITIONING Living Master Bedroom	UPVC / Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper cement paint  Oil bound distemper Cement paint  oil bound distemper  Cement paint acrylic emulsion paint synthetic enamel paint  UPVC  CPVC for water supply UPVC  CPVC STP treated water Treatment- STP PVC PVC Not applicable  16A switch & socket point with wiring for spilt AC 16A switch & socket point with wiring for spilt AC
1:	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works WATER SUPPLY/DRAINAGE a) Sewage Line b)Water supply External piping Internal piping Flushing c) Drainage External piping Internal piping Internal piping Internal piping Internal piping AIR CONDITIONING Living Master Bedroom Bedrooms	UPVC / Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper cemulsion paint  oil bound distemper  Cement paint  oil bound distemper  Cement paint  acrylic emulsion paint  synthetic enamel paint  UPVC  CPVC for water supply  UPVC  CPVC  STP treated water  Treatment- STP  PVC  PVC  Not applicable  16A switch & socket point with wiring for spilt AC
1:	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage External piping Internal piping Internal piping Internal piping Internal piping Internal piping AIR CONDITIONING Living Master Bedroom Bedrooms 4 ELECTRICAL	UPVC / Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper cement paint  Oil bound distemper Cement paint  oil bound distemper  Cement paint acrylic emulsion paint synthetic enamel paint  UPVC  CPVC for water supply UPVC  CPVC STP treated water Treatment- STP PVC PVC Not applicable  16A switch & socket point with wiring for spilt AC 16A switch & socket point with wiring for spilt AC
1:	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage External piping Internal piping Internal piping Internal piping Internal piping Master Bedroom Bedrooms 4 ELECTRICAL Apartment	UPVC / Aluminium with bug screen and safety grill  External texture paint  emulsion paint  emulsion paint Oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint emulsion paint Oil bound distemper Cement paint acrylic emulsion paint synthetic enamel paint  UPVC CPVC for water supply UPVC CPVC STP treated water Treatment- STP PVC PVC Not applicable  16A switch & socket point with wiring for spilt AC 16A switch & socket point with wiring for spilt AC 16A switch & socket point with wiring for spilt AC
1:	D WINDOWS 1 PAINTING & FINISHES a) Exterior finish b) Internal ceilings common area lift Lobby staircase, utility area and service area basement unit ceiling c) Internal walls common area lift Lobby staircase, utility area and service area basement unit walls d) steel works WATER SUPPLY/DRAINAGE a) Sewage Line b) Water supply External piping Internal piping Flushing c) Drainage External piping Internal piping Internal piping Internal piping Internal piping Internal piping AIR CONDITIONING Living Master Bedroom Bedrooms 4 ELECTRICAL	UPVC / Aluminium with bug screen and safety grill  External texture paint  emulsion paint  oil bound distemper economy range emulsion acrylic emulsion paint  emulsion paint  emulsion paint  oil bound distemper cement paint  Oil bound distemper Cement paint  oil bound distemper  Cement paint acrylic emulsion paint synthetic enamel paint  UPVC  CPVC for water supply UPVC  CPVC STP treated water Treatment- STP PVC PVC Not applicable  16A switch & socket point with wiring for spilt AC 16A switch & socket point with wiring for spilt AC

	Modular switches	Anchor Roma/Viola or equivalent make
	DG Backup	3-KW for 3 BR, 2KW - 2BR ; Emergency power for lifts, pumps & lighting in common areas – 100%
15	VERTICAL TRANSPORTATION	Lifts provided as per design- OTIS / kone or equivalent
16	SECURITY SYSTEM & AUTOMATIONS	Intercom facility to be provided(in living area or next to main door). Handset in customer scope. Cable TV/DTH or internet on subscription basis.
17	LANDSCAPING	Yes
18	GAS SUPPLY*	Only shaft provision
19	WARDROBES	Not applicable
20	SUSTAINABILITY	
	Solar water heater	provided only for top 2 floors
	Organic waste converter	Yes
	Ground water recharging	Yes
	Rain water storage	Yes
	Street light	Yes
	STP*	Yes
21	CAR PARKING	as per local authroity requirement
*At additional cost		