

## FORM 1 ARCHITECT'S CERTIFICATE

Date: 28/04/2022

To, Sai Sharddha Developers Sr.No.28, Ambegaon-Budruk, Pune 411046

Subject: Certificate of percentage of completion of construction work of the A, B & C of the Project name Meriton Tower Phase of the project [RERA Registration Number [P52100027260] situated on the plot bearing Sr. No- 28/10/1,28/10/2,28/10/3,28/10/4, 28/10/5,28/10/5A,28/11/2, 28/12/2,28/14 Demarcated by its boundaries (Latitude 18.27'21.41" N Longitude 73.50'26.01" E) Sr. No. 28 (p) to the North, Sr. No. 28(p) & 12.00 M.W Road to the South, Sr. No. 28(P) to the East, Sr. No.28 (p) & 18.00 M.W. Road to the West of Division Pune village Ambegaon (Bk.) Taluka Haveli District Pune PIN 411046 Admeasuring 10497.28 sq. m. Area being Developed by SAI SHARDDHA DEVELOPERS.

Sir,

I Ar. Sangram Salunke have undertaken assignment as Architect / Licensed surveyor of certifying percentage of completion of construction work of the buildings A, B & C of the Project name Meriton Tower of the project situated on the plot bearing Sr. No-28/10/1, 28/10/2,28/10/3,28/10/4, 28/10/5,28/10/5A,28/11/2, 28/12/2,28/14) Of Division Pune village Ambegaon (Bk.) Taluka Haveli District Pune PIN 411057 Admeasuring 10497.28 sq. m. Area being developed by SAI SHARDDHA AASOCIATES.

- 1. Following technical professionals are appointed by owner/promoter: -
- (i) Shri Ar. Sangram Salunke Architect;
- (ii) Shri Arvind Chauhan as Site Supervisor
- (iii) M/S. GENSYS TECHNOLOGIES PVT LTD as structural consultants

Based on Site Inspection, with respect to each of the Building / Wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building / wing of the Real Estate Project as registered vide Number [P52100027260] RERA is as per table A Herein below. The percentage of the work executed with respect to each of the major activity of the Building / Wing and overall percentage of work done with respect to each Building / Wing is detailed in the Table B.



## Table A Wing- A

Sr. No	Task /Activity	Percentage of Work completed	
1 Excavation		100%	
2	1 no of Plinths	100%	
3	17 Numbers of Slabs of super structure	30%	
4	External walls, Internal Walls, Internal Plaster, Flooring within flats, Doors & windows to each flat	0%	
5	Sanitary Fittings, Electrical fittings within the flat	0%	
6	Staircase, Lift Wells, Lobbies at each level connecting staircases and lifts, overhead and underground water tanks	0%	
7	External Plumbing and External Plaster, elevation, completion of terraces with water proofing of wings	0%	
8	Installation of lifts, water pumps, fire fighting fittings and equipment's as per CFO NOC, electrical fittings to common areas, electro mechanical equipment's, compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall, and all other requirements as may be required to obtain Occupancy/ completion Certificate	0%	



Sr. No	Task /Activity	Percentage of Work completed 100%	
1	Excavation		
2	1 no of Plinths	100%	
3	17 Numbers of Slabs of super structure	70%	
4	External walls, Internal Walls, Internal Plaster, Flooring within flats, Doors & windows to each flat	0%	
5	Sanitary Fittings, Electrical fittings within the flat	0%	
6	Staircase, Lift Wells, Lobbies at each level connecting staircases and lifts, overhead and underground water tanks	0%	
7	External Plumbing and External Plaster, elevation, completion of terraces with water proofing of wings	0%	
8	Installation of lifts, water pumps, fire fighting fittings and equipment's as per CFO NOC, electrical fittings to common areas, electro mechanical equipment's, compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall, and all other requirements as may be required to obtain Occupancy/ completion Certificate	0%	






Table A Wing- C

Sr. No	Task /Activity	Percentage of Work completed 100%	
1	Excavation		
2	1 no of Plinths	100%	
3	17 numbers of Slabs of super structure	70%	
4	External walls, Internal Walls, Internal Plaster, Flooring within flats, Doors & windows to each flat	0%	
5	Sanitary Fittings, Electrical fittings within the flat	0%	
6	Staircase, Lift Wells, Lobbies at each level connecting staircases and lifts, overhead and underground water tanks	0%	
7	External Plumbing and External Plaster, elevation, completion of terraces with water proofing of wings	0%	
8	Installation of lifts, water pumps, fire fighting fittings and equipment's as per CFO NOC, electrical fittings to common areas, electro mechanical equipment's, compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall, and all other requirements as may be required to obtain Occupancy/ completion Certificate	0%	





Table B
Internal & External Development works in Respect of the entire registered phase

Sr. No.	Common Area And Facilities, Amenity	Proposed (Yes/No)	Percentage Of Work Done	Details
1.	Solid Waste Management And Disposal	Yes	0%	Garbage Chute With Room Provide After Completion
2.	Water Conservation, Rain water Harvesting	Yes	0%	Rain water Harvesting Provide After Completion
3.	Energy management	Yes	0%	Solar Water As Per PMC Norms Provide After Completion
4.	Fire Protection And Fire Safety Requirements	Yes	0%	As Per Fire Department Norms Provide After Completion
5.	Internal Roads & Footpaths	Yes	0%	Internal Road & Marginal Drive way In Concrete
6.	Water Supply	Yes	0%	Bore well & PMC Waterline After Completion
7.	Street Lighting	Yes	0%	As Per PMC Norms
8.	Electrical Meter Room, Sub-Station, Receiving Station	Yes	0%	As Per MSEDCL
9.	Open Parking	Yes	0%	Provide After Completion
10.	Community Buildings	Yes	0%	Only Club House
11.	Treatment And Disposal Of Sewage And Sullage Water	Yes	0%	As Per PMC Norms
12.	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	0%	As Per PMC Norms
13.	Storm Water Drains	Yes	0%	As Per PMC Norms
14.	Landscaping & Tree Planting	Yes	0%	As Per PMC Norms & Consultant
			ion Studi	