SACHIN SUTAR

ARCHITECTS & INTERIOR DESIGNERS

A1 NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRINGI TEMPLE, SENAPATI BAPAT RD. PUNE -411016 .

FORM 1 ARCHITECT'S CERTIFICATE

Date:19th March 2020

To, R- Retail Ventures Pvt Ltd Runwal Omkar Square, 5th Floor Off Eastern Express Highway, Sion Mumbai - 400 022 Tel: 61133000

Subject:Certificate of Cost Incurred for Development of "The Central Park – Phase 1" for Construction of 02 (Two) building(s)/ 05 (Five) Wing(s)ofthe First Phase situated on the Plotbearing CTS No. 4510(P), 4513(P) demarcated by its boundaries (latitude and longitude of the endpoints) 18°38'6.89"N, 73°47'44.44"E to the North, 18°37'57.42"N, 73°47'47.65"E totheSouth, 18°38'5.6"N, 73°47'52.79"E totheEast, 18°38'0.72"N, 73°47'39.41"E to the West of Village Chinchwad, tehsil Haveli, District Pune, PIN – 411 019 admeasuring 95,516.12 sqm area being developed by Retail Ventures Private Limited.

Sir,

I have undertaken assignment as Architect of certifying PercentageofCompletionofConstructionWorkoftheR-Retail Ventures Pvt Ltd Building(s)/ 1Wing(s) 5ofthe first Phase of the Project, situated on the plot bearing 4510, 4510p & 4513 village ChinchwadTehsil ChinchwadDistrict PunePIN 411019andmeasuring 95516.12 sqm area being developed by [R-Retail Ventures Pvt Ltd]

Following technical professionals are appointed by Owner / Promoter:

M/s Unusual Spaces Pvt Ltd - Shri Sachin SutarLicense Architect

M/s JWConsultants Shri UmeshJoshi asStructuralConsultant

M/s SN Joshi Consultants Shri Anand JoshiasMEP Consultant

M/s Santosh Supekar as SiteSupervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide

number____under Real Estate Regulatory Authority, Pune is as per table A herein below.

SACHIN SUTAR

ARCHITECTS & INTERIOR DESIGNERS

A1 NATURE VIEW APT, PRAKASH BHAVAN LANE, NEAR CHATURSHRINGI TEMPLE, SENAPATI BAPAT RD. PUNE -411016.

The percentage of the work executed with respect to each of the activity of the entire phase is detailed in

Table B.

Table A Building C1

Sr. No	Building C1 Tasks /Activity	Percentage of		
		work done		
1	Excavation			
2	2 number of Basement(s) and Plinth			
3	1 number of Podiums			
4	Stilt Floor			
5	36number of Slabs of SuperStructure			
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises			
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings with	hin the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connec	ting Staircases and Lifts,		
	Overhead and Underground WaterTanks			
9	The external plumbing and external plaster,			
	elevation, completion of terraces with waterproofing of the Building/Wing,			
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC,			
	Electrical fittings to Common Areas, electro, mechanical eq	uipment, Compliance to		
	conditions of environment NOC, Finishing to entrance lobby/s,	plinth protection, paving		
	of areas appurtenant to Building/Wing, Compound Wall and all other requirements as			
	may be required to Obtain Occupation / CompletionCertificate			

SACHIN SUTAR

ARCHITECTS # INTERIOR DESIGNERS

AT NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRINGI TEMPLE, SENAPATI BAPAT RD. PUNE -411016.

Building C2

Sr. No	Tasks / Activity Percentage of
	work done
1	Excavation
2	2_number of Basement(s) and Plinth
3	1 number of Podiums
4	Stilt Floor
5	36number of Slabs of SuperStructure
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts
	Overhead and Underground WaterTanks
9	The external plumbing and external plaster,
	elevation, completion of terraces with waterproofing of the Building/Wing,
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC
	Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to
	conditions of environment NOC, Finishing to entrance lobby/s, plinth protection, paving
	of areas appurtenant to Building/Wing, Compound Wall and all other requirements as
	may be required to Obtain Occupation / CompletionCertificate

SACHIN SUTAR

ARCHITECTS # INTERIOR DESIGNERS

AT NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRINGI TEMPLE, SENAPATI BAPAT RD. PUNE -411018.

Building C3

Sr. No	Tasks /Activity Percentage of		
	work done		
1	Excavation		
2	2_number of Basement(s) and Plinth		
3	1 number of Podiums		
4	Stilt Floor		
5	36 number of Slabs of SuperStructure		
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises		
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts,		
	Overhead and Underground WaterTanks		
9	The external plumbing and external plaster,		
	elevation, completion of terraces with waterproofing of the Building/Wing,		
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NO	-	
	Electrical fittings to Common Areas, electro, mechanical equipment, Compliance t	0	
	conditions of environment NOC, Finishing to entrance lobby/s, plinth protection, pavin	g	
	of areas appurtenant to Building/Wing, Compound Wall and all other requirements a	15	
	may be required to Obtain Occupation / CompletionCertificate		

SACHIN SUTAR

ARCHITECTS & INTERIOR DESIGNERS

AT NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRINGI TEMPLE, SENAPATI BAPAT RD. PUNE -411016 .

Building B1

Sr. No	Tasks /Activity	Percentage of
1	Excavation	work done
2	2_number of Basement(s) and Plinth	
3	1 number of Podiums	
4	Stilt Floor	
5	36number of Slabs of SuperStructure	
6	Internal walls, Internal Plaster, Floorings within Flats/Pre Doors and Windows to each of the Flat/Premises	mises,
7	Sanitary Fittings within the Flat/Premises, Electrical Fittin	gs within the Flat/Premises
8	Staircases, Lifts Wells and Lobbies at each Floor level of	onnecting Staircases and Lifts,
	Overhead and Underground WaterTanks	
9	The external plumbing and external plaster,	
	elevation, completion of terraces with waterproofing of	the Building/Wing,
10	Installation of lifts, water pumps, Fire Fighting Fittings at	nd Equipment as per CFO NOC,
	Electrical fittings to Common Areas, electro, mechanic	cal equipment, Compliance to
	conditions of environment NOC, Finishing to entrance loi	bby/s, plinth protection, paving
	of areas appurtenant to Building/Wing, Compound Wal	l and all other requirements as
	may be required to Obtain Occupation / CompletionCerti	ficate

ARCHITECTS & INTERIOR DESIGNERS AT NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRING! TEMPLE, SENAPATI BAPAT RD. PUNE -411016.

Building B2

Sr. No	Tasks /Activity	Percentage of
		work done
1	Excavation	
2	2_number of Basement(s) andPlinth	
3	1 number of Podiums	
4	Stilt Floor	
5	36 number of Slabs of SuperStructure	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises Doors and Windows to each of the Flat/Premises	25,
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings w	vithin the Flat/Premises
8	Staircases, Lifts Wells and Lobbies at each Floor level conne	ecting Staircases and Lifts,
	Overhead and Underground WaterTanks	
9	The external plumbing and external plaster,	
	elevation, completion of terraces with waterproofing of the B	Building/Wing,
10	Installation of lifts, water pumps, Fire Fighting Fittings and E	quipment as per CFO NOC,
	Electrical fittings to Common Areas, electro, mechanical e	equipment, Compliance to
	conditions of environment NOC, Finishing to entrance lobby/	s, plinth protection, paving
	of areas appurtenant to Building/Wing, Compound Wall and	d all other requirements as
	may be required to Obtain Occupation / CompletionCertificat	e

SACHIN SUTAR

ARCHITECTS \$ INTERIOR DESIGNERS
AT NATURE VIEW APT. PRAKASH BHAVAN LANE, NEAR CHATURSHRING! TEMPLE, SENAPATI BAPAT RD. PUNE -411016.

TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

S.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage Work done	of	Details
1.	Internal Roads & Foot-paths	Yes	0		
2.	Water Supply	Yes	0		
3.	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0		
4.	Storm Water Drains	Yes	0		
5.	Landscaping & Tree Planting	Yes	0		
6.	Street Lighting	Yes	0		
7.	Community Buildings	Yes	0		
8.	Treatment and disposal of sewage and sullage water	Yes	0		
9.	Solid Waste management & Disposal	Yes	0		
10.	Water conservation, Rainwater harvesting	Yes	0		
11.	Energy management	Yes	0	1	
12.	Fire protection and fire safety requirements	Yes	0		
13.	Electrical meter room, sub-station, receiving station	Yes	0		
14.	Others (Option to Add more)	Yes	0		

Yours Faithfully

SACHIN SUTAR

CA/95/18039