

Date: 01/12/2022

## Annexure A FORM 1 [see Regulation 3] ARCHITECT'S CERTIFICATE

To, M/s. A. K. Surana Developers, Off No. 138, Patil Plaza, Near Sarasbaug, Mitramandal Chowk, Parvati, Pune – 411009.

Subject: Certificate of Percentage of Completion of Construction Work of **01** No. of Building(s) of the Project "Arbor Vista" having MahaRERA Registration Number – \_\_\_\_\_, on the Plot bearing S. No. 71, Hissa No. 1A/1, Village. Wakad, Tal. Mulshi, Dist. Pune is being developed by **M/s. A. K. Surana Developers.** 

Sir,

We VK:a architecture have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of **01** No. of Building(s) of the Project "**Arbor Vista**" having MahaRERA Registration Number – \_\_\_\_\_\_, on the Plot bearing S. No. 71, Hissa No. 1A/1, Village. Wakad, Tal. Mulshi, Dist. Pune is being developed by **M/s. A. K. Surana Developers.** 

Based on Site Inspection, with respect to each of the Building / Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building / Wing of the Real Estate Project as registered under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the major activity of the entire phase detailed Table B.



Page 1 of 3
P:\1901-1950\1938 - A K Surana, S No 71 Wakad\Text\b0 Data\b05 RERA Certificates\221201 - RERA Certificate (Form-1).docx



## Table A Building - "Arbor Vista"

	Duituing - Aiboi vista	
Sr. No.	Tasks / Activity	Percentage of Actual Work done
1	Excavation	20%
2	Basements (If any)	0%
3	Podiums (If any)	0%
4	Plinth	0%
5	Stilt floor	0%
6	Slabs of super Structure	0%
7	Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises	0%
8	Sanitary Fittings within The Flats/Premises	0%
9	Staircases. lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing,	0%
11	Installation of Lift's. water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, electrical fittings, mechanical equipment, compliance to Conditions of environment/CRZ NOC. Finishing to entrance lobby's, plinth protection, having of areas appurtenant to Building/wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Another acclivities.	o%  archirec



TABLE – B Internal & External Development Works in Respect of the Registered Project "Arbor Vista"

S. No.	Common areas and Facilities	Proposed (Yes/No)	Percentage of Actual work done	Details
1	Internal Roads & Footpaths	Yes	0%	
2	Water Supply	Yes	0%	
3	Sewerage (chamber, lines, septic tank, STP).	Yes	0%	
4	Strom Water Drains	Yes	0%	
5	Landscaping & Tree Planting	Yes	0%	
6	Street Lighting	Yes	0%	
7	Community Buildings	No	ä	NA
8	Treatment and disposal of sewage and Sullage water.	Yes	0%	
9	Solid Waste management & Disposal	Yes	0%	
10	Water conservation / Rain water harvesting	Yes	0%	
11	Energy management	Yes	0%	
12	Fire protection and lire safety requirements	Yes	0%	
13	Electrical meter room, sub-station, Receiving station.	Yes	0%	
14	Others (Option to Add more)	No	-	NA

Yours Faithfully

AR. VISHWAS KULKARNI VK:a architecture (License No. CA/84/8465) SthFloor
SthFloor
SthCloor
Sth

Agreed and Accepted By:

Signature of Promoter:

Name: M/s. A. K. Surana Developers.

Date: 01/12/2022

Page 3 of 3

P:\1901-1950\1938 - A K Surana, S No 71 Wakad\Text\b0 Data\b05 RERA Certificates\221201 - RERA Certificate (Form-1).docx