

Date: 30/06/2023

Annexure A
FORM 1 [see Regulation 3]
ARCHITECT'S CERTIFICATE

To,
M/s. Highpoint Landmark LLP,
Mhalunge Real Estate Developers Pvt. Ltd.
through Authorized Signatory Mr. Sachin Garg.

Subject: Certificate of Percentage of Completion of Construction Work of 7 Nos. of Tower- A, B, C, D, E, F and MLCP of the Project "Itrend Futura" having MahaRERA Registration Number – P52100050688, on the Plot bearing Sector No. R-12 of Integrated Township at S No. 39/1(P), 39/2(P), S. NO. 40 H. No. 1(P), 2, 3, 4, S. No. 41/1(P), 41/4, S. No. 42/1, 42/2A, 2B, S. No. 42.1, 3, 4, 5, 6, 7, 8(P), 9, 10, 13, S. No. 43/1 (P), 43 H. No. 2/1,2/2, S. No. 44 H. No. 1,2, S. No. 45(P), S. No. 46 H. No. 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, S. No. 47, H. No. 1,2(P), 3(P), at Village Mhalunge, and S. No. 187/3/A(P), 188/1, 189/3, 189/4, 190/2, 191/1, 191/3(P), 192/1/1, 192/1/2, 192/1/3, 192/3, 193/3, 193/5, 194, 195/1, 195/2, 196/3, 198/1/1, 199/1, 199/2, 199/3, 199/4, 200/1/1(P), 200/1/2, 200/1/3, 200/3/2, 201/1, 201/2, 201/3, 201/4, 202 (P), 203/1, 203/2, 203/3, 203/4, 204/2(P), 204/3, 204/4, 204/5, 204/6, 205/1, 205/2, 206/1, 206/2/2(P), 206/2/3, 207,208/1(P), 208/2/2(P), 208/5, 208/6/1(P), 208/6/3, 216/1, 216/2, 216/3(P), 217/1(P), 218/1/1, 218/1/2, at Village Hinjewadi And S. No. 49/1(P), 49/2(P), 49/3(P), 50/1/A, 50/2/A, 52/1/B, 52/2B, 52/2/A, 52/2/C, 52/2/D, 52/2/E, 52/2/F at Village Mann, Tal. Mulshi, Pune is being developed by M/s. Highpoint Landmark LLP, Mhalunge Real Estate Developers Pvt. Ltd. through authorized signatory Mr. Sachin Garg.

Sir,

We VK:a architecture have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of 7 Nos. of Tower- A, B, C, D, E, F and MLCP of the Project "Itrend Futura" having MahaRERA Registration Number – P52100050688, on the Plot bearing Sector No. R-12 for Integrated Township on above mention site address is being developed by M/s. Highpoint Landmark LLP, Mhalunge Real Estate Developers Pvt. Ltd. through authorized signatory Mr. Sachin Garg.

Based on Site Inspection, with respect to each of the Building / Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building / Wing of the Real Estate Project as registered under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the major activity of the entire phase detailed Table B.

Page 1 of 4

P:\2351-2400\2360 - Sachin Agarwal, Sector R12, Mahalunge, Pune\Text\b0 Data\b05 RERA Certificates\230824 - RERA Certificate (Form-1).docx

5th Floor, Next Gen Avenue, Off. Senapati Bapat Rd, Pune, Maharashtra 411016 Email: mail@vkarch.com Phone: +91 20 6626 8888





## Table A

| Sr.<br>No. |   | Percentage of Actual Work done |         |         |  |
|------------|---|--------------------------------|---------|---------|--|
|            | Tasks / Activity  | Tower-A                        | Tower-B | Tower-C |  |
| 1          | Excavation  | 0%                             | 100%    | 100%    |  |
| 2          | Basement  | 0%                             | 0%      | 0%      |  |
| 3          | Podiums   | 0%                             | 0%      | 0%      |  |
| 4          | Plinth  | 0%                             | 0%      | 0%      |  |
| 5          | Stilt floor   | 0%                             | 0%      | 0%      |  |
| 6          | Slabs of super Structure  | 0%                             | 0%      | 0%      |  |
| 7          | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises  | 0%                             | 0%      | 0%      |  |
| 8          | Sanitary Fittings within The Flats/Premises   | 0%                             | 0%      | 0%      |  |
| 9          | Staircases, lifts Wells and Lobbies at each Floor level<br>Overhead and Underground Water Tanks   | 0%                             | 0%      | 0%      |  |
| 10         | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing,  | 0%                             | 0%      | 0%      |  |
| 11         | Installation of Lift's. water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, electrical fittings, mechanical equipment, compliance to Conditions of environment/CRZ NOC. Finishing to entrance lobby's, plinth protection, having of areas appurtenant to Building/wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Another activities. | 0%                             | 0%      | 0%      |  |

Page 2 of 4 P:\2351-2400\2360 - Sachin Agarwal, Sector R12, Mahalunge, Pune\Text\b0 Data\b05 RERA Certificates\230824 - RERA Certificate (Form-1).docx

5th Floor, Next Gen Avenue, Off. Senapati Bapat Rd, Pune, Maharashtra 411016

Email: mail@vkarch.com Phone: +91 20 6626 8888



## Table A

| Sr.<br>No. | Tasks / Activity  | Percentage of Actual Work done |                                 |                |      |
|------------|---|--------------------------------|---------------------------------|----------------|------|
|            |   | Tower-D                        | Tower-E                         | Tower-F        | MLCP |
| 1          | Excavation  | 0%                             | 100%                            | 0%             | 0%   |
| 2          | Basement  | 0%                             | 0%                              | 0%             | 0%   |
| 3          | Podiums   | 0%                             | 0%                              | 0%             | 0%   |
| 4          | Plinth  | 0%                             | 0%                              | 0%             | 0%   |
| 5          | Stilt floor   | 0%                             | 0%                              | 0%             | 0%   |
| 6          | Slabs of super Structure  | 0%                             | 0%                              | 0%             | 0%   |
| 7          | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises  | 0%                             | 0%                              | 0%             | 0%   |
| 8          | Sanitary Fittings within The Flats/Premises   | 0%                             | 0%                              | 0%             | 0%   |
| 9          | Staircases, lifts Wells and Lobbies at each Floor level<br>Overhead and Underground Water Tanks   | 0%                             | 0%                              | 0%             | 0%   |
| 10         | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing,  | 0%                             | 0%                              | 0%             | 0%   |
| 11         | Installation of Lift's. water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, electrical fittings, mechanical equipment, compliance to Conditions of environment/CRZ NOC. Finishing to entrance lobby's, plinth protection, having of areas appurtenant to Building/wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Another activities. | 0%                             | 0%                              | 0%             | 0%   |
|            |   | 4                              | Bahirati<br>Near ICC<br>S. B. F | wadi.<br>Tower |      |

Page 3 of 4

P:\2351-2400\2360 - Sachin Agarwal, Sector R12, Mahalunge, Pune\Text\b0 Data\b05 RERA Certificates\230824 - RERA Certificate (Form-1).docx

5th Floor, Next Gen Avenue, Off. Senapati Bapat Rd, Pune, Maharashtra 411016

Email: mail@vkarch.com Phone: +91 20 6626 8888





## TABLE - B Internal & External Development Works in Respect of the Registered Phase/Project

| S. No. | Common areas and Facilities                               | Proposed<br>(Yes/No) | Percentage of<br>Actual work<br>done | Details          |
|--------|---|----------------------|--------------------------------------|------------------|
| 1      | Internal Roads & Footpaths                                | Yes                  | 0%                                   | Work not started |
| 2      | Water Supply  | Yes                  | 0%                                   | Work not started |
| 3      | Sewerage (chamber, lines, septic tank, STP).              | Yes                  | 0%                                   | Work not started |
| 4      | Strom Water Drains  | Yes                  | 0%                                   | Work not started |
| 5      | Landscaping & Tree Planting                               | Yes                  | 0%                                   | Work not started |
| 6      | Street Lighting   | Yes                  | 0%                                   | Work not started |
| 7      | Community Buildings                                       | Yes                  | 0%                                   | Work not started |
| 8      | Treatment and disposal of sewage and Sullage water.       | Yes                  | 0%                                   | Work not started |
| 9      | Solid Waste management & Disposal                         | Yes                  | 0%                                   | Work not started |
| 10     | Water conservation / Rain water<br>harvesting             | Yes                  | 0%                                   | Work not started |
| 11     | Energy management   | Yes                  | 0%                                   | Work not started |
| 12     | Fire protection and fire safety requirements              | Yes                  | 0%                                   | Work not started |
| 13     | Electrical meter room, sub-station,<br>Receiving station. | Yes                  | 0%                                   | Work not started |
| 14     | Others (Option to Add more)                               | -                    | 0%                                   | Work not started |

Yours Faithfully

AR. HRISHIKESH KULKARNI VK:a architecture

Reg. No. CA/2002/29235

Agreed and Accepted By:

Signature of Promoter:

Name: M/s. Highpoint Landmark LLP, Mhalunge Real Estate Developers Pvt. Ltd. through authorized signatory Mr. Sachin Garg

Date: 30/06/2023

P:\2351-2400\2360 - Sachin Agarwal, Sector R12, Mahalunge, Pune\Text\b0 Data\b05 RERA Certificates\230824 - RERA Certificate (Form-1).docx

5th Floor, Next Gen Avenue, Off. Senapati Bapat Rd, Pune, Maharashtra 411016

Email: mail@vkarch.com Phone: +91 20 6626 8888



