

## FORM 1 [see Regulation 3] ARCHITECT'S CERTIFICATE

Date: 16/01/2019

SURBHI MANGALAM PRAKRITI SPACE LLP

B201, Runwal Regency , Sadhu Vaswani Chowk, camp , Pune 411001

Subject : Certificate of Percentage of Completion of Construction Work of wing C Building(s) of the SURBHI MANGALAM Project [MahaRERA Registration Number] situated on the Plot bearing S.NO.3/5, 3/8 DHANORI, PUNE demarcated by its boundaries Admeasuring 491.00 sq.mts. Area being developed by PRAKRITI SPACE LLP.

To the north - Sr No. 3/7(latitude-18°36'04.40" and longitude-73°53'54.24")

To the south - Sr no 3/5 (latitude-18°36'03.46" and longitude-73°53'54.28")

To the east - Sr No 3/8 (latitude-18°36'04.02" and longitude-73°53'57.06")

To the west-24.00 M.WIDE D.P ROAD (latitude-18°36'04.27" and longitude-73°53'49.52")

I cubix architects associates have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the wing C Building(s) of the SURBHI MANGALAM Project, situated on the plot bearing S.NO.3/5, 3/8, DHANORI, PUNE.

Admeasuring 491.00 sq.mts. Area being developed by PRAKRITI SPACE LLP

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) M/s CUBIX ARCHITECTS ASSOCIATES as L.S. / Architect;
- (ii) M/s Hansal Parekh & Associates as Structural Consultant
- (lii) MEP Consultant: SIDDHIVINAYAK MEP CONSULTANTS

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Office No. 1 & 2, Aristrocat 'L', Opp. Beverly Hills Hotel, Near Magnus Club, Lulla Nagar, Bibwewadi, Pune - 411 040.

Office: 7757043086 / 7757043087 Email: cubixarchitects@gmail.com

## LIASONING OFFICE:

94,Sai Narayan Plaza, Ganjave Chowk, Near Patrakar Bhavan, Navi Peth, Pune - 411 030. Email: gajanan.panjarkar@gmail.com shrushtiassociates2013@gmail.com

Table A

## **Building /Wing Number**

Sr.	Tasks /Activity	Percentage of work done Building		
No.	i I			
1	1 <u>.</u> —	'c'		
100	Excavation	100%		
2 <u> </u>	1 number of Basement	0%		
10 to 100	Plinth/stilt floor	0%		
3	8 number of Slabs of Super Structure	0%		
4	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%		
5	Sanifary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%		
6	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%		
7	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%		
	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Waff and all other requirements as may be required to Obtain Occupation /Completion	0%		

TABLE-B
Internal & External Development Works in Respect of the entire Registered Phase

S.No.	Common areas and Facilities,	Proposed (Yes/No)	% of Work done	Details
1	Internal Roads & Foothpaths	YES	0%	
2	Water Supply	YES	0%	
3	Sewarage (chamber, lines, Septic Tank , STP)	YES	0%	San Lapari
4	Storm Water Drains	YES	0%	
5	Landscaping & Tree Planting	YES	0%	
6	Street Lighting	YES	0%	
7	Community Buildings	NO	0%	
8	Treatment and disposal of sewage and sullage water	YES	0%	
9	Solid Waste management & Disposal	NO	0%	
10	Water conservation, Rain water harvesting	YES	0%	
11	Energy management	NO	0%	
12	Fire protection and fire safety requirements	YES	0%	
13	Electrical meter room, sub-station, receiving station	YES	0%	
14	Others (Option to Add more)	NO	0%	
15	Solar water heater	Yes	0%	
16	Compound wall	Yes	30%	

