



Sharmistha Mukerjee Shinde  
ARCHITECT

Date: - 01<sup>st</sup> November, 2018

To,  
Roma Builders Pvt. Ltd.  
514, Dalamal Towers, Nariman Point,  
Mumbai 400021.

**Subject :** Certificate of Percentage of Completion of Construction Work of **Building No. 11 (Glendale)** Building of the Phase of the Project [MahaRERA Registration Number ] situated on the Plot bearing Survey No. 123/1B demarcated by its boundaries ( latitude and longitude of the endpoints)

- 1) 19°15'34.47"N, 72°58'49.59"E
- 2) 19°15'34.15"N, 72°58'49.43"E
- 3) 19°15'34.97"N, 72°58'48.40"E
- 4) 19°15'34.62"N, 72°58'48.24"E
- 5) 19°15'34.45"N, 72°58'48.66"E
- 6) 19°15'34.16"N, 72°58'48.55"E
- 7) 19°15'34.01"N, 72°58'48.92"E
- 8) 19°15'34.29"N, 72°58'49.04"E

Survey No. 123/1A to the North, Survey No. 123/2C to the South, Survey No. 123/5D to the East, Survey No. 123/2B, 123/2A to the West of village Kavesar, Taluka Thane, District Thane, PIN- 400607, Built up area admeasuring 8308.19 sq. mts. area being developed by Roma Builders Pvt. Ltd.

Sir,

I, Sharmistha Mukerjee have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of **Building No.11 (Glendale)** building of the Phase of the Project, situated on the plot bearing Survey No.123/1B of village Kavesar, Taluka Thane, District Thane, PIN – 400607, Built up area admeasuring 8308.19 sq.mts. are being developed by Roma Builders Pvt. Ltd.

1. Following technical professionals are appointed by Owner/promoter.:-

- (i) Design Architect Ms. Gunisha Sethi Sanyal &Municipal Sharmistha Mukerjee Shinde as Liasoning Architect.
- (ii) M/s. Epicons Consultant Pvt. Ltd. as Structural Consultant.
- (iii) M/s. Clancy Global Consulting Engineers and Waternet Consulting Services Pvt. Ltd. as MEP Consultant.
- (iv) Shri. Pradeep Gaikwad as Quantity Surveyor..

4<sup>th</sup> Floor, Basilus Building, Rodas Enclave, Ghod Bunder Road, Patlipada, Thane (W) 400 607



Sharmistha Mukerjee Shinde  
ARCHITECT

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on 30<sup>th</sup> October, 2018 the Percentage of work done for each of the building/wing of the Real Estate project as registered vide number \_\_\_\_\_ under MahaRERA is as per table A herein below. The work executed with respect to each of the activity of the entire below. The percentage of phase is detailed in Table B. The disclosures with respect to the project is detailed in Table C.



*Sharmistha Mukerjee Shinde*  
ARCHITECT

**TABLE –A**  
**Building No. 11 (Glendale)**

| <b>SR. NO.</b> | <b>TASKS/ ACTIVITIES</b>                                                                                                                                                                                                                                                                                                                                                                                               | <b>PERCENTAGES OF WORK</b> |
|----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| 1              | Excavation                                                                                                                                                                                                                                                                                                                                                                                                             | 0%                         |
| 2              | 2 Number of Basement (s) & Plinth                                                                                                                                                                                                                                                                                                                                                                                      | 0%                         |
| 3              | 0 Number of Podium                                                                                                                                                                                                                                                                                                                                                                                                     | 0%                         |
| 4              | 01 Stilt Floor                                                                                                                                                                                                                                                                                                                                                                                                         | 0%                         |
| 5              | 29 Number of Slab of Super Structure                                                                                                                                                                                                                                                                                                                                                                                   | 0%                         |
| 6              | Internal Wall, Internal Plaster, Floorings With Flats/Premises, Doors & Windows To Each of The Flat/Premises                                                                                                                                                                                                                                                                                                           | 0%                         |
| 7              | Sanitary Fittings Within The Flat/Premises, Electrical Fittings Within The Flat/ Premises                                                                                                                                                                                                                                                                                                                              | 0%                         |
| 8              | Staircases, Lifts Wells & Lobbies At Each Floor Level Connecting Staircases & Lifts, Overhead & Underground Water Tanks                                                                                                                                                                                                                                                                                                | 0%                         |
| 9              | The External Plumbing, External Plaster, Elevation, Completion Of Terraces With Waterproofing Of The Building/Wing                                                                                                                                                                                                                                                                                                     | 0%                         |
| 10             | Installation With Lifts, Water Pumps, Fire Fighting Fitting & Equipment As Per CFO NOC, Electrical Fittings To Common Areas, Electro, Mechanical Equipment, Compliances To Conditions Of Environment/ CRZ NOC , Finishing To Entrance Lobby/s, Plinth Protection, Paving Of Areas Appurtenant To Building/Wing, Compound Wall & All Other Requirements As May Be Required To Obtain Occupation/ Completion Certificate | 0%                         |



*Sharmistha Mukerjee Shinde*  
ARCHITECT

**TABLE - B**

**Internal & External Development Works in Respect of the entire Registered Phase**

| Sr. No. | Common areas & Facilities, Amenities                   | Proposed (Yes/No) | Percentage of Work done | Details                   |
|---------|--------------------------------------------------------|-------------------|-------------------------|---------------------------|
| 1.      | Internal Roads & Footpaths                             | Yes               | 0%                      | Shall be done prior to OC |
| 2.      | Water Supply                                           | Yes               | 0%                      | Shall be done prior to OC |
| 3.      | Sewerage (chamber, lines, Septic Tank, STP)            | Yes               | 0%                      | Shall be done prior to OC |
| 4.      | Storm Water Drains                                     | Yes               | 0%                      | Shall be done prior to OC |
| 5.      | Landscaping & Tree Planting                            | Yes               | 0%                      | Shall be done prior to OC |
| 6.      | Street Lighting                                        | Yes               | 0%                      | Shall be done prior to OC |
| 7.      | Community Buildings                                    | No                | -                       | NA                        |
| 8.      | Treatment and Disposal of sewage and sullage water.    | Yes               | 0%                      | Shall be done prior to OC |
| 9.      | Solid Waste Management & Disposal                      | Yes               | 0%                      | Shall be done prior to OC |
| 10.     | Water conservation, Rain water harvesting.             | Yes               | 0%                      | Shall be done prior to OC |
| 11.     | Energy management                                      | Yes               | 0%                      | Shall be done prior to OC |
| 12.     | Fire protection and Fire safety requirements           | Yes               | 0%                      | Shall be done prior to OC |
| 13.     | Electrical meter room, Sub-station, Receiving station. | Yes               | 0%                      | Shall be done prior to OC |






Sharmistha Mukerjee Shinde  
ARCHITECT

**TABLE – C**  
**DISCLOSURES**  
**Building No. 11 (Glendale)**

- Column sizes / location may change due to structural requirement.
- Wall thickness may change as per structural requirement.
- Direction or location of Door may revise for better circulation.
- Service areas / duct may change as per requirement of municipal, services requirement and requirements of any other concerned authorities.
- Room names & nomenclatures may differ in brochure & approved plans.
- Mechanized parking may be provided as per requirement, which may entail amendment accordingly.
- Elevational features may differ from approved dwgs. for aesthetic purpose.
- All internal dimensions are from unfinished wall surfaces. Minor variations up to  $\pm 3\%$  in actual carpet areas may occur on account of site conditions/ RCC/ Finish line/ Pali/ Dado tiles etc.
- *Entrance canopy may be added for aesthetic purpose.*
- Wherever land area is mentioned it is the area of land under the building.
- Security Cabin will be provided as per requirement.
- Required RG, common to the buildings in the layout will be provided as per the site conditions prior to obtaining OC of the last building in the said layout.
- Sewage collection capacity, sump location, UGT & STP provided may be revised as per MEP requirements.
- OHT & LMR heights may be revised as per requirements.
- Number of super structure slab mentioned are as per slabs above ground level & including podium levels, which may be overlapped.
- Additional parking spaces shown may be used for services, if required.
- Fitness centre area may be revised as per municipal requirement.

Yours Faithfully

  
Sharmistha Mukerjee  
Architect  
(CA/ 95/18614 )