

Pravin Sadashiv Jagtap

Flat no -701 A wing Parshuram Tower Kalyan - Murbad Road Behind Central Bank Mharal Pada Varp Thane.

FORM-2A

Date:-15-07-2021

[See MahaRERA order no. of 2018]

ENGINEER'S CERTIFICATE FOR QUALITY ASSURANCE

(site supervisor's certificate) —
(To be uploaded quarterly)

To,

M/s SAMARTH SAI BUILDERS & DEVELOPERS

Behind 50-50 Dhaba, Opp. Essar Petrol Pump, Haji Malang

Road, Pisavli, Kalyan (E) 421 306.

Quality Assurance Certificate

Subject: Certificate of Cost Incurred for Development of
[SEASON SAHARA], Building No 3
for Construction (MahaRERA Registration Number) situated on the Plot bearing
S.No.33 NO 11, SNO 34 , HNO 9/10/11/12/14/15
demarcated by its boundaries at

Corner No	Latitude	Latitude	Description
North	19.12'50.2" N	73.07'50.2" E	15 Mtr D.P. Road
South	19.12'47.4" N	73.07'50.0" E	Namdev Sadan
East	19.12'48.9" N	73.07'49.3" E	Sai Dham Chawl
West	19.12'49.0" N	73.07'51.2" E	Davakhar Elegance, 30 Mtr, Road

Division Kokan Village: Pisavli, Taluka: Kalyan, District: Thane, Pin – 421306, admeasuring 9740.00 Sq.Mtrs out of 6469.20 Sq. M. area which is being developed by M/s SAMARTH SAI BUILDERS & DEVELOPERS.

Ref: MahaRERA Registration Number P51700020644

Pravin Sadashiv Jagtap

Flat no -701 A wing Parshuram Tower Kalyan - Murbad Road Behind Central Bank Mharal Pada Varp Thane.

Sir,

I **Pravin Sadashiv Jagtap** have undertaken an assignment of supervision of this real estate project.

1. Our Responsibility: –

To carry out the work in accordance with the development permission and as per the approved plan and submit certificate of supervision of work and to carry out material testing in-situ or in the authorized laboratory and to ensure quality of work and

1. Material Testing :-

I/we, have applied following mandatory checks on the basic materials, used in the construction.

i. Cement-

It has been tested for its fineness, soundness, setting time, compressive strength etc. as per IS code 3535:1986 or as per other relevant IS/85/NBC code, or as per industry standards and its results are within the permissible limits.

ii. Coarse aggregate –

It has been tested, for deleterious materials, clay lumps, crushing value, impact value as per IS 24301 1986 or as per other relevant IS/BS/NBC code or as per industry standards and its results are within the permissible limits.

iii. Bricks/ blocks –

They have been tested for water absorption, crushing strength etc. as per IS 5454:1978 or as per other relevant IS/85/NBC code or as per industry standards and its results are within permissible limits.

Pravin Sadashiv Jagtap

Flat no -701 A wing Parshuram Tower Kalyan - Murbad Road Behind Central Bank Mharal Pada Varp Thane.

iv. Concrete/Ready-mix Concrete-

It has been tested for compressive strength for various periods as per IS 456:2000 and IS 1199 or as per other relevant IS/BS/NBC codes, as per industry standards and its results are within permissible limits.

v. Steel for concrete-

It has been tested as per IS 2062:2011 or as per other relevant IS/BS/NBC code or as per industry standards for tensile strength, elongation and gauge length etc. and its results are within permissible limits.

vi. Testing of Other materials

Other materials like sand, crushed sand, floor tiles, fixtures and fittings, pipes and sanitary fittings etc. (List out all items) used in this project conform to relevant IS/BS/NBC code or as per standards laid down by the Industry for a particular material.

2. Workmanship:-

I/ we hereby certify that work has been carried out under our supervision. We further certify that workmanship and quality is satisfactory and up to the mark and the work has been acceptable within the permissible limits of deviations as per relevant code of practice.

3. Electrical Materials and workmanship: –

works of all the electrical wiring/connections/lift installation/other electrical installations have been carried out under authorized/registered electrical engineer and its records has been maintained. The materials used conform to the relevant I.S/ B.S/ National Building codes or as per industry standards.

Pravin Sadashiv Jagtap

Flat no -701 A wing Parshuram Tower Kalyan - Murbad Road Behind Central Bank Mharal Pada Varp Thane.

4. Structural engineer: –

Promoters has engaged structural engineer

Mr. A.R Khasnis

Having Licenses no. BMC/STR/K3


Cell no: 9821210221

The structural design of buildings in this project has been done under his supervision. He has checked the soil report before laying PCC for foundation in consultation with soil consultant. The formwork and concrete mix design has been done as per Is 10262:2009 or as per other relevant codes as applicable. His periodic checks and certificates for STABILITY and SAFETY have been kept on record.

5. Preservation of records: –

Record of all test results of this project have been properly kept in the prescribed formats and will be preserved at least up to the defect liability period or for the period as required by any other provision of law

6. Please specify materials or any other item of work which were not conforming to the standard specifications and which were not rejeded.



Yours Faithfully,

Signature of Engineer (Site Supervisor)

Name: Pravin Sadashiv Jagtap

Diploma Reg no. 111042LDC0285,

Phone no.9765044251

Place: Kalyan