DIP. ARCH. A.I.I.A.



#### **ARCHITECTS & ENGINEERS**

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX: 2207725 TEL.: 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

# FORM 1 [see Regulation 3] ARCHITECT'S CERTIFICATE

Date: - 19th July, 2017

Ankita Builders
Daisy Gardens Survey No.12/12, 15/7 & 11,
KhojKhuntavli, Kamlakar Nagar,
Ambernath (west)

Subject: Certificate of Percentage of Completion of Construction Work of Project "Daisy Gardens", Situated at Survey No. 11 No. of Building(s) 3 of the Project [MahaRERA Registration Number] situated on the Plot bearing CTS No. 24/Survey no. 11/ Final Plot no 11demarcated by its boundaries (latitude and longitude of the end points) \_19.222432 -73.198054 to the North, 19.221785 - 73.221794 to the South, 19.222204 - 73.198199 to the East, 19.222188 - 73.197898 to the West of Division \_Konkan\_ village - Khoj- Khuntavali, taluka - Ambernath, District - Thane, PIN - 421505 admeasuring 2550 sq.mts. area being developed by ANKITA BUILDERS.

Sir,

I Anil R. Nirgude have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion of Construction Work of the Project "Daisy Gardens" situated on the plot bearing Survey no11 CTS No.24 Final Plot no 11 CTS No. 24 of village Khoj-Khutavlitaluka - Ambernath, District - Thane, PIN - 421505 admeasuring 2550 sq.mts. area being developed by ANKITA BUILDERS.

- 1. Following technical professionals are appointed by Owner / Promoter :-
  - (i) Shri. Anil R. Nirugde as L.S. / Architect;
  - (ii) M/s. C.M. CONSULTANTS & PRAMOD KAMBLE as Structural Consultant
  - (iii) Shri. NileshJha& Narendra Singh as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building /Wing of the Real Estate Project as registered vide number under Maha RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

2

DIP. ARCH. A.I.I.A.



## **ARCHITECTS & ENGINEERS**

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX: 2207725 TEL.: 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

2

#### Table A

## **Building No 1**

Sr. No.	Task/Activity	Percentage of work done	
1	Excavation		
2	Number of Plinth	100%	
3	Number of Podiums	-N.A	
4	Stilt Floor	100%	
5	8 Number of Slabs of Super Structure	100%	
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of the Flat/Premises	50%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/ Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%	
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain Occupation/Completion Certificate.	0%	



## **ARCHITECTS & ENGINEERS**

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX: 2207725 TEL.: 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

..3..

## **Building No 2**

Sr. No.	Task/Activity	Percentage of work done 100%	
1	Excavation		
2	Number of Plinth	100%	
3	Number of Podiums	-N.A	
4	Stilt Floor	100%	
5	8 Number of Slabs of Super Structure	100%	
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of the Flat/Premises	50%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/ Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%	
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain Occupation/Completion Certificate.	0%	

DIP. ARCH. A.I.I.A.



## **ARCHITECTS & ENGINEERS**

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX: 2207725 TEL.: 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

#### ..4..

## **Building No 3**

		vitanconsultants@yma	
Sr. No.	Task/Activity	Percentage of work done	
1	Excavation	100%	
2	Number of Plinth	100%	
3	Number of Podiums	-N.A	
4	Stilt Floor	100%	
5	8 Number of Slabs of Super Structure	100%	
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of the Flat/Premises	50%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/ Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%	
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain Occupation/Completion Certificate.	0%	

DIP. ARCH. A.I.I.A.



## ARCHITECTS & ENGINEERS

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX : 2207725 TEL. : 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

..5..

# TABLE - B Building No. 1, 2, 3

Sr. No.	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	yes	100%	
2	Water Supply	yes	0%	
3	Sewerage (chamber, Lines, Septic Tank, STP)	yes	0%	
4	Storm Water Drains	yes	0%	
5	Landscaping & Tree Planting	yes	100%	
6	Street Lighting	yes	100%	
7	Community Buildings	yes	0%	
8	Treatment and disposal of swage and Sullage Water	yes	0%	
9	Solid Waste Management and Disposal	yes	0%	
10	Water Conservation, Rain Water harvesting	yes	0%	
11	Energy management	yes	0%	
12	Fire Protection and Fire safety requirements	yes	0%	
13	Electrical Meter Room, Sub Station, Receiving station	yes	0%	
14	Aggregate Area of Recreational Open Space	ves	0%	
15	Open Parking	yes	100%	
16	Specify if any further facility is provided (other than above mentioned)	no		

Yours Faithfully

VITAN CONSULTANTS

ANIL R. NIRGUDE

Architect CA/81/6472