ANIL R. NIRGUDE

DIP. ARCH. A.I.I.A.

FORM 1 [see Regulation ARCHITECT'S CERTIFICATE

Designated Account)

ARCHITECTS & ENGINEERS

B-101, 1ST FLOOR, BINDU TOWER, (To be submitted at the time of Registration of Ongoing Project and for OPPO drows DESIGNOUN SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX: 2207725 TEL:: 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com vitanconsultants@ymail.com

Date: 31/03/2019

To

Ankita Builders Daisy Garden Survey No.12/12, 15/7 & 11 Khoj Khuntavali, Kamlakar Nagar, Ambernath (west)

Subject : Certificate of Percentage of Completion of Construction Work of Project "Daisy Gardens", Situated at Survey No.11 No. of Building(s) 3 of the Project [Maha RERA Registration Number P51700005390] situated on the Plot bearing CTS No. 24/Survey no.11/ Final Plot no. 11 demarcated by its boundaries (latitude and longitude of the end points) _____to the North 12mtr D.P.ROAD to the South OPEN LAND to the East SHREE SAI RAM NAGAR ROW HOUSE to the West of Division_ Konkan_ village_ Khoj Khuntavali, taluka Ambernath, District – Thane PIN – 421505 admeasuring 2550 sq.mts. Area being developed by ANKITA BUILDERS.

Sir,

I Anil Nirgude have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the Project "Daisy Gardens" situated on the plot bearing Survey no.11 CTS No.24 of village Khoj-Khutavali Taluka-Ambernath, District - Thane, PIN-421505 admeasuring 2550 sq.mts.area being by ANKITA BUILDERS.

- 1. Following technical professionals are appointed by Owner / Promoter :-
- (i) Shri. Anil Nirugde as L.S. / Architect;
- (ii) M/s. C.M.CONSULTANTS & PRAMOD KAMBLE as Structural Consultant
- (iii Shri.Nilesh Jha & Narendra Singh as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number P51700005390 under Maha RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

ANIL R. NIRGUDE

DIP. ARCH. A.I.I.A.



ARCHITECTS & ENGINEERS

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX : 2207725 TEL. : 2207724 / 2203494

E-mail: vitanconsultants@yahoo.com

Table A Building No.1

Sr. No.	Task/Activity vitanco	nsultants@yma Percentage of work done
1	Excavation	100%
2	Number of Plinth	100%
3	Number of Podiums	-N.A
4	Stilt Floor	100%
5	8 Number of Slabs of Super Structure	100%
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of the Flat/Premises	100 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/ Premises	80%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	70%
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain Occupation/Completion Certificate.	25%

Building No.2

Sr. No.	Task/Activity			
1	Excavation			
2	Number of Plinth	100%		
3	Number of Podiums	-N.A		
4	Stilt Floor			
5	8 Number of Slabs of Super Structure			
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of the Flat/Premises			
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/ Premises			
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks			
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing			
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of			





ARCHITECTS & ENGINEERS

B-101, 1ST FLOOR, BINDU TOWER, OPP. LOURDES SCHOOL, SANTOSHI MATA ROAD, KALYAN (W)

TEL. / FAX : 2207725 TEL : 2207724 / 2203494

Building No.3

Sr. No.	E-mail : v	itandonsultants@yahpo.co itandonsultants@ythail.cor work done
1	Excavation	100%
2	Number of Plinth	100%
3	Number of Podiums	-N A
4	Stilt Floor	100%
5	8 Number of Slabs of Super Structure	87%
6	Internal Walls, Internal Plaster, Floorings within flats/premises, Doors and windows to each of Flat/Premises	the 60 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	25%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	25%
9	The External plumbing and external plaster, elevation, completion of terraces with waterproofin of the Building/Wing	ng 60 %
10	Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain Occupation/Completion Certificate.	0%

TABLE - B Building No.1.2.3

Sr. No.	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	yes	100%	
2	Water Supply	yes	0%	
3	Sewerage (chamber, Lines, Septic Tank, STP)	yes	30%	
4	Storm Water Drains	yes	40%	
5	Landscaping & Tree Planting	yes	100%	
6	Street Lighting	yes	100%	
7	Community Buildings	yes	0%	
8	Treatment and disposal of swage and Sullage Water	yes	0%	
9	Solid Waste Management and Disposal	yes	0%	
10	Water Conservation, Rain Water harvesting	yes	0%	
11	Energy management	yes	0%	
12	Fire Protection and Fire safety requirements	yes	0%	
13	Electrical Meter Room, Sub Station, Receiving station	yes	30%	
14	Aggregate Area of Recreational Open Space	yes	0%	
15	Open Parking	yes	100%	
16	Specify if any further facility is provided (other than above mentioned)	no		

Yours Faithfully

VITAN CONSULTANTS

Architect License No. CA/81/06472