

Building Number A3

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Building Number A4

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving	0%

ARCHITECT VIVEK KUMAR**CA/2014/64244**

Page 3 of 11

Vivek Kumar

	of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	
--	---	--

Building Number A5

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Building Number A6

S. No.	Task/ Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%

ARCHITECT VIVEK KUMAR
CA/2014/64244

Vivek Kumar