10.	Installation of lifts, water pumps, Fire Fighting Fittings	0%
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	
	Finishing to entrance lobby/s, plinth protection, paving	
	of areas appurtenant to Building/Wing, Compound Wall	
	and all other requirements as may be required to Obtain	
	Occupation /Completion Certificate	

Building Number A7

T 1/4 4: 14	
Task/Activity	Percentage of work done
Excavation	0%
1 No. Plinth	0%
0 No. of Podiums	Not Applicable
Stilt floor	Not Applicable
5 No. of slabs of superstructure	0%
Internal walls, Internal plaster,	0%
Floorings within flats/premises, Doors & Windows of to	2
each flat/premises	
Sanitary Fittings within the flat/Premise,	0%
Electrical fittings within the flat/Premise	
Staircases, Lifts Wells and Lobbies at each	0%
Floor level connecting Staircases and Lifts,	2.7
Overhead and Underground Water Tanks	
The external plumbing and external plaster,	0%
elevation, completion of terraces with waterproofing of	
the Building/Wing,	
Installation of lifts, water pumps, Fire Fighting Fittings	0%
and Equipment as per CFO NOC, Electrical fittings to	2/4
Common Areas, electro, mechanical equipment,	0.80
Compliance to conditions of environment /CRZ NOC,	8
Finishing to entrance lobby/s, plinth protection, paving	3
of areas appurtenant to Building/Wing, Compound Wall	200
and all other requirements as may be required to Obtain	
Occupation /Completion Certificate	
	Excavation 1 No. Plinth 0 No. of Podiums Stilt floor 5 No. of slabs of superstructure Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing, Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain

Building Number A8

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts,	0%



	Overhead and Underground Water Tanks	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

Building Number B1

S. No.	Number B1 Task/Activity	Percentage of work done
	Excavation	0%
1.	1 No. Plinth	0%
2.		Not Applicable
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	0%
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster,	070
	Floorings within flats/premises, Doors & Windows of to	F 1
	each flat/premises	00/
7.	Sanitary Fittings within the flat/Premise,	0%
	Electrical fittings within the flat/Premise	00/
8.	Staircases, Lifts Wells and Lobbies at each	0%
	Floor level connecting Staircases and Lifts,	4
	Overhead and Underground Water Tanks	*
9.	The external plumbing and external plaster,	0%
	elevation, completion of terraces with waterproofing of	
	the Building/Wing,	8.
10.	D' D'-latin a Eittings	0%
10.	and Equipment as per CFO NOC, Electrical fittings to	85
	Common Areas, electro, mechanical equipment,	£.
	Compliance to conditions of environment /CRZ NOC,	
	Finishing to entrance lobby/s, plinth protection, paving	
	of areas appurtenant to Building/Wing, Compound Wall	
	and all other requirements as may be required to Obtain	
	Occupation /Completion Certificate	
	Occupation /Completion Certificate	

Building Number B2

	Task/Activity	Percentage of work done
1	Excavation	0%
2	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster,	0%
	Floorings within flats/premises, Doors & Windows of to	
	each flat/premises	

ARCHITECT VIVEK KUMAR
CA/2014/64244

Rivek Kuman