7.	Sanitary Fittings within the flat/Premise,	0%
	Electrical fittings within the flat/Premise	
8.	Staircases, Lifts Wells and Lobbies at each	0%
	Floor level connecting Staircases and Lifts,	
	Overhead and Underground Water Tanks	
9.	The external plumbing and external plaster,	0%
	elevation, completion of terraces with waterproofing of	
	the Building/Wing,	
10.		0%
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	
	Finishing to entrance lobby/s, plinth protection, paving	=
	of areas appurtenant to Building/Wing, Compound Wall	
	and all other requirements as may be required to Obtain	
	Occupation / Completion Certificate	2 4

Building Number B3				
Task/Activity	Percentage of work done			
Excavation	0%			
1 No. Plinth	0%			
0 No. of Podiums	Not Applicable			
Stilt floor	Not Applicable			
5 No. of slabs of superstructure	0%			
	0%			
	0%			
	0%			
	K.			
	3			
	0%			
elevation, completion of terraces with waterproofing of	2			
	0%			
and Equipment as per CFO NOC, Electrical fittings to				
Common Areas, electro, mechanical equipment,				
Compliance to conditions of environment /CRZ NOC,				
Finishing to entrance lobby/s, plinth protection, paving				
and all other requirements as may be required to Obtain				
	Excavation 1 No. Plinth 0 No. of Podiums Stilt floor 5 No. of slabs of superstructure Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,			

Building Number B4

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable



5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to	0%
	each flat/premises	
7.	Sanitary Fittings within the flat/Premise,	0%
	Electrical fittings within the flat/Premise	
8.	Staircases, Lifts Wells and Lobbies at each	0%
	Floor level connecting Staircases and Lifts,	=
	Overhead and Underground Water Tanks	*
9.	The external plumbing and external plaster,	0%
	elevation, completion of terraces with waterproofing of	
	the Building/Wing,	
10.		0%
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	-
	Finishing to entrance lobby/s, plinth protection, paving	2
	of areas appurtenant to Building/Wing, Compound Wall	
	and all other requirements as may be required to Obtain	
	Occupation /Completion Certificate	

Building Number B5

S. No.	Task/Activity	Percentage of work done
1.	Excavation	0%
2.	1 No. Plinth	0%
3.	0 No. of Podiums	Not Applicable
4.	Stilt floor	Not Applicable
5.	5 No. of slabs of superstructure	0%
6.	Internal walls, Internal plaster, Floorings within flats/premises, Doors & Windows of to each flat/premises	0%
7.	Sanitary Fittings within the flat/Premise, Electrical fittings within the flat/Premise	0%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10.		*