## FORM 1 ARCHITECT'S CERTIFICATE

To Vascon Engineers, Vascon Weikfield Chambers, Vascon Weikfield IT City Infopark, Pune Nagar Road, Viman Nagar, Pune - 14

Date: June 5, 2020,

Subject: Certificate of percentage of Completion of Construction Work of **Phase A** – building 1, building 2, building 4&5, of the **'VASCON GOOD LIFE'** Project situated on the G. NO. 78,79,80,132,133,134,135 AT KATVI, TAL. MAVAL, PUNE. Demarcated by its boundaries (latitude 18°44'35.68"N, and longitude 73°39'48.41"E of the end points), Gat no. 80,81 to the **North** 12.00 m wide internal road to the **South**, Gat no. 72 to the **East**, and remaining plot of Good Life to the **West** in Village –Katvi, Taluka-Maval, District- Pune. PIN-410507, admeasuring **8893.00 Sq.mts**. out of total plot area admeasuring **35045.64 sq.mt**. being developed by **Vascon Engineers LTD**.

Sir.

I, Ar. Leena Dharde Upadhye have undertaken assignment as Architect of certifying percentage of Completion of Construction Work of Phase A – building 1, building 2, building 4&5, of the 'VASCON GOOD LIFE' Project situated on the G. NO. 78,79,80,132,133,134,135 AT KATVI, TAL. MAVAL, PUNE. in Village –Katvi, Taluka-Maval, District- Pune. PIN-410507, admeasuring 8893.00 Sq.mts. out of total plot area admeasuring 35045.64 sq.mt. being developed by Vascon Engineers LTD.

Following technical professionals are appointed by Owner / Promoter :-

- (i) Ar. Sandeep Hardikar as L.S. / Architect.
- (ii) Dr. Santosh Sunderajan (Vastech Consultants) as Structural Consultant.
- (iii) Shri Madhusudan Murthy (Power Engineers) as Electrical Consultant
- (iv) Mr. Vivek Botre as Project Head.

Based on Site Inspection, with respect to each of the Building of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of work done for the above mentioned building of the Real Estate Project is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

| Sr. No | Tasks /Activity   | Percentage of work done |
|--------|---|-------------------------|
| 1      | Excavation  |                         |
| 2      | Plinth  | 100%<br>92%             |
| 3      | Number of Podiums   | 0%                      |
| 4      | Stilt Floor   | 78%                     |
| 5      | 10 number of Slabs of Super Structure   | 40%                     |
| 6      | Internal walls, Internal Plaster,<br>Floorings within Flats/Premises,<br>Doors and Windows to each of the Flat/Premises   | 20%                     |
| 7      | Sanitary Fittings within the Flat/Premises,<br>Electrical Fittings within the Flat/Premises   | 0%                      |
| 8      | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts,  |                         |
|        | Overhead and Underground Water Tanks  | 0%                      |
| 9      | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,  | 0%                      |
| 10     | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate | 0%                      |
|        | Overall percentage of completion of work done for the entire building/ wing.  | 38%                     |

TABLE-B

Internal & External Development Works in Respect of the entire Registered
Phase

| SR.N<br>O. | COMMON AREAS & FACILITIES AND AMENITIES              | PROPOSED<br>(YES/NO) | PERCENTAGE OF WORK COMPLETED | DETAILS |
|------------|--|----------------------|------------------------------|---------|
| 1          | Internal Road & Footpath                             | YES                  | 0%                           |         |
| 2          | Water Supply   | YES                  | 0%                           |         |
| 3          | Sewage (Chambers, Lines, STP)                        | YES                  | 0%                           |         |
| 4          | Storm Water drain                                    | YES                  | 0%                           |         |
| 5          | Landscape & Tree Planting                            | YES                  | 0%                           |         |
| 6          | Street Light   | YES                  | 0%                           |         |
| 7          | Community Building                                   | NO                   |                              |         |
| 8          | Treatment & Disposal of Sewage & Sulage water        | YES                  | 0%                           |         |
| 9          | Solid Waste Management & disposal                    | YES                  | 0%                           |         |
| 10         | Water Conservation, Rain water harvesting            | YES                  | 0%                           |         |
| 11         | Energy Management                                    | NO                   |                              |         |
| 12         | Fire Protection & Safety                             | YES                  | 0%                           |         |
| 13         | Electrical Meter room, Substation, Receiving Station | YES                  | 0%                           |         |
| 14         | Aggregate Area of Open space                         | YES                  | 0%                           |         |
| 15         | Open Parking (Visitor's)                             | YES                  | 0%                           |         |

Yours Faithfully.

Name : Ar. Leena Dharde Upadhye .

Date : 05/06/2020 Regn no.: **CA/2000/ 25883**