

## FORM 1 ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

To Kumar Beharay Properties LLP, Project- HILLVIEW RESIDENCY 796/189 B, Bhandarkar Institute Road, Deccan Gymkhana, Pune 411 004.

Subject: Certificate of Percentage of Completion of Construction Work of Wings/Buildings N & O out of the project Hill view Residency [MahaRERA Registration Number P52100014885] situated on the land bearing S. No. 69/5B/2, 69/8/1 & 70/1 to 17A1 demarcated by its boundaries (18°19'51.60"N, 73°47'27.07"E to the North, 18°18'50.75"N, 73°47'35.61"E to the South, 18°30'00.57"N, 73°47'35.21"E to the East, 18°30'01.05"N, 73°47'31.91"E to the West of Division) Village: Kothrud, Taluka: Haveli, District: Pune, Pin.: 411 038, admeasuring 5566.56 Sq.mts. (Proportionate Plot area for Mentioned Wings/Buildings) being developed by Kumar Beharay Properties LLP.

Sir,

I, Ar. Jagadish P. Deshpande have undertaken assignment as an Architect for certifying Percentage of Completion of Construction Work of Wings/Buildings N & O out of the project "Hill View Residency", situated on the land bearing S. No. 69/5B/2, 69/8/1 & 70/1 to 17A1, Village: Kothrud, Taluka: Haveli, District: Pune, Pln.: 411 038 admeasuring 5566.56 Sq.mts. (Proportionate Plot area for Mentioned Wings/Buildings) being developed by Kumar Beharay Properties LLP.

- 1. As informed by the Owner / Promoter following technical professionals are appointed:
- (i) Mr. Jagadish P. Deshpande as Liaison Architect.
- (ii) M/s, A, Solanki & Associates as Design Architects.
- (iii) M/s. Sunil Mutalik & Associates as Structural Consultants.
- (iv) Integrated Consultant as MEP Consultants.
- (v) Mrs. Shobha Bhopatkar as Landscape Consultant.
- (vi) M/s. S. B. Khurjekar & Company Advocates.
- (vii) Mr. Milind Vaman Sahasrabudhe Advocates.
- (viii) Mr. Vivek Haralkar Site Supervisor.

Based on Site Inspection, with respect to Wings/Buildings N & O out of the aforesaid Real Estate Project "Hill view Residency", I certify that as on the date of this certificate, the Percentage of Construction Work done of Wings/Buildings N & O out of the Real Estate Project as registered vide number P52100014885 under MahaRERA is as per "Table A" enclosed herewith. The percentage of the development works executed till 31/12/2019 with respect to each of the activity of the entire phase is detailed in "Table B".

Date: 07/01/2020

Place: Pune

(Jagadish P. Deshpande)

..2



architect

PRO	DJEC	BUILDING 'N' TABLE A  T - HILLVIEW RESIDENCY, S. No. 69/5B/2, 6 Village: Kothrud, Taluka: Haveli, District: LDG. NAME - 'N', 2P + 15 Floors, Total No. of T	Pune. Pin: 411 038.	-2012/06/04/05/04/04/04/05/04		
Sr. No.		Tasks/Activity				
1	Exca	Excavation				
2	a)	Lower Parking		100%		
2	b)	Upper Parking		100%		
3	a)	Podium I (Not proposed)		N.A.		
ં	b)	b) Podium 2 (Not proposed)				
4	-	floor Parking (Ground Floor Parking)		100%		
5	4,212,011	ber of Slabs of Super Structure arkings +15 floors)	17 Slabs completed	100%		
			No. of Flats			
	a)	Internal Walls	52	86.66%		
	b)	Internal Plaster- Toilets	60	100%		
6	c)	Internal Plaster-Flats	48	80%		
	d)	Flooring within Flats/Premises	Nil	0%		
	e)	Doors and Windows to each of the Flat/Premises	Nil	0%		
			No. of Floors			
7	a)	Sanitary Fittings within Flats/Premises	Nil	0%		
	b)	Electrical Fittings within Flats/Premises	Nil	0%		
	Structural work only		No. of Floors			
	a)	Staircases	15 Floors	100%		
8	b)	Lift Wells	15 Floors	100%		
	c)	Lobbies at each floor connecting staircase & lift	Nil	0%		
	d)	Overhead and Underground Tanks		0%		
	a)	External Plumbing (No. of Ducts)	Nil	0%		
9	b)	External Plaster (No. of Sides)	Nil	0%		
	c)	Elevation Treatment (No. of Sides)	Nil	0%		
	d)	Completion of Terraces with Waterproofing of the Building/Wing	NiI	0%		

Date: 07/01/2020

Place: Pune

(Jagadish P. Deshpande)

..3



architect

..3...

10	a)	Installation of Lifts (3 Lifts - 1 Stretcher + 2 Passengers)	Nil	0%
	b)	Water Pumps	Nil	0%
	c)	Fire Fighting Fittings and Equipment as per CFO NOC	Nil	0%
	d)	Electrical Fittings to Common areas of floors (No. of Floors)	Nil	0%
	e)	Electro- Mechanical Equipment	524	N.A.
	f)	Compliance to conditions of environment/CRZ NOC No. SEAC-2010/CR.727/TC.2	F2.	
	g)	Finishing to entrance lobby/s	Nil	0%
	h)	Plinth Protection	15-5	Yes
	i)	Paving of areas appurtenant to Building/Wing	Nil	0%
	j)	Compound Wall	Nil	0%
	k)	All other requirements as may be required to obtain Occupation/Completion Certificate	<del>(**</del>	-

Date: 07/01/2020

Place : Pune

(Jagadish P. Deshpande)



..4..

PRO	JEC	BUILDING 'O' TABLE A  T - HILLVIEW RESIDENCY, S. No. 69/5B/2, Village: Kothrud, Taluka: Haveli, District: LDG. NAME - 'O', 2P + 15 Floors, Total No. of T	Pune. Pin: 411 038.	
Sr. No.	Tasks/Activity			Percentage of Work completed
1	Exca	Excavation		
2	a)	a) Lower Parking (Not proposed)		
2	b)	Upper Parking (Not proposed)		100%
3	a)	Podium 1 (Not proposed)		N.A.
	b)	Podium 2 (Not proposed)		N.A.
4	Stilt	Stilt floor Parking (Ground Floor Parking)		
5	Number of Slabs of Super Structure (2 Parkings +15 floors)		17 Slabs completed	100%
		5°	No. of Flats	
	a)	Internal Walls	52	86.66%
	b)	Internal Plaster- Toilets	60	100%
6	c)	Internal Plaster- Flats	48	80%
	d)	Flooring within Flats/Premises	Nil	0%
	e)	Doors and Windows to each of the Flat/Premises	Nil	0%
			No. of Floors	
7	a)	Sanitary Fittings within Flats/Premises	Nil	0%
	b)	Electrical Fittings within Flats/Premises	Nil	0%
	Structural work only		No. of Floors	
3	a)	Staircases	15 Floors	100%
8	b)	Lift Wells	15 Floors	100%
	c)	Lobbies at each floor connecting staircase & lift	Nil	0%
	d)	Overhead and Underground Tanks	1	0%
	a)	External Plumbing (No. of Ducts)	Nil	0%
	b)	External Plaster (No. of Sides)	Nil	0%
9	c)	Elevation Treatment (No. of Sides)	Nil	0%
	d)	Completion of Terraces with Waterproofing of the Building/Wing	Nil	0%

Date: 07/01/2020

Place: Pune

(Jagadish P. Deshpande)

..5



..5..

	a)	Installation of Lifts (3 Lifts - 1 Stretcher + 2 Passengers)	Nil	0%
	b)	Water Pumps	Nil	0%
	c)	Fire Fighting Fittings and Equipment as per CFO NOC	Nil	0%
	d)	Electrical Fittings to Common areas of floors (No. of Floors)	Nil	0%
30	e)	Electro- Mechanical Equipment		N.A.
10	f)	Compliance to conditions of environment/CRZ NOC No. SEAC-2010/CR.727/TC.2		C70
	g)	Finishing to entrance lobby/s	Nil	0%
	h)	Plinth Protection		Yes
	i)	Paving of areas appurtenant to Building/Wing	Nil	0%
	j)	Compound Wall	Nil	0%
	k)	All other requirements as may be required to obtain Occupation/Completion Certificate	144	-

Date: 07/01/2020

Place: Pune

(Jagadish P. Deshpande)



..6..

## TABLE B

Internal & External Development Works in Respect of the entire Registered Phase

	of proportionate land				
No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details	
1	a) Internal Roads	Yes	0%	**	
	b) Footpaths	No	224		
2	Water Supply	Yes	0%	-	
	Sewerage				
	a) Chamber	Yes	0%	<del>(10</del> )	
3	b) Lines	Yes	0%		
	c) Septic Tanks	No	<del>**</del> **		
	d) STP	Yes	100%	77 (m.)	
4	Storm Water Drains	Yes	0%	**:	
5	Landscaping and Tree Planting	Yes	0%	***	
6	Street Lighting	Yes	0%	***	
7	Community Buildings	No	2.00	48	
8	Treatment and Disposal of sewage and sullage water	Yes	0%	State of the state	
9	Solid Waste Management & Disposal	Yes	0%	###	
10	Water Conservation, Rain Water Harvesting	Yes	0%	S <del>el</del> sk	
11	Energy Management (Solar - Water Only)	Yes	U%	3000	
12	Fire protection and Fire safety requirements	Yes	0%	77.22km	
13	a) Electrical meter room	Yes	0%	i <del>i i i</del>	
	b) Sub-station	Yes	28	Area handed over to MSEB	
	c) Receiving station (Civil work completed & Unit installed)	Yes	0%		
4	Others (Option to Add more)			7 (22	

Date: 07/01/2020

Place: Pune

(Jagadish P. Deshpande)