

3rd Floor, Arihant Building, Agyari Laine, Jambhli Naka. Thane - 400 601 | Tel: 2540 6310 • e-mail: suvarnaghoshi@gmail.com

FORM 1 [see Regulation 3]

ARCHITECT'S CERTIFICATE

Date: 20/09/2019

To, CONCORDE REALTY.

Address: -Cosmos House, Behind T.M.C. Office, Sant Dnyaneshwar Road, Pachpakhadi, Thane (W).

Subject: Certificate of Percentage of Completion of Construction Work of COSMOS MELUHA, of Building(s)/10 Wing(s) of the 3 Phase of the Project [P51700009729] situated on the Plot bearing C.N. No/CTS No. /Survey No./ Final Plot No. __No155/1B, 155/4/1/B, 156/2, 157/1B, 157/2, 162/1demarcated by its boundaries (latitude and longitude of the end points)

Latitude 19 9' 20.17"N and longitude 73 3' 48, 29 E to the North Latitude 19 9' 14, 02"N and longitude 73 3' 44.71" E to the South Latitude 19 9' 17.10"N and longitude 73 3' 48.47" E to the East Latitude 19 9' 17.47"N and longitude 73 3' 44.20" E to the West

Of Division KOKAN village KHIDKALI taluka THANE District THANE (M. CORP.)PIN 421204 admeasuring 16370 sq.mts. Area being developed by CONCORDE REALTY.

Sir.

J/-We-SMT, SUVARNA GHOSH have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the Building(s) 10W ing(s) of the Phase of the Project. COSMOS MELUHA situated on the plot bearing C.N. No/CTS No/Survey No./ Final Plot No155/1B, 155/4/1/B, 156/2, 157/1B, 157/2, 162/1 of Division KOKAN village KHIDKALI Taluka THANE District THANE (M. CORP)PIN421204 admeasuring 16370sq.mts. Area being developed by CONCORDE REALTY.

- 1. Following technical professionals are appointed by Owner-Promoter:-
- (i) M/s/Shri/SMT-SUVARNA GHOSH as L.S. / Architect;
- (ii) M/s/Shri-/Smt R.C TIPNIS Structural Consultant
- (iii) M/s /Shri-/Smt ELECTROMECH CONSULTANTS as MEP Consultant
- (iv) M/s /Shri /Smt SAGAR CHAVAN Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project. I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number P51700009729 under MAHARERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A COSMOS MELUHA Building 4 - OMKARA (Gr Pt. +7)

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	- number of Basement(s) and Plinth	
3	number of Podiums	
4	Stilt Floor	100%
5	8number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	50%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

Table A COSMOS MELUHA Building 5 - OMKARA (Gr Pt. +7)

Sr. No	Sr. No Tasks /Activity	
1	Excavation	100%
2	number of Basement(s) and Plinth	
3	number of Podiums	
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	50%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

Table A COSMOS MELUHA Building 6 - OMKARA (Gr Pt. +7)

Sr. No Tasks /Activity		Percentage of work done	
1	Excavation	100%	
2	number of Basement(s) and Plinth		
3	number of Podiums		
4	Stift Floor	100%	
5	8 number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises		
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Fanks		
8			
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing. Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate		
10			

Table A COSMOS MELUHA Building 7 - OMKARA (Gr Pt. +7)

Sr. No		
1		
2	number of Basement(s) and Plinth	
3	- number of Podiums	
4	Stilt Floor	100%
5	8number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	50%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

Table A COSMOS MELUHA Building 8 - PASHUPATI (Stilt+7)

Sr. No	Sr. No Tasks /Activity	
1	Excavation	100%
2	- number of Basement(s) and Plinth	
3	number of Podiums	
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	6,25%
7	Sanitary Fittings within the Flat/Premises. Electrical Fittings within the Flat/Premises	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

Table A - COSMOS MELUHA Building 9 - PASHUPATI (Stilt+7)

Sr. No Tasks / Activity		Percentage of work done	
1	Excavation	100%	
2	number of Basement(s) and Plinth		
3	number of Podiums		
4	Stilt Floor	100%	
5	8 number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flots/Premises, Doors and Windows to each of the Flat/Premises	6.25%	
7	Sanitary Fittings within the Flat/Premises. Electrical Fittings within the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks		
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,		
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate		

Table A COSMOS MELUHA Building 10 - PASHUPATI (Stilt+7)

Sr. No	Tasks / Activity	Percentage of work done	
1	Excavation	100%	
2	number of Basement(s) and Plinth		
3	number of Podiums	10.00	
4	Stilt Floor	100%	
5	8 number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	6.25%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks		
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.		
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC. Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate		

Internal & External Development Works in Respect of the entire Registered Phase

TABLE-B

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
l.	Internal Roads & Foothpaths	Yes		To be completed before o.c.
2.	Water Supply	Yes	4	
3.	Sewerage (chamber, lines, Septic Tank, STP)	Yes	1 114	To be completed before o.c.
4.	Storm Water Drains	Yes	7.	to be completed before o.c.
5,	Landscaping & Tree Planting	Yes		to be completed before o.c.
6.	Street Lighting	Yes	*	to be completed before o.c.
7.	Community Buildings	Yes		to be completed before o.c.
8.	Treatment and disposal of sewage and sullage water	Yes		to be completed before o.c.
9_	Solid Waste management & Disposal	Yes	-	to be completed before o.c.
10.	Water conservation, Rain water harvesting	Yes		only rain water harvesting to be completed before o.e.
11.	Energy management	Yes		only solar water heater & d.g. set installation to be completed before o.c.
12.	Fire protection and fire safety requirements	No		
13.	Electrical meter room, sub- station, receiving station	Yes	3	to be completed before o.c.
14.	Aggregate area of recreational open spaces	3320.94		to be completed before o.e.
15.	Open Parking	Yes		
16.	Others (Option to Add more)	4"	-	

Yours Faithfully

Signature

Name: - SUVARNA CLOSH of LaSt Architect

(License NO. CA/91/14324)