FORM-2A

[See MahaRERA order no. of 2018]

ENGINEER'S CERTIFICATE FOR QUALITY ASSURANCE

(site supervisor's certificate)

To,

Yashada Nivasa Associates

Dudulgaon,

Pune - 412105

Quality Assurance Certificate

(Certificate no. 01 for the quarter ending June 2019)

Subject: Certificate for quality of materials used and quality of Construction and workmanship for the Work of 02 No. of Buildings / A & B wings of the I Phase of the project situated on the Plot bearing S. NO. 215, demarcated by its boundaries (latitude- 18°40'46.95"N and longitude - 73°52'4.59"E of the end points) to the North S. NO GAT NO 212, to the South Forest Land to the East S. NO GAT NO 212 to the West S. NO GAT NO 216 of Division Pune, village- WAKAD, taluka- Haveli, District - Pune, PIN – 412105, admeasuring 3641.23 sq.mts. area being developed by Yashada Nivasa Associates

rashada Mivasa Associates

Reference: MahaRERA Registration Number- P52100002191

Sir,

I Mr. Upendra Gulve have undertaken an assignment of supervision of this real estate project.

1. Our Responsibility: -

To carry out the work in accordance with the development permission and as per the approved plan and submit certificate of supervision of work and to carry out material testing in-situ or in the authorized laboratory and to ensure quality of work and

ii. Coarse aggregate -

It has been tested, for deleterious materials, clay lumps, crushing value, impact value as per IS 243011986 or as per other relevant IS/BS/NBC code or as per industry standards and its results are within the permissible limits.

iii. Bricks/ blocks -

They have been tested for water absorption, crushing strength etc. as per IS 5454:1978 or as per other relevant IS/85/NBC code or as per industry stan fords, and its results are within permissible limits.

iv. Concrete/Ready-mix Concrete-

It has been tested for compressive strength for various periods as per 15 456:2000 and IS 1199 or as per other relevant IS/BS/NBC codes, as per industry standards and its results are within permissible limits.

v. Steel for concrete-

It has been tested as per IS 2062:2011 or as per other relevant IS/BS/NBC code or as per industry standards for tensile strength, elongation and gauge length etc. and its results are within permissible limits.

vi. Testing of Other materials

Other materials like sand, crushed sand, floor tiles, fixtures and {ittings, pipes and sanitary fittings etc. (List out all items) used in this project conform to relevant IS/BS/NBC code or as per standards laid down by the Industry for a particular material.

2. Workmanship:-

I/ we hereby certify that work has been carried out to der our supervision. We further certify that workmanship and quality is satisfactory and on to the mark and the work has been acceptable within the permissible limits of deviations as per relevant code of practice.

3. Electrical Materials and workmanship: -

works of all the electrical wiring/connections/lift installations have been carried out under authorized/registered electrical engineer and its records has been maintained. The materials used conform to the want LS/ B.S/ National Building codes or as per industry standards.

4. Structural engineer: -

Promoters has engaged structural engineer Mr.G.A THLARE CONSULTANT PVT LTD Mr. Hemant Nimbalkar having Licenses no. PMC-383 had affice no 02067215411 cell no

The structural design of buildings in this project has been ander his supervision. He has checked the soil report before laying PCC for foundation accountation with soil consultant. The formwork and concrete mix design has been done as her is 10262:2009 or as per other relevant codes as applicable. His periodic checks and cellicates for STABILITY and SAFETY have been Light record.

on

5. Preservation of records: -

Record of all test results of this project have been propagate in the prescribed formats and will be preserved at least up to the defect liability product or for the period as required by any other provision of law

6. Please specify materials or any other item of work a light were not conforming to the standard specifications and which were not rejeded.

Yours Faithfully,

1

Signature of Engineer (Site Supervisor)

Name: UPENDRA G. GULVE License no.(if any)———— Phone no. 7888012381

Place:PUNE