

### ARCHITECT'S CERTIFICATE

Date: 24/07/2017

Ref. No. TADPL \_102/Bloomfield/ J&K Building/ RERA/ Certificate/17

To,

Amit Enterprises,

PUNE.

**Subject**: Certificate of Percentage of Completion of Construction Work of Building J & k of the Project "AMIT'S BLOOMFIELD PHASE-III" of the project [MahaRERA Registration Number] situated on the S.nos. 59(pt) & S.no. 4 (pt) demarcated by its boundaries to the North-Internal road [N-18°27'7.70"N 73°49'50.39"E], To East -Amenity space -2 [E- 18°27'6.88"N 73°49'51.31"E], To South – Service road and Mumbai-Banglore Highway [S- 18°27'7.00"N 73°49'50.04"E], To West –Internal road and plot boundary -[ W- 18°27'7.97"N 73°49'49.18"E] Mouje- Ambegaon Budruk, Tal-Haveli, Dist- Pune of Total Land Admeasuring 68805.22 sq.mts, wherein Net plot Area 57791.95 sq.mts out of which area admeasuring 21004.53 sq.mts is being developed by Amit Enterprises Housing Ltd.

Sir.

I/We, Ar. Sameer Valimbe have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the building "J &K" of the project "AMIT'S BLOOMFIELD PHASE-III" situated on the S.nos. 59(pt) & S.no. 4 (pt) Mouje -Ambegaon Budruk, Tal-Haveli, Dist -Pune of Total Land Admeasuring 68805.22 sq.mts, wherein Net Plot Area 57791.95 sq.mts out of which area admeasuring 21004.53 sq.mts is being developed by Amit Enterprises Housing Ltd.

- 1. Following technical professionals are appointed by Owner / Promoter: -
- (i) Ar. Sameer Valimbe as Architect.
- (ii) M/s JW CONSULTANTS LLP as Structural Consultant.
- (iii) M/s sn joshi consultants pvt. ltd. as Electrical Consultant.
- (iv) M/s Unicorn MEP consultants Pvt Ltd.
- (v) M/s Nilima Bhosekar as Landscape architect.
- (vi) M/s Ultratect as environmental architect.
- (vii) Shri. Milind Patki as Project Manager (Site Supervisor).

The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



# Table A

# Building "J":

Sr. No	Tasks /Activity	Percentage of work done
î.	Excavation	100%
2.	One number of basement & Plinth	0%
3.	one number of Podiums	0%
4.	Stilt floor	0%
5.	22 number of Slabs of Super Structure	0%
4.	Internal walls	0%
5.	Internal Plaster	0%
6.	Floorings within Flats/Premises,	0%
	Doors and Windows to each of the Flat/Premi	ises
7.	Sanitary Fittings within the Flat/Premises,	0%
	Electrical Fittings within the Flat/Premises	
8.	Staircases, Lifts Wells and Lobbies at each	0%
	Floor level connecting Staircases and Lifts,	
	Overhead and Underground Water Tanks	
9.	The external plumbing and external plaster,	0%
	elevation, completion of terraces with waterp	proofing of
	the Building/Wing,	
10.	Installation of lifts, water pumps, Fire Fighting F	Fittings 0%
	and Equipment as per CFO NOC, Electrical fit	ttings to
	Common Areas, electro, mechanical equipm	nent,
	Compliance to conditions of environment /CI	RZ NOC,
	Finishing to entrance lobby/s, plinth protection	n,
	paving of areas appurtenant to Building/Wing	9.
	Compound Wall and all other requirements a	s may be
	required to Obtain Occupation /Completion	Certificate





## Building "K":

Sr. No	Tasks /Activity Perce	Percentage of work done	
ĩ.	Excavation	100%	
2.	One number of basement & Plinth	50%	
3.	one number of Podiums	0%	
4.	Stilt floor	0%	
5.	22 number of Slabs of Super Structure	0%	
4.	Internal walls	0%	
5.	Internal Plaster	0%	
6.	Floorings within Flats/Premises,	0%	
	Doors and Windows to each of the Flat/Premises		
7.	Sanitary Fittings within the Flat/Premises,	0%	
	Electrical Fittings within the Flat/Premises		
8.	Staircases, Lifts Wells and Lobbies at each	0%	
	Floor level connecting Staircases and Lifts,		
	Overhead and Underground Water Tanks		
9.	The external plumbing and external plaster,	0%	
	elevation, completion of terraces with waterproof	ing of	
	the Building/Wing,		
10.	Installation of lifts, water pumps, Fire Fighting Fitting	gs 0%	
	and Equipment as per CFO NOC, Electrical fittings	to	
	Common Areas, electro, mechanical equipment,		
	Compliance to conditions of environment /CRZ NO	OC.	
	Finishing to entrance lobby/s, plinth protection,		
	paving of areas appurtenant to Building/Wing,		
	Compound Wall and all other requirements as ma	ny be	
	required to Obtain Occupation /Completion Cert	ificate	





## TABLE-B

S.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
,				
1.	Internal Roads & Footpaths	YES	0%	Driveways will be provided
2.	Water Supply	YES	0%	Water supply from Pune Municipal Corporation
3.	Sewerage (chamber, lines, Septic Tank, STP)	YES	0%	STP
4.	Storm Water Drains	YES	0%	
5.	Landscaping & Tree Planting	YES	0%	
6.	Street Lighting	YES	0%	
J.	Community	120	0,0	Multipurpose hall
7.	Buildings	Yes	0%	for all phases
8.	Treatment and disposal of sewage and sullage water	YES	0%	STP
9.	Solid Waste management & Disposal	YES	0%	owc
10.	Water conservation, Rain water harvesting	YES	0%	Recharge Pit
11.	Energy management		0%	Solar Water Provision and low energy consuming light fittings will be provided.
12.	Fire protection and fire safety requirements	YES	0%	As per Fire and safety norms of competent Authority.
13.	Electrical meter room, sub-station, receiving station	YES	70%	Sub-Station, Receiving Station is completed
14.	Aggregate Area of open Space	YES	100%	Common for all phases.
15.	Open Parking	Yes	0%	
16.	Gymnasium	Yes	100%	





17.	Squash Court	Yes	100%	Common for all phases.
18.	Cards+Chess Room	Yes	100%	
19.	Billiards Room	Yes	100%	
20.	Guest Room	Yes	100%	
21.	Swimming pool	Yes	100%	
22.	Toddler's pool	Yes	100%	
23.	Changing room	Yes	100%	
24.	Jacuzzi	Yes	100%	
25.	Steam Bath	Yes	100%	
26.	Fountain	Yes	100%	
27.	Tennis Court	Yes	100%	
28.	Children's Play Area	Yes	100%	
29.	Herbal Garden	Yes	100%	

Yours Faithfully,

Ar. Sameer Valimbe.

CA/92/14618