

FORM 1 ARCHITECT'S CERTIFICATE

Date: 27/06/2017

To S2 REALTY, PUNE.

Subject · Certificate of Percentage of Completion of Construction Work of TWO (2) No. of **Buildings A, B, & C** of the first phase of the Project CAVANSITE WARJ Esituated on the Plot bearing Survey no. 111/1 demarcated by its boundaries [N-18°29'21.5"N 73°47'32.1"E], [S-18°29'15.1"N 73°47'32.0"E], [E-18°29'18.5"N 73°47'35.2"E], [W-18°29'17.9"N 73°47'31.5"E] to the North: 12 mtr wide Service Road to the South: S. No. 81 (P)to the East: S. No. 112(P) and 113 to the West: S. No. 111(P), RMD College of Division WARJE village HAVELI taluka PUNE District admeasuring 12,000 sq.mts. area being developed by S2 REALTY.

Sir.

We, M/s. Jay Prakash Aeram Associates have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the TWO (2) Buildings A,B, C of the first Phase of the Project CAVANSITE WARJE, situated on the plot bearing Survey no.111/1 of WARJE village HAVELI taluka PUNE District admeasuring 12,000sq.mts. area being developed by S2 REALTY.

- Following technical professionals are appointed by Owner / Promoter:-
- (i) Mr. Jay Aeram as an Architect;
- (ii) M/s SPECTRUM CONSULTANTS as Structural Consultant
- (iii) M/s ZOPATE ELECTRICAL CONSULTANTS as Electrical Consultant
- (iii) M/s APEX PLUMBING CONSULTANT as Plumbing Consultant
- (iv) Shri Prashant Chavan as Project Manager (Site Supervisor)

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered vide number under MahaRERA is as per table A herein below.

The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

1

Table A
Ruilding /Wing Number A

	Building / wi	ng Number_ A	
Sr.No.	Tasks /Activity	Percentage of work done %	
1	Excavation	0%	
2	number of Basement(s) and Plinth	0%	
3	number of Podiums	0%	
4	Stilt Floor	0%	
5	number of Slabs of Super Structure	0%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises		
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	



Table A uilding /Wing Number_

	Building /W	ing Number_B	
Sr.No.	Tasks /Activity	Percentage of work done %	
1	Excavation	100%	
2	02 number of Parking and Plinth	80%	
3	00 number of Podiums		
4	Stilt Floor	- 050/	
5	number of Slabs of Super Structure	65%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	25%	
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks 65%		
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	



Table A Building /Wing Number_

	T A	'ing Number_C	
.No.	Tasks /Activity	Percentage of work done %	
1	Excavation	100%	
2	01 number of Parking and Plinth	80%	
3	00 number of Podiums		
4	Stilt Floor		
5	04 number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster,	100%	
7	Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
9	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
10	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90%	
11	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	100%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	



TABLE-B
Internal & External Development Works in Respect of the entire Registered Phase

S.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Foothpaths	YES	0%	
2	Water Supply	YES	0%	
3	Sewarage (chamber, lines, Septic Tank	YES	0%	
4	Storm Water Drains	YES	0%	
5	Landscaping & Tree Planting	YES	0%	
6	Street Lighting	YES	0%	
6	Electrical meter room, sub- station,	YES	0%	
7	Aggregate area of recreational Open Space :	YES	0%	
8	Open Parking:	YES	0%	
9	Community Buildings	YES	0%	
10	Treatment and disposal of sewage and	YES	0%	
11	Solid Waste management & Disposal	YES	0%	
12	Water conservation, Rain water	YES	0%	
13	Energy management	YES	0%	
14	Fire protection and fire safety requirements	YES	0%	

Thanking You,

Regards

JAY AERAM (ARCHITECT)