

Table A
COSMOS MELUHA Building 6 - OMKARA (Gr Pt. +7)

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	__ - __ number of Basement(s) and Plinth	100%
3	__ - __ number of Podiums	--
4	Stilt Floor	100%
5	__ 8 __ number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	46%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	--
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	33%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	25%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	--

J J Ghal

Table A
COSMOS MELUHA Building 7 - OMKARA (Gr Pt. +7)

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	- number of Basement(s) and Plinth	100%
3	- number of Podiums	--
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	32%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	--
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	33%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	25%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	--

JJG

Table A
COSMOS MELUHA Building 8 - PASHUPATI (Stilt+7)

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	- number of Basement(s) and Plinth	100%
3	- number of Podiums	--
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	3%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	--
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	16%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	--
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	--

U/G

Table A
COSMOS MELUHA Building 9 - PASHUPATI (Stilt+7)

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	__ - __ number of Basement(s) and Plinth	100%
3	__ - __ number of Podiums	--
4	Stilt Floor	100%
5	__ 8 __ number of Slabs of Super Structure	87.5%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	3%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	--
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	16%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	--
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	--

Table A
COSMOS MELUHA Building 10 - PASHUPATI (Stilt+7)


Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100%
2	- number of Basement(s) and Plinth	100%
3	- number of Podiums	-
4	Stilt Floor	100%
5	8 number of Slabs of Super Structure	87.5%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	3%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	--
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	16%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	--
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	--

JSGW

TABLE-B
Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Foothpaths	Yes	-	To be completed before o.c.
2.	Water Supply	Yes	-	
3.	Sewerage (chamber, lines, Septic Tank , STP)	Yes	-	To be completed before o.c.
4.	Storm Water Drains	Yes	-	to be completed before o.c.
5.	Landscaping & Tree Planting	Yes	-	to be completed before o.c.
6.	Street Lighting	Yes	-	to be completed before o.c.
7.	Community Buildings	Yes	-	to be completed before o.c.
8.	Treatment and disposal of sewage and sullage water	Yes	-	to be completed before o.c.
9.	Solid Waste management & Disposal	Yes	-	to be completed before o.c.
10.	Water conservation, Rain water harvesting	Yes	-	only rain water harvesting to be completed before o.c.
11.	Energy management	Yes	-	only solar water heater & d.g. set installation to be completed before o.c.
12.	Fire protection and fire safety requirements	No	-	-
13.	Electrical meter room, sub-station, receiving station	Yes	-	to be completed before o.c.
14.	Aggregate area of recreational open spaces	3320.94	-	to be completed before o.c.
15.	Open Parking	Yes	-	
16.	Others (Option to Add more)	-	-	

Yours Faithfully



Signature

Name: - SUVARNA GHOSH of L.S/ Architect
(License NO. CA/91/14324)

Suvarna S. Ghosh

Architect

301, 'Arihant' Agvadi Lane