# Form- 2A ENGINEER'S CERTIFICATE FOR QUALITY ASSURANCE (Site Supervisor's Certificate)

(To be uploaded Quarterly)

Date: 9th Nov 2019

To,

The NAMRATA CONSTRUCTION COMPANY

592, Raviwar Peth, Talegaon Dabhade, Tal:

Maval, Dist: Pune-410507.

# Quality Assurance Certificate

(Certificate no 01 for the quarter ending September 2019)

Subject: Certificate for quality of materials used and quality of construction and workmanship for the work of 2 No. Of Building(s)/ K & L Wing(s) of the project "Aikonic 2" situated on the plot bearing C.S. No./C.T.S. No./Survey No./Final Plot No. 38/2/1(Old), 49/2/1(New) PART,C.T.S. 377,392 (PART), Talegaon dabhade-410507. Demarcated by its boundaries (latitude 18°44'24.67" N and longitude 73°40'41.5" E of the end points)

C.T.S. no. 357 to the North,12 M Wide D.P. Road to the south, C.T.S. No. 371,372,373,374,375,376 to the East, C.T.S. No. 379 to the West of division Pune village:Talegaon Dabhade, Taluka: Maval, Dist: Pune,Pin-410507, admeasuring 2396.10 Sq.Mts Area being developed by Namrata Construction Company.

Reference: MAHARERA Registration Number- P52100022242

Sir,

I/We \_\_\_\_Sudhir Suresh Kumbhar\_\_ have undertaken as assignment of supervision of this real estate project.

# Our Responsibility:-

To carry out the work in accordance with the development permission and as per the approved plan and submit certificate of supervision of work and to carry out material testing in-situ or in the authorized laboratory and to ensure quality of work and workmanship as per prescribed specifications , and as per NBC and or other relevant code of practice.

#### 1.Material Testing:-

I/We, have applied following mandatory checks on the basic materials, used in the construction.

#### i)Cement-

It has been tested for its fineness, soundness, setting time, compressive strength etc. as per IS code 3535:1986 or as per other relevant IS/BS/NBC code, or as per industry standards and its results are within the permissible limits.

#### ii)Coarse Aggregate-

It has been tested, for deleterious materials, clay lumps, crushing value, impact value as per IS 2430:1986 or as per other relevant IS/BS/NBC Code or as per industry standards and its results are within the permissible limits.

#### iii)Bricks/Blocks-

The have been tested for water absorption , crushing strength etc. as per IS 5454:1978 or as per other relevant IS/BS/NBC code or as per industry standards and its results are within permissible limits.

#### iv)Concrete /Ready -Mix Concrete-

It has been tested for compressive strengths for various periods as per IS 456:2000 and IS:1199 or as per other relevant IS/BS/NBC codes, as per industry standards and its results are within permissible limits.

#### v)Steel For Concrete-

It has been tested as per IS 2062:2011 or as per other relevant IS/BS/NBC code or as per industry standards for tensile strength , elongation and gauge length etc. and its results are within permissible limits.

#### vi)Testing of Other materials-

Other materials like sand, crushed sand, floor tiles, fixtures and fittings, pipes and sanitary fittings etc. (List out all items) used in this project conform to relevant IS/BS/NBC or as per standards laid down by the industry for a particular material

### 2.Workmanship:-

I/We hereby certify that work has been carried out under our supervision. We further certify that workmanship and quality is satisfactory and up to the mark and the work has been acceptable within the permissible limits of deviations as per relevant code of practice

# 3. Electrical Materials and workmanship:-

Works of all the electrical wirings/ connections/lift Installation/ other electrical installations have been carried out under authorized/ registered electrical engineer and its records has been maintained. The materials used conform to the relevant IS/BS/National Building Codes or as per industry standards.

4.Structural	<b>Engineer:-</b>
--------------	-------------------

Promoters	has engaged structural eng	ineer w/s_kanui Darvekar And
Associates	having Licenses no	having office no
	cell no	·

The structural design of buildings in this project has been done under his supervision. He has checked the soil report before laying PCC for foundation in consultation with soil consultant. The formwork and concrete mix design has been done as per IS 10262:2009 or as per other relevant codes as applicable. His periodic checks and certificates for STABILITY and SAFETY have been kept on record.

## 5.Preservation of records:-

Record of all test results of this project have been properly kept in the prescribed formats and will be preserved at least up to the defect liability period or for the as period as required by any other provision of law.

**6.**Please specify materials or any other item of work which were not conforming to the standards specification and which were not rejected.

Yours Faithfully,

CONSTANTANT CO. + APAMARA CO.

Signature of Engineer (Site Supervisor)

Name: Sudhir S. Kumbhar

Phone No: 7757008203

Place: Talegon dashall.