

SHAILENDRA CHAUHAN ARCHITECT & INTERIOR DESIGNER

117,DEVPATH,B/H LAL BUNGLOW,C.G. ROAD,AHMEDABAD-380006,PHONE: (O) +91 79 26403288,E-mail: ar.shailendra@gmail.com

FORM 1

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 31/05/2019

To, KUSHAL INFRASTRUCTURE PVT.LTD. C/o KUSHAL AWAAS-2, Plot no-74, behind Patel rice mill, new vatva. Ahmadabad.

Subject: Certificate of Percentage of Completion of Construction Work of KUSHAL AWAAS-2Building ENTIRE Phase of the Project BLOCK B,C,D AND E+F(PR/AHMEDABAD/AHMEDABAD CITY/AUDA/180226/004714) situated on the Plot bearing SUB PLOT No.2, F.P.No.30/3,T.P.S. No.84 (VATWA), F.P 74 LAND to the North, F.P 73 LAND to the South, F.P 66/1 AND F.P 67 LANDto the East And 12 Mt. Road to the West of Division, Village-VATWA, Taluka- VATWA, District-Ahmedabad is owned by KUSHAL INFRASTRUCTURE PVT.LTD. Having its "KUSHAL AWAAS-2" ADMESSURING 5278SQ.MT. BEING DEVELOPED byKUSHAL INFRASTRUCTURE PVT.LTD.

Sir,

I SHAILENDRA CHAUHANhave undertaken assignment as Architect of certifying Percentage of Completion of Construction of KUSHAL AWAAS-2Plot bearing SUB PLOT No.2, F.P.No.30/3,T.P.S. No.84 (VATWA) at , Village-VATWA, Taluka- VATWA, District-Ahmedabad is owned by KUSHAL INFRASTRUCTURE PVT.LTD. having its "KUSHAL AWAAS-2" ADMESSURING 5278 SQ.MT. BEING DEVELOPED by KUSHAL INFRASTRUCTURE PVT.LTD.AS PER THE PLAN.

Following technical professionals are appointed by Owner/Promoter:- (as applicable)

- 1. Shri KRUNAL K. MISTRY as Engineer
- 2. Shri KRUNAL K. MISTRYas Structural Consultant
- 3. Shri AMIT DAVE

as MEP Consultant

4. Shri AMIT DAVE

as Site Supervisor/Clerk of Works

Based on Site Inspection undersigned on31/05/2019with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number (PR/AHMEDABAD/AHMEDABAD CITY/AUDA/180226/004714) under GujRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table A and B.

ARCHITECTS & INTERIOR DESIGNER 117, DEVPATH, B/H. LAL BUNGLOW, C. G. FIDAD, AHMEDABAD-380006. CA/2003/31903

Table - A

Building/Wing Number - BLOCK-B(KUSHAL AWAAS-2)

Building	Wing Number - BLOCK-BIKOSHAL ATTAIN TO	Percentage of work done
Sr. No.	Tasks/Activity	100%
1	Excavation	
2	Onumber of Basement(s) and Plinth	N/A
3	number of Podiums	N/A
4	Stilt Floor	N/A
5	EIGHT Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within	
	Flats/Premises, Doors and Windows to each of	100%
	the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises	60%
8	Staircases, Lifts Wells and Lobbies at each Floor	100%
0	level connecting Staircases and Lifts, Overhead	
	and Underground Water Tanks	
9	The external plumbing and external plaster,	65%
	elevation, completion of terraces with	
	waterproofing of the Building/Wing.	
10	Installation of lifts, water pumps, Fire Fighting	0%
	Fittings and Equipment as per CFO NOC,	
	Electrical fittings to Common Areas, electro,	
	mechanical equipment, compliance to	
	conditions of environment/CRZ NOC, Finishing	
	to entrance lobby/s, plinth protection, paving of	
	areas appurtenant to Building/Wing, Compound	
	Wall and all other requirements as may be	
	required to Obtain Occupation/Completion	
	Certificate	

Table - A

Building/Wing Number - BLOCK-C(KUSHAL AWAAS-2)

Sr. No.		
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	number of Podiums	N/A
4	Stilt Floor	N/A
5	EIGHT Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within	
	Flats/Premises, Doors and Windows to each of	100%
	the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises	80%
8	Staircases, Lifts Wells and Lobbies at each Floor	100%
	level connecting Staircases and Lifts, Overhead	
	and Underground Water Tanks	
9	The external plumbing and external plaster,	100%
	elevation, completion of terraces with	
	waterproofing of the Building/Wing.	
10	Installation of lifts, water pumps, Fire Fighting	65%
	Fittings and Equipment as per CFO NOC,	
	Electrical fittings to Common Areas, electro,	
	mechanical equipment, compliance to	4.1 (6)
	conditions of environment/CRZ NOC, Finishing	All and the second seco
	to entrance lobby/s, plinth protection, paving of	
	areas appurtenant to Building/Wing, Compound	
	Wall and all other requirements as may be	
	required to Obtain Occupation/Completion	· · · · · · · · · · · · · · · · · · ·
	Certificate	SHAILENDRA CHAUH

Table - A

Building/Wing Number - BLOCK-D (KUSHAL AWAAS-2)

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	0 number of Basement(s) and Plinth	N/A	
3	number of Podiums	N/A	
4	Stilt Floor	N/A	
5	EIGHT Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%	
7	Sanitary Fittings within the Flat/Premises	90%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	75%	

Table - A

Building/Wing Number - BLOCK- E+F (KUSHAL AWAAS-2)

Sr. No.	p. Tasks/Activity Percentage of work done		
1	Excavation	100%	
2	0 number of Basement(s) and Plinth	N/A	
3	number of Podiums	N/A	
4	Stilt Floor	N/A	
5	EIGHT Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within	9-1	
	Flats/Premises, Doors and Windows to each of the Flat/Premises	100%	
7	Sanitary Fittings within the Flat/Premises	90%	
8	Staircases, Lifts Wells and Lobbies at each Floor	100%	
	level connecting Staircases and Lifts, Overhead		
	and Underground Water Tanks		
9	The external plumbing and external plaster,	100%	
	elevation, completion of terraces with	a single contraction of	
	waterproofing of the Building/Wing.		
10	Installation of lifts, water pumps, Fire Fighting	75%	
	Fittings and Equipment as per CFO NOC,		
	Electrical fittings to Common Areas, electro,	A 10 M 10	
	mechanical equipment, compliance to	KLAS, FLORIDA	
	conditions of environment/CRZ NOC, Finishing	18 Jan	
	to entrance lobby/s, plinth protection, paving of		
	areas appurtenant to Building/Wing, Compound	The state of the s	
	Wall and all other requirements as may be	THE RESERVE OF THE PARTY OF THE PARTY OF THE PARTY.	
	required to Obtain Occupation/Completion		
	Certificate	MI ENDRA CHAUHAN	
	ARO 117. C. C	All ENLIFIA LITROSIGNER HITECTS & INTERIOR DESIGNER DEVPATH, B/H. LAL BUNGLOW, DEVET HER BENEFIT HER BUNGLOW, DEVET HER BY BROWN, DEVET HER BUNGLOW, DEVET HER BY BROWN, DEVET HER BUNGLOW, DEVET HER BY BROWN, D	

TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

<u></u>	Common areas and	Proposed	Percentage of	Remarks
Sr.	Facilities Amenities	(Yes/No)	Work Done	
No1	Internal Roads &	YES	0%	-
	Footpaths	YES	0%	-
2	Water Supply	YES	0%	-
3	Sewerage (chamber,	1123		
	lines, Septic Tank, STP)	YES	0%	-
4	Storm Water Drains	YES	0%	-
5	Landscaping & Tree	ILJ		
	Planting	YES	0%	-
6	Street Lighting	N.A.	0%	-
7	Community Buildings		0%	-
8	Treatment and disposal	N.A.	070	
	of sewage and sullage			
	water /STP		0%	<u> </u>
9	Solid Waste Management	N.A	0%	
	& Disposal			
10	Water Conservation, Rain	YES	0%	-1.0
	Water Harvesting,		11	10 0 5/25
	Percolating Well/Pit			
11	Energy Management	N.A.	0%	-
12	Fire Protection and Fire	YES	0%	-
	Safety Requirements			
13	Electrical Meter Room,	YES	0%	- 60
	Sub-station, Receiving		,	
	Station			
14	Fire fighting facilities	YES	0%	-
15	Drinking water facilities	YES	0%	-
16	Emergency evacuation	N.A.	0%	-
	services .			
17	Use of renewable energy	N.A.	0%	-
18	Security using CCTV	YES	0%	
	surveillance		"	Rate was
19	Letter Box	YES	0%	_

Yours-Kaithfully

MR. SHAILENDRA CHAUHAN 117,DEVPATH

AHMEDABAD.

B/H LAL BUNGLOW C.G ROAD,

(License No : CA/2003/31903)

SHAILENDRA CHAUHAN ARCHITECTS & INTERIOR DESIGNER 117, DEVPATH, B/H, LAL BUNGLOW, C.G. FOAD, AHMEDABAD-380006. CA/2003/31903

Council of Architects (CoA) Registration No: CA/2003/31903. Council of Architects (CoA) Registration valid till (Date): 31/12/2024.