
#### FORM1 [as per Regulation 3]

#### ARCHITECT'S CERTIFICATE FOR

Project Unique Identification No.: P52100018824 (as per MahaRERA)

To, Mr. Preyesh G. Daswani M/S. Bharat Developers Pune



<u>Subject</u>: Certificate of Percentage of Completion of Construction Work of **03 Buildings** of the Project 'THE Province' (MahaRERA Registration Number P52100018824) situated on the Plot bearing S.No.16/3 demarcated by its boundaries (latitude and longitude of the end points) 18°37'25.76"N,73°44'1.16"E to the North,18°37'24.78"N,73°44'1.02"E to the South, 18°37'24.27"N, 73°44'5.36"E to the East & 18°37'26.06"N,73°43'57.52"E to the West) of Division Pune Village Punavale Taluka Mulshi District Pune, Pin 411019 admeasuring 7,550.00 sq.mt. area being developed by Mr. Preyash G.Daswani & others, M/s. Bharat Developers

Sir.

We VK:a architecture have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work for the above mentioned project.

- 1. Following technical professionals are appointed by Owner / Promoter :-
- (I) M/s. VK:a architecture as Architect;
- (ii) G. A. Bhilare Consultants PVT. LTD., as Structural Consultant
- (iii) M/s Skyline as MEP Consultant
- (iv) Mr. Ajinath Patil as Site Engineer



Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate

Project, I certify that as on the date of this certificate, the Percentage of Work done for each of
the building/Wing of the Real Estate Project as registered vide number P52100018824 under VK:a

MahaRERA is as per table A herein below. The percentage of the work executed with respect to

each of the activity of the entire phase is detailed in Table B.

<u>Note</u>: Above certificate has been made based on the data provided by Promoter & Project Engineer and visual inspection carried out on site.



VK:a architecture

73/2, Bhakti Marg,
 Off Law College Road,
 Pune 411 004

+91 20 66268888

+91 20 66268801

e: mail@vkarch.com

w: www.vkarch.com

Table A Building - C

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100
2	Number Basement	NA
3	Podiums	NA
4	Stilt Floor	0
5	Number of Slabs of Super Structure	0
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0
а	Internal walls	0
b	Internal Plaster	0
С	Floorings within Flats/Premises	0
d	Doors to each of the Flat/Premises	0
е	Windows to each of the Flat/Premises	0
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0
а	Sanitary Fittings within the Flat/Premises	0
b	Electrical Fittings within the Flat/Premises	0
8	Staircases, Lifts Wells & Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0
а	Staircases	0
b	Lifts Wells	0
С	Lobbies at each Floor level connecting Staircases and Lifts	0
d	Overhead and Underground Water Tanks	0
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
а	External plumbing	0
b	External plaster	0
С	Elevation	0
d	Completion of terraces with waterproofing of the Building/Wing,	0
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0
а	Installation of lifts	0
b	Fire Fighting Fittings and Equipment as per CFO NOC	0
С	Electrical fittings to Common Areas	0
d	Mechanical Equipment	0
е	Environment /CRZ NOC	NA
f	Finishing to entrance Lobby/s	0
g	Plinth Protection-antitermite	0
h	Water Pumps	0







## VK:a architecture

a: 73/2, Bhakti Marg, Off Law College Road, Pune 411 004

t: +91 20 66268888

f: +91 20 66268801

e: mail@vkarch.com

# Table A Building – D

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	100
2	Number Basement	NA
3	Podiums	NA
4	Stilt Floor	0
5	Number of Slabs of Super Structure	0
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0
а	Internal walls	0
b	Internal Plaster	0
С	Floorings within Flats/Premises	0
d	Doors to each of the Flat/Premises	0
е	Windows to each of the Flat/Premises	0
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0
а	Sanitary Fittings within the Flat/Premises	0
b	Electrical Fittings within the Flat/Premises	0
8	Staircases, Lifts Wells & Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0
а	Staircases	0
b	Lifts Wells	0
С	Lobbies at each Floor level connecting Staircases and Lifts	0
d	Overhead and Underground Water Tanks	0
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0
а	External plumbing	0
b	External plaster	0
С	Elevation	0
d	Completion of terraces with waterproofing of the Building/Wing,	0
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0
а	Installation of lifts	0
b	Fire Fighting Fittings and Equipment as per CFO NOC	0
С	Electrical fittings to Common Areas	0
d	Mechanical Equipment	0
е	Environment /CRZ NOC	NA
f	Finishing to entrance Lobby/s PLOT NO.7312	0
g	Plinth Protection-antitermite	0
h	Water Pumps COLLEGE RD.,	0







## VK:a architecture

- a: 73/2, Bhakti Marg, Off Law College Road, Pune 411 004
  - +91 20 66268888
- f: +91 20 66268801
- e: mail@vkarch.com
- w: www.vkarch.com

# Table A Building – A2

Sr. No Tasks /Activity	Percentage of work done
1 Excavation	100
2 Number Basement	NA
3 Podiums	NA
4 Stilt Floor	0
5 Number of Slabs of Super Structure	0
Internal walls, Internal Plaster, Floorings within Flats/Premises  Doors and Windows to each of the Flat/Premises	s, 0
a Internal walls	0
b Internal Plaster	0
c Floorings within Flats/Premises	0
d Doors to each of the Flat/Premises	0
e Windows to each of the Flat/Premises	0
7 Sanitary Fittings within the Flat/Premises, Electrical Fittin within the Flat/Premises	gs 0
a Sanitary Fittings within the Flat/Premises	0
b Electrical Fittings within the Flat/Premises	0
Staircases, Lifts Wells & Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
a Staircases	0
b Lifts Wells	0
c Lobbies at each Floor level connecting Staircases and Lifts	0
d Overhead and Underground Water Tanks	0
The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Win	ng, 0
a External plumbing	0
b External plaster	0
c Elevation	0
d Completion of terraces with waterproofing of the Building/Wing,	0
Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requiremen as may be required to Obtain Occupation /Completion Certificate	t ts
a Installation of lifts	0
b Fire Fighting Fittings and Equipment as per CFO NOC	0
c Electrical fittings to Common Areas	0
d Mechanical Equipment	0
e Environment /CRZ NOC	NA
f Finishing to entrance Lobby/s	0
g Plinth Protection-antitermite (COLLEGE RD.)	0
h Water Pumps	0







### VK:a architecture

a: 73/2, Bhakti Marg, Off Law College Road, Pune 411 004

t: +91 20 66268888

f: +91 20 66268801

e: mail@vkarch.com

TABLE-B Internal & External Development Works in Respect of the entire Registered Phase I

Sr. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	Yes	0	Work yet to be start
2	Water Supply	Yes	0	Work yet to be start
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0	Work yet to be start
4	Storm Water Drains	Yes	0	Work yet to be start
5	Landscaping & Tree planting	Yes	0	Work yet to be start
6	Street Lighting	Yes	0	Work yet to be start
7	Electrical meter room, sub-station	Yes	0	Sub-station - NA
8	Open Parking	Yes	0	Work yet to be start
9	Community Buildings	NA		-
10	Treatment and disposal of sewage and sullage water	Yes	0	Work yet to be start
11	Solid Waste management & Disposal	NA		-
12	Water conservation, Rain water harvesting	Yes	0	Water conservation - NA
13	Energy management	Yes	0	Work yet to be start
14	Fire protection and fire safety requirements	Yes	0	Work yet to be start
15	Swimming Pool	NA	0	-
16	Multipurpose court	NA	0	=
-	Part of the second of the seco		520 - T	Expense to the control of the control of

Yes

0

Work yet to be start





Yours Faithfully

Ar. Hrishikesh Kulkarni VK:a architecture

17 | Compound Wall

(Regd. No. CA/2002/29235)

PLOT NO.7312 BHAKTIMARG

COLLEGE RD



#### VK:a architecture

- a: 73/2, Bhakti Marg, Off Law College Road, Pune 411 004
- t: +91 20 66268888
- f: +91 20 66268801
- e: mail@vkarch.com
- w: www.vkarch.com

\*1