

## ARCHITECT'S CERTIFICATE (F1)

Regd. No.: 965/2014

Date: 24-05-2023

- (To be submitted at the time of Registration of Ongoing Project and for Withdrawal of Money from Designated Account)

To

HALLMARK PROPERTIES
PLOT NO 23, HIG, ALKAPOOR TOWNSHIP,
NEKNAMPOOR (V), GANDIPET (M),
RANGAREDDY (DIST),
TELANGANA - 500 089.

**Subject:** Certificate of Percentage of Completion of Construction work of 5 Nos of Buildings of the Hallmark Sunny side Project situated on the Survey No 418, 470, 471, 425/A, 425/B, 425/C, 473/Part, demarcated by its boundaries to the North: Survey No.473/Part and to South Survey.No.471 Part & 80'-0" Wide Road and to the East Survey Nos. Survey Nos.425/Part & 470/Part, and to the West Survey Nos. 60'-0" Wide Road, Manchirevula Village &G.P., Rajendranagar Mandal(Old), Gandipet Mandal(New), Ranga Reddy District, Telangana State 500 089 admeasuring 27947. Square yards area being developed by Hallmark Properties.

Sir,

I/ We **Instone** have undertaken assignment as Architect /<del>Licensed Surveyor of certifying Percentage of Completion of Construction Work of the \_\_5\_\_\_Building(s)/\_\_\_\_Wing(s) of the \_\_1\_Phase of the Project, situated on the plot bearing <del>C.N. No/CTS No./Survey no Survey Nos. 418, 470, 471, 425/A, 425/B, 425/C, 473/Part, admeasuring 27947.07 Square yards situated at MANCHIREVULA Village, Gandipet Mandal (previously Rajendranagar Mandal), Ranga Reddy District, Telangana State.</del></del>

1.	Following technical professionals are appointed by Owner	/ Promoter: -
----	--	---------------

- (i) M/s/Shri/Smt\_\_Instone \_\_\_\_ as L.S. / Architect
- (ii) M/s-/Shri /-Smt\_ N Vamshi Krishna \_\_ as Structural Consultant
- (iii) M/s /Shri / Smt\_Synergy Infra Consultants Pvt Ltd \_\_ as MEP Consultant
- (iv) M/s-/Shri /-Smt\_\_Shaik Abdul Muzeer\_as Project Manager

Based on Site Inspection, with respect to each of the Building/Wing of the foresaid Real Estate Project, I certify that as on the date of this certificate, the percentage of work done for each of the building/Wing of the Real Estate Project as registered vide number P02400001918 under TSRERA is as per table A here in below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Instone RAMANA REDDY SOMA

ARCHITECT Reg. No. CA/2015/09370 COUNCIL OF ARCHITECTURE

Architecture . Interiors . Landscape

Sr No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2 -	Number of Basements and Plinth	100%
3	Number of Podiums	100%
4	Stilt Floor	100%
5	Number of Slabs of super structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	60%
3	Staircases, Lifts Wells and Lobbies at each Floor level connecting Stare cases and Lifts, Overhead and Underground Water Tanks.	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
0	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, Electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation Certificate.	80%

Long

Instone
RAMANA REDDY SOMA
ARCHITECT
Reg. No. CA/2015/69370
COUNCIL OF ARCHITECTURE

Sr No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2 -	Number of Basements and Plinth	10070
3	Number of Podiums	100%
		100%
4	Stilt Floor	100%
5	Number of Slabs of super structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises Doors and Windows to each of the Flat/Premises	80%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
3	Staircases, Lifts Wells and Lobbies at each Floor level connecting Stare cases and Lifts, Overhead and Underground Water Tanks.	100%
	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	80%
0	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, Electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation Certificate.	80%

RAMANA REDDY SOMA

ARCHITECT

Sr No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	Number of Basements and Plinth	10070
3	Number of Podiums	100%
4		100%
	Stilt Floor	100%
5	Number of Slabs of super structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises	60%
IVe	Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises,	0%
	Electrical Fittings within the Flat/Premises	
}	Staircases, Lifts Wells and Lobbies at each Floor level	100%
	connecting Stare cases and Lifts, Overhead and Underground Water Tanks.	
	The external plumbing and external plaster, elevation,	80%
	completion of terraces with waterproofing of the	3070
	Building/Wing.	
0	Installation of lifts, water pumps, Fire Fighting Fittings and	60%
	Equipment as per CFO NOC, Electrical fittings to Common	
	Areas, Electro , mechanical equipment, Compliance to	
	conditions of environment/CRZ NOC, Finishing to entrance	
	lobby/s, plinth protection, paving of areas appurtenant to	
	Building/Wing, Compound Wall and all other requirements as	
	may be required to Obtain Occupation Certificate.	

RAMANA REDDY SOMA

Sr No	Tasks/Activity	Percentage of work done
1	Excavation	
2 -	Number of Basements and Plinth	100%
	reamber of basements and Plinth	
3	Number of Podiums	100%
		100%
4	Stilt Floor	100%
5	Number of Slabs of super structure	100%
6	Internal walls, Internal Plaster,	
	Floorings within Flats/Premises	60%
	Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises,	0%
	Electrical Fittings within the Flat/Premises	070
	Staircases, Lifts Wells and Lobbies at each Floor level	100%
	connecting Stare cases and Lifts, Overhead and Underground	10070
	Water Tanks.	
	The external plumbing and external plaster, elevation,	(00)
	completion of terraces with waterproofing of the	60%
	Building/Wing.	
)	Installation of lifts, water pumps, Fire Fighting Fittings and	
		60%
	Equipment as per CFO NOC, Electrical fittings to Common	
	Areas, Electro , mechanical equipment, Compliance to	
	conditions of environment/CRZ NOC, Finishing to entrance	
	lobby/s, plinth protection, paving of areas appurtenant to	
	Building/Wing, Compound Wall and all other requirements as	
	may be required to Obtain Occupation Certificate.	

RAMANA REDDY SOMA

ARCHITECT

Sr No	Tasks/Activity	Percentage of work done
1	Excavation	
2 -	Number of Basements and Plinth	100%
	of Basements and Finth	
		100%
3	Number of Podiums	100%
4	Stilt Floor	100%
5	Number of Slabs of super structure	
6	Internal walls, Internal Plaster,	100%
		50%
	Floorings within Flats/Premises	
	Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises,	00/
	Electrical Fittings within the Flat/Premises	0%
}	Staircases, Lifts Wells and Lobbies at each Floor level	1000/
	connecting Stare cases and Lifts, Overhead and Underground	100%
	Water Tanks.	
	The external plumbing and external plaster, elevation,	60%
	completion of terraces with waterproofing of the	
	Building/Wing.	
0	Installation of lifts, water pumps, Fire Fighting Fittings and	
	Equipment as per CFO NOC, Electrical fittings to Common	30%
	Areas, Electro , mechanical equipment, Compliance to	
	conditions of environment/CRZ NOC, Finishing to entrance	
	lobby/s, plinth protection, paving of areas appurtenant to	
44	Building/Wing, Compound Wall and all other requirements as	
	may be required to Obtain Occupation Certificate.	

RAMANA REDDY SOMA

TABLE - B

Internal & External Development Works in Respect of the entire Registered Phase

Sno	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	Yes	50%	Not Yet Started
2	Water Supply	Yes	30%	Not Yet Started
3	Sewarage (Champber, lines,Septic Tank, STP)	Yes	80%	Not Yet Started
4	Strom Water Drains	Yes	60%	Not Yet Started
5	Landscaping & Tree Planting	Yes	40%	Not Yet Started
6	Street Lighting	Yes	30%	Not Yet Started
7	Community Building	Yes	50%	Not Yet Started
8	Treatment and disposal of sewage and sullage water	Yes	80%	Not Yet Started
9	Solid Waste management & Disposal	Yes	60%	Not Yet Started
10	Water conservation, Rain water harvesting	Yes	60%	Not Yet Started
11	Energy management	Yes	60%	Not Yet Started
12	Fire protection and fire safety requirements	Yes	60%	Not Yet Started
13	Electrical meter room, sub-station, receiving station	Yes	60%	Not Yet Started
14	Others	NO	NA	NA

Yours Faithfully

For Instone

Authorized Signatory RAMANA REDDY SOMA

CA/2015/69370

Instone

RAMANA REDDY SOMA

ARCHITECT