- Engineers
- · Architects
- · Licensed Surveyor
- . Development Manager
- PMC



## FORM 1

## ARCHITECT'S CERTIFICATE

Date: 15/07/2019

To

M/s Shraddha Landmark Pvt Ltd 301, Sai Heritage, Tilak Road, Above Axis Bank Ghatkopar East, Mumbai - 400077

Subject: Certif	icate of Percentage of Comple	ction of Constru	ction Work of I
MHADA Redeve	elopment Building, situated or	n Plot bearing C	rs No 351(pt) of
Village Hariyal	i, Tagore Nagar, Building	No 22, Taluka	Kurla, Mumbai
Suburban Dis	trict, Mumbai - 400083, M	aharashtra der	marcated by its
boundaries (las	titude and longitude of the	end points)	N &
	*E to the North	N &	_E to the South
	E to the East		
West of Divisi	on Konkan, Village Hariyali,	Tagore Nagar,	Building No 22,
Taluka Kurla,	Mumbai Suburban District,	Mumbai - 4000	983 admeasuring
754.36 sqmtrs.	Area being developed by M/s	Shraddha Landn	nark Pvt Ltd

Sir

I Shri. Sachin Rakshe of M/s Archo Consultants have undertaken assignment of Architect/LS of certifying percentage of completion of construction work of I MHADA Redevelopment Building, situated on Plot bearing CTS No 351 (pt) of Village Hariyali, Taluka Kurla, Mumbai Suburban District, Mumbai - 400083, Maharashtra

SACHIN K. RAKSHE BE. (Civil), Licensed Surveyor (R/172/LS/2009)

Ground Floor, Room No 2, A-Wing, Sunveiw CHS Ltd., off Sahakar Theater, Tilaknagar, Chembur (W), Mumbai-400 089
Tel.: 022 25272997 | Mob.: +91 9833986465 | Email archaeonsultants@gmail.com

- 1. Following technical professionals are appointed by the Promoter;
- i) Shri. Sachin Rakshe of M/s Archo Consultants as Architect/ LS;
- ii) Shri. Vinayak Chopdekar of M/s Vinayak Chopdekar & Associates as Structural Consultant
- iii) Shri Rajendra Bankar as Site Supervisor

Based on site inspection, with respect to each of the building/wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the percentage of work done for each of the building / wing of the Real Estate Project as registered vide number -- under RERA is as per Table A herein below.

TABLE A

## MHADA REDEVELOPMENT BUILDING

Sr. No	Tasks / Activity	% of Work Done
1.	Excavation	10%
2.	No Basement Only 1 Number of Plinth	0%
3.	0 Number of Podiums	NA
4.	Stilt Floor	0%
5.	24 Number of Slabs of Super Structure	0%
6.	Internal Walls, Internal Plaster, Flooring with Flat / Premises, Doors and Windows to each of the Flat / Premises	0%
7.	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8.	Staircases, Lifts Wells and Lobbies at Each Floor Level connecting staircases and lifts, Overhead and Underground	0%

Sochin Ratife

SACHIN K. RAKSHE BE. (Civil), Licensed Surveyor (R/172/LS/2009)

	Water Tanks	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building /	0%
10.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance Lobby, Plinth Protection, Paving of Areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate	0%

The percentage of work executed with respect to each of the major activity of the Building / Wing and Overall Percentage of work done with respect to each of the Building / Wing is detailed in Table

TABLE B

Sr.	Common Areas and	Propose	Percentag	Details
No	Facilities, Amenities	d (Yes /	e of Work	
		No)	Done	
1.	Internal Roads & Footpaths	Yes	0%	Driveway
2.	Water Supply	Yes	0%	MCGM
3.	Sewerage (Chamber Lines, Septic Tank, STP)	Yes	0%	MCGM
4.	Storm Water Drains	Yes	0%	Developer
5.	Landscape & Tree Planting	No	0%	NA

SACHIN K. RAKSHE BE. (Civil), Licensed Surveyor (R/172/LS/2009)

1	Street Lighting	Yes	004	
1	Community Buildings	No	0%	Driveway Lighting
8.	Treatment and Disposal	No	0%	NA
	of sewage and sullage water		070	NA
9.	Solid Waste	No	00/	
10.	Management & Disposal		0%	NA
10.	Water Conservation,	Yes	0%	Only Rain Water
	Rain Water Harvesting			Harvesting by
11.	Energy Management			Developer
12.	Fire Protection & Fire	No	0%	NA
	Safety Requirements		0%	Developer
13.	Electrical Meter Room, Sub-station, receiving station		0%	Developer
14.	Others - Mechanical / Stack Parking System	Yes	0%	Developer
15	. Others - Society Office	Yes	0%	Developer
16	. Others - Fitness Center	Yes	0%	Developer

## Yours Faithfully

Shri. Sachin Rakshe (LS)

of M/s Archo Consultants

Architect /LS

License No: R/172/LS/2009

SACHIN K. RAKSHE BE. (Civil), Licensed Surveyor (R/172/LS/2009)