

e-mail:ss\_associates1@yahoo.co.in

#### FORM 1

## ARCHITECT'S CERTIFICATE

Date: 26/07/2017

Τo

M/s Om Vaishnavi Developers 301, Sai Heritage, Tilak Road, Above Axis Bank Ghatkopar East, Mumbai – 400077

Subject: Certificate of Percentage of Completion of Construction Work of I Composite Building with 1 Sale Wing & 1 Rehab Wing, situated on Plot bearing CTS No 893, 893/1 and 894 of Village Kanjur, Taluka Kurla, Mumbai Suburban District, Mumbai - 400042, Maharashtra demarcated by its boundaries (latitude and longitude of the end points) 19°08'05.39"N & 72°56'16.50"E to the North 19°08'04.76"N & 72°56'18.13"E to the South 19°08'05.33"N & 72°56'17.62"E to the East 19°08'04.39"N & 72°56'16.67"E to the West of Division Konkan; Village Kanjur; Taluka Kurla; District Suburban Mumbai PlN 400042 admeasuring 847.3 sqmtrs. Area being developed by M/s Om Vaishnavi Developers.

Sir

1 Smt. Sheetal Nikhare of S. S. Associates have undertaken assignment of Architect of certifying percentage of completion of Construction Work of 1 Composite Building with /1 Sale Wing & 1 Rehab Wing, situated on Plot





e-mail; ss\_associates1@yahoo.co.in

bearing CTS No 893, 893/1 and 894 of Village Kanjur, Taluka Kurla, Mumbai Suburban District, Mumbai - 400042, Maharashtra

- 1. Following technical professionals are appointed by the Promoter;
- i) Smt. Sheetal Nikhare of S.S.Associates as Architect;
- ii) Shri. Bahubali T. Dhamane of M/s Shravani Consultant as Structural Consultant
- iii) Shri Rajendra Bankar as Site Supervisor

Based on site inspection, with respect to each of the building/wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the percentage of work done for each of the building / wing of the Real Estate Project as registered vide number — under RERA is as per Table A herein below.

#### TABLE A

### SALE WING "A":

Sr.	Tasks / Activity	% of
No		Work
PROPERTY OF THE PROPERTY OF TH		Done
1.	Excavation	0%
2.	No Basement Only 1 Number of Plinth	0%
3.	0 Number of Podiums	NA
4.	Stilt Floor	0%
5.	20 (pt) Number of Slabs of Super Structure	0%




202, ODYSSEY IT PARK, ROAD NO.9, NEAR OLD PASSPORT OFFICE, WAGLE ESTATE, THANK (W) 400 604. • TEL: 65565570



e-mail:ss\_associates1@yahoo.co.in

).	Internal Walls, Internal Plaster, Flooring with Flat / Premises, Doors and Windows to each of the Flat / Premises	0%		
7.	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises			
3.	Staircases, Lifts Wells and Lobbies at Each Floor Level connecting staircases and lifts, Overhead and Underground Water Tanks	0%		
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	0%		
10.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance			
	Lobby, Plinth Protection, Paving of Areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate	s		





e-mail:ss\_associates1@yahoo.co.in

### TABLE A

# REHAB WING "B":

Sr. No	Tasks / Activity	
		Work
1.	Excavation	Done
2.	No Basement Only 1 Number of Plinth	0%
3.	0 Number of Podiums	0%
4.	Stilt Floor	NA 0%
5.	22 (pt) Number of Slabs of Super Structure	0%
6.	Internal Walls, Internal Plaster, Flooring with Flat / Premises, Doors and Windows to each of the Flat / Premises	0%
7.	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8.	Staircases, Lifts Wells and Lobbies at Each Floor Level connecting staircases and lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	O%
10.	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of Environment / CRZ NOC, Finishing to Entrance	O%,
	Lobby, Plinth Protection, Paving of Areas appurtenant to	





e-maif:ss\_associates1@yahoo.co.in

Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate

The percentage of work executed with respect to each of the major activity of the Building / Wing and Overall Percentage of work done with respect to each of the Building / Wing is detailed in Table B.

### TABLE B

Sr.	Common Areas and	Propose	Percentag	Details
No	Facilities, Amenities	d (Yes /	e of Work	
		No)	Done	
1.	Internal Roads &	Yes	0%	Internal Access Road
	Footpaths			and Driveway
2.	Water Supply	Yes	0%	MCGM
3.	Sewerage (Chamber	Yes	0%	MCGM
	Lines, Septic Tank, STP)			
4.	Storm Water Drains	Yes	0%	Developer
5.	Landscape & Tree	No .	0%	NA.
	Planting			
6.	Street Lighting	Yes	0%	Driveway Lighting
7.	Community Buildings	No	0%	NA
8.	Treatment and Disposal	No	0%	NΛ
	of sewage and sullage			
	water / /			





e-mail; ss\_associates1@yahou.co.in

9,	Solid Waste	No	0%	NA
	Management & Disposal	V 100 100 100 100 100 100 100 100 100 10		
10.	Water Conservation, Rain Water Harvesting	Yes	0%	Only Rain Water Harvesting by Developer
11.	Energy Management	No	0%	NA
12.	Fire Protection & Fire Safety Requirements	Yes	0%	Developer
13.	Electrical Meter Room, Sub-station, receiving	Yes	0%	Developer
14.	Others — Mechanical / Stack Parking System	Yes	0%	Developer
15.	Others – Society Office	Yes	0%	Developer
16.	Others - Fitness Center	Yes	0%	Developer

Yours Faithfully

Smit. Spectal Nikhare

of S. S. Associates

Architect

License No: CA / 2003 / 31138