

e-mail: ss_associates1@vahoo.co.in

FORM 1 ARCHITECT'S CERTIFICATE

Date: 27/05/2021

To

M/s. Ranbir Real Estate and Developers LLP. 8, Gokul Arcade, B-Building, Subhash Road, Near Gaware House, Ville Parle-East, Mumbai- 400 057.

Subject:- Certificate of Percentage of Construction Work of proposed building comprising of Composite Building No.A2 Rehab Wing-A, B & Sale Wing-A, B & C situated on the plot bearing C.T.S. No. 156 (pt.), 160/A/1 (pt.) & 162 (pt.) "SHRISTI RESIDENCY" demarcated by its boundaries of North- 18.30 m wide Proposed D.P. road., South- 13.40 m wide Existing Jijamata Road, East- 18.30 m wide Existing D.P. road., West- adjoining B.E.S.T. Bus Station. of village Majas, at sarvoday Nagar, Meghwadi, Jogeshwari (East), Taluka Andheri, District Mumbai, Admeasuring 8229.72 Sq. Mtrs. plot area being developed by M/s. Ranbir Real Estate and Developers LLP.

Sir,

We, S. S. Associates have undertaken assignment as Achitect of certifying Percentage of Construction Work of the proposed building comprising of Composite Building No.A2 Rehab Wing-A, B & Sale Wing-A, B & C situated on the plot bearing, 156 (pt.), 160/A/1 (pt.) & 162 (pt.) of village Majas, at sarvoday Nagar, Meghwadi, Jogeshwari (East), Taluka Andheri, District Mumbai, Admeasuring 8229.72 Sq. Mtrs. plot area being developed by M/s. Ranbir Real Estate and Developers LLP., having registered office at 8, Gokul Arcade, B-Building, Subhash Road, Near Gaware House, Ville Parle-East, Mumbai- 400 057.

Following technical professionals are appointed by Promoter:-

- M/s. S.S. Associates as Architect.
- (ii) M/s. Raje Structural Consultants as Structural Consultant
- (iii) M/s. Electo Mech Consultants as MEP consultant.
- (iv) M/s. ACE Project Management Consultant as Quantity Surveyor.

Based on Site Inspection, with respect to the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for the building of the Real Estate Project is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



e-mail: ss_associates1@yahoo.co.in

TABLE - A

(Rehab Wing-A)

Sr. No. (1)	Tasks / Activity (2)	Percentage of work done (3)	
1.	Excavation	100 %	
2.	Plinth	100 %	
3.	Podiums	N.A.	
4.	1 Stilt floor	0.00 %	
5.	21 number of Slabs of Super Structure	0.00 %	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.00 %	
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0.00 %	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00 %	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00 %	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0.00 %	





202, ODYSSEY IT PARK, ROAD NO. 9, NEAR OLD PASSPORT OFFICE, WAGLE ESTATE, THANE (W) - 400604

Landline: +91 8097565570


e-mail: ss_associates1@yahoo.co.in

TABLE - A

(Rehab Wing-B)

Sr. No. (1)	Tasks / Activity (2)	Percentage of work done (3)	
1.	Excavation	30 %	
2.	Plinth	0.00 %	
3.	Podiums	N.A.	
4.	1 Stilt floor	0.00 %	
5.	20 number of Slabs of Super Structure	0.00 %	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.00 %	
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0.00 %	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00 %	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00 %	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0.00 %	







e-mail: ss_associates1@yahoo.co.in

TABLE - A

(SALE Wing-A)

Sr. No. (1)	Tasks / Activity (2)	Percentage of work done (3)	
1.	Excavation	0.00 %	
2.	Plinth	0.00 %	
3.	Podiums	N.A.	
4.	1 Stilt floor	0.00 %	
5.	16 number of Slabs of Super Structure	0.00 %	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.00 %	
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0.00 %	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00 %	
9,	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00 %	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0.00 %	





202, ODYSSEY IT PARK, ROAD NO. 9, NEAR OLD PASSPORT OFFICE, WAGLE ESTATE, THANE (W) - 400604

Landline: +91 8097565570

e-mail: ss_associates1@yahoo.co.in

TABLE - A

(SALE Wing-B)

Sr. No. (1)	Tasks / Activity (2)	Percentage of work done (3)	
1.	Excavation	0.00 %	
2.	Plinth	0.00 %	
3.	Podiums	N.A.	
4,	1 Stilt floor	0.00 %	
5.	16 number of Slabs of Super Structure	0.00 %	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.00 %	
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0.00 %	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00 %	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00 %	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC,	0.00 %	
	Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation /		

Completion Certificate.





202, ODYSSEY IT PARK, ROAD NO. 9, NEAR OLD PASSPORT OFFICE, WAGLE ESTATE, THANE (W) - 400604 Landline: +91 8097565570

e-mail: ss_associates1@yahoo.co.in

TABLE - A

(SALE Wing-C)

Sr. No. (1)	Tasks / Activity (2)	Percentage of work done (3)	
1.	Excavation	0.00 %	
2.	Plinth	0.00 %	
3.	Podiums	N.A.	
4.	1 Stilt floor	0.00 %	
5.	16 number of Slabs of Super Structure	0.00 %	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.00 %	
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0.00 %	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00 %	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0.00 %	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0.00 %	





202, ODYSSEY IT PARK, ROAD NO. 9, NEAR OLD PASSPORT OFFICE, WAGLE ESTATE, THANE (W) - 400604

Landline: +91 8097565570

e-mail: ss_associates tillyahoo co.in-

TABLE - B

Internal and External Development Works in respect of the entire Registered Phase.

Sr.No	Common areas and Facilities Amenities	Proposed (Yes/No) (3)	Percentage of work done (4)	Details (5)
1.	Internal Roads & Footh- paths.	Yes	0%	Developer
2.	Water Supply	Yes	0%	MCGM
3.	Sewerage(Chamber, lines, Septic Tank, STP)	Yes	0%	MCGM
4.	Storm Water Drains	Yes	0%	Developer
5.	Landscaping & Tree Planting.	Yes	0%	Developer
6.	Street Lighting	No	N.A	N.A
7.	Community Buildings	No	N.A	N.A
8.	Treatment and disposal of sewage and sullage water.	Yes	0%	Developer
9.	Solid Waste management & Disposal	Yes	0%	Developer
10.	Water conservation Rain water harvesting	Yes	0%	Developer
11.	Energy management	No	N.A	N.A
12.	Fire protection and fire safety requirements	Yes	0%	Developer
13	Electrical meter room, sub- station, receiving station.	Yes	0%	Developer
14	Pump Room	Yes	0%	Developer

FOR S. S. ASSOCIATES (CA/2003/31138)

Yours faithfully S. S.