

#### FORM 1 ARCHITECT'S CERTIFICATE

Date:-15/02/2018

To, M/S. AKSHAR GROUP, Gut No. 100/1, 101, 104 & 110/2B Village Chavane, Tal Panvel, Dist Raigad.

SUBJECT: Certificate of Percentage of Completion of Construction Work of (PLOT F) 4
BUILDINGS of the project AKSHAR RIVERGATE [ P52000014488 ] situated on the
GUT NO.-100/1,101,104 &110/2B, Demarcated by its boundaries PATALGANGA
RIVER,GUT NO. 11/1 to the North, GUT NO. 102 to the South, GUT NO. 108 to the East,
PLOT-E to the West; of Division - KONKAN, Village - CHAVANE, Taluka - PANVEL, DistrictRAIGAD & PIN NO. 410206 admeasuring 6848.000 SQ.MT. area being developed by M/S.
AKSHAR GROUP.

Sir.

- I, Dharmesh Bhalani, partner of M/s. Destination Architecture Interior Designs, have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of (PLOT F) 4 BUILDINGS of the project AKSHAR RIVERGATE situated on the GUT NO.-100/1,101,104 & 110/2B; of Division KONKAN, Village CHAVANE, Taluka PANVEL, District- RAIGAD & PIN NO. 410206 admeasuring 6848.000 SQ.MT. area being developed by M/S. AKSHAR GROUP.
- 1. Following technical professionals are appointed by Owners / Promoters:-
- (i) M/s. DESTINATION ARCHITECTURE INTERIOR DESIGNS as Architect;
- (ii) Shri. SUKHTANKAR as Structural Consultant
- (iii) Shri. <u>UMESH THAMKE</u> as MEP Consultant
- (iv) Shri KANTI RAVERIYA as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number

[ P52000014488 ] under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



### 1) BUILDING NO 1 - WING F1

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	100%	
2	0 Basement and 1 Plinth	100%	
3 -	Podiums	N.A 100% 60%	
4	Stilt Floor		
5	8 Slabs of Super Structure (5 slab constructed out of 8)		
6	Internal walls	0%	
	Internal Plaster	0%	
	Floorings within Flats/Premises	0%	
	Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
	Electrical Fittings within the Flat/Premises	0%	
8	Staircases (R.C.C. Work)	60%	
	Lifts Wells (R.C.C. Work)	60%	
	Lobbies (R.C.C. Work)	60%	
	Overhead Water Tanks	0%	
	Underground Water Tanks.	0%	
9	External plumbing	0%	
	External plaster	0%	
	Elevation	0%	
	Completion of terraces with waterproofing	0%	
10	Installation of lifts	0%	
	Installation of water pumps	0%	
	Fire Fighting Fittings and Equipment as per CFO NOC	N.A.	
	Electrical fittings to Common Areas	0%	
	Electro mechanical equipment	0%	
	Compliance to conditions of environment /CRZ NOC	N.A.	
	Finishing to entrance lobby/s	0%	
	Plinth protection	0%	
	Paving of areas appurtenant to Building/Wing	0%	
	Compound Wall	0%	
	All other requirements as may be required to Obtain Occupation /Completion Certificate	0%	





#### 2) BUILDING NO 2-WING F2

Sr. No	Tasks /Activity	Percentage of work done 100%	
1	Excavation		
2	0 Basement and 1 Plinth	100%	
3	Podiums	N.A	
4	Stilt Floor	100%	
5	8 Slabs of Super Structure (2 slab constructed out of 8)	25%	
6	Internal walls	0%	
	Internal Plaster	0%	
	Floorings within Flats/Premises	0%	
	Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
	Electrical Fittings within the Flat/Premises	0%	
8	Staircases (R.C.C. Work)	25%	
	Lifts Wells (R.C.C. Work)	25%	
	Lobbies (R.C.C. Work)	25%	
	Overhead Water Tanks	0%	
	Underground Water Tanks	0%	
9	External plumbing	0%	
	External plaster	0%	
	Elevation	0%	
	Completion of terraces with waterproofing	0%	
10	Installation of lifts	0%	
	Installation of water pumps	0%	
	Fire Fighting Fittings and Equipment as per CFO NOC	N.A.	
	Electrical fittings to Common Areas	0%	
MES	Electro mechanical equipment	0%	
	Compliance to conditions of environment /CRZ NOC	N.A.	
	Finishing to entrance lobby/s	0%	
	Plinth protection	0%	
	Paving of areas appurtenant to Building/Wing	0%	
	Compound Wall	0%	
	All other requirements as may be required to Obtain Occupation /Completion Certificate	0%	

Ar. DHARMESH V. BHALANI CA/2007/41110

Howsey.





#### 3) BUILDING NO 3 - WING F3

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	100%	
2	0 Basement and 1 Plinth	100%	
3	Podiums	N.A	
4	Stilt Floor	100%	
5	8 Slabs of Super Structure (8 slab constructed out of 8)	100%	
6	Internal walls	0%	
	Internal Plaster	0%	
	Floorings within Flats/Premises	0%	
	Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
	Electrical Fittings within the Flat/Premises	0%	
8	Staircases (R.C.C. Work)	100%	
	Lifts Wells (R.C.C. Work)	100%	
	Lobbies (R.C.C. Work)	100%	
	Overhead Water Tanks	0%	
1	Underground Water Tanks	0%	
9	External plumbing	0%	
	External plaster	0%	
	Elevation	0%	
	Completion of terraces with waterproofing	0%	
10	Installation of lifts	0%	
	Installation of water pumps	0%	
	Fire Fighting Fittings and Equipment as per CFO NOC	N.A.	
	Electrical fittings to Common Areas	0%	
	Electro mechanical equipment	0%	
	Compliance to conditions of environment /CRZ NOC	N.A.	
	Finishing to entrance lobby/s	0%	
	Plinth protection	0%	
	Paving of areas appurtenant to Building/Wing	0%	
	Compound Wall	0%	
	All other requirements as may be required to Obtain Occupation /Completion Certificate	0%	





#### 4) BUILDING NO 4 - WING F4

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	100%	
2	0 Basement and 1 Plinth	100%	
3	Podiums	N.A	
4	Stilt Floor	100%	
5	8 Slabs of Super Structure (7 slab constructed out of 8)	90%	
6	Internal walls	0%	
	Internal Plaster	0%	
	Floorings within Flats/Premises	0%	
	Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
	Electrical Fittings within the Flat/Premises	0%	
8	Staircases (R.C.C. Work)	90%	
	Lifts Wells (R.C.C. Work)	90%	
	Lobbies (R.C.C. Work)	90%	
	Overhead Water Tanks	0%	
	Underground Water Tanks	0%	
9	External plumbing	0%	
	External plaster	0%	
	Elevation	0%	
	Completion of terraces with waterproofing	0%	
10	Installation of lifts	0%	
	Installation of water pumps	0%	
	Fire Fighting Fittings and Equipment as per CFO NOC	N.A.	
	Electrical fittings to Common Areas	0%	
	Electro mechanical equipment	0%	
	Compliance to conditions of environment /CRZ NOC	N.A.	
	Finishing to entrance lobby/s	0%	
	Plinth protection	0%	
	Paving of areas appurtenant to Building/Wing	0%	
	Compound Wall	0%	
	All other requirements as may be required to Obtain Occupation /Completion Certificate	0%	





# TABLE-B PROJECT -AKSHAR RIVERGATE Internal & External Development Works in Respect of the entire project

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	% of Work done	Details
1	Internal Roads &Foothpaths	Yes	0%	Not commenced. Will be provided as per DCPR FOR REGIONAL AREA.
2	Water Supply	Yes	0%	Not commenced. Will be provided as per DCPR FOR REGIONAL AREA.
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	0%	Not commenced, Will be provided as per DCPR FOR REGIONAL AREA.
4	Storm Water Drains	Yes	0%	Not commenced. Will be provided as per DCPR FOR REGIONAL AREA.
5	Landscaping & Tree Planting	Yes	0%	Not commenced. Will be provided as per DCPR FOR REGIONAL AREA.
6	Street Lighting	Yes	0%	Not commenced. Will be provided as per DCPR FOR REGIONAL AREA.
7	Community Buildings	No	a carefalter	N.A.
8	Treatment and disposal of sewage and sullage water	No		N.A.
9	Solid Waste management & Disposal	No		N.A.
10	Water conservation, Rain water harvesting	Yes		N.A.
11	Energy management	No	A SOUTH IN	N.A.
12	Fire protection and fire safety requirements	Yes		N.A.
13	Electrical meter room, sub- station, receiving station	Yes	0%	Not commenced, Meter room will be provided as per DCPR FOR REGIONAL AREA.

Yours Faithfully,

DESTINATION

FOR.

Architecture interior designs

Ar. DharmeshBhalani

(License no. CA/2007/41110)

