

Date: 11/04/2023

The Director,

## M/s-Sai Ventures through Mr. Vinod K. Matani.

<u>Subject:</u> Certificate of percentage of completion of construction work of 'B, C & D' Building" of the project [P52100049314] situated on the plot bearing Survey No.-21/11 (P), Demarcated by its boundaries (Latitude 18°37'09.1"N and Longitude 73°44'10.8"E of the end points) to the North 12.00m wide D.P.Road, to the South S.No.21(P), to the East S.No.- 21(P), to the West S.No-21(P), Village-Punavale, Taluka -Haveli, District-Pune, Pin- 411033 admeasuring 3391.14Sqm. area being developed by M/s-Sai Venture through Mr. Vinod K. Matani

Sir.

I have undertaken assignment as Architect/Licensed surveyor of certifying percentage of completion of construction work of 'B, C & D' Building" of the project, situated on the plot bearing Survey No.-21/13 (P), Village-Punavale, Taluka -Haveli, District-Pune, Pin- 411033. admeasuring area 3391.14 Sqm. being developed by M/s-Sai Venture through Mr. Vinod K. Matani.

- 1. Following technical professionals are appointed by Owner/Promoter:-
- (i) Ar. Vilas Yele as Architect.
- (ii) Spectrum Consultant as Structural Consultant.
- (iii) Mr.Guddu Pandey as Site Engg.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building / wing of the Real Estate Project as Registered vide Number [P52100049314] as per table A Herein below. The percentage of the work executed with respect to each of the major activity of the Building/Wing and overall percentage of work done with respect to each Building/Wing is detailed in the Table B

Cell: +91 9130058295

Email: vilasyele1986@gmail.com

## Table -A

Sr. No.	Particular	Percentage of work done			
NO.		Building-B	Building-C	Building-D	
1	Excavation	100%	100%	100%	
2	Number of Basement(s) and Plinth	100%	100%	100%	
3	Number of podiums	NA	NA	NA	
4	0 number of Stilt Floor	NA	NA	NA	
5	10 Number of % slabs of super structure	70%	70%	70%	
6	Internal Walls, Internal Plaster, 10% Flooring within Flats/Premises, Doors and windows to each of the flat/Premises	0%	0%	0%	
7	Sanitary Fittings within the flat premises, Electrical Fittings within the Flat/Premises.	0%	0%	0%	
8	Staircases, Lifts wells and Lobbies at each Floor level, Connecting Staircases &Lifts, overhead& Underground water Tanks	0%	0%	0%	
9	The external plumbing and external plaster, elevation, completion of Terraces with water proofing of the building/Wing	0%	0%	0%	
10	Installation of lifts, water pumps, Fire Fighting fittings & Equipment as per CFO NOC, Electrical Fittings to Common Areas, Electro, Mechanical equipment, Compliance to conditions of environment/CRZ NOC, finishing to entrance lobby/s, Plinth protection, paving Of areas Appurtenant to Building/Wing, Compound wall and all other requirements As may be required to obtain occupation/completion certificate.	0%	0%	0%	

Cell: +91 8308679535

Email: vilasyele1986@gmail.com

<u>TABLE-B</u>
Internal & External Development works in Respect of the entire registered phase

Sr. No.	Particular	Proposed	Percentage of Completion	Detail
1	Internal Roads & footpaths	YES	0	NA
2	water supply	YES	0	BOREWELL, PCMC WATER SUPPLY
3	Sewerage (Chamber , lines, septic tank, STP)	YES	0	AS PER REAMRK  MENTIONED IN  DRAINAGE NOC
4	Storm water Drains	YES	0	CHAMBER , LINES
5	Landscaping & Tree Planting	YES	0	AS PER REAMRK  MENTIONED IN GARDEN  NOC
6	Street Lighting	YES	0	LED LIGHTS
7	Electrical Meter room, Substation, Receiving Station	YES	0	AS PER PCMC RULES
8	Aggregate area of recreation open space	NO	N.A	N.A
10	Community Buildings	NO	N.A	NA
11	Treatment and disposal of	YES	0	AS PER REAMRK

Add: Shop No-113, Rose Icon, Pimple Saudagar, Pune-411027

Cell: +91 8308679535

Email: vilasyele1986@gmail.com

	sewage and sullage water			MENTIONED IN
				DRAINAGE NOC
40	0.111	No	NI A	N. A
12	Solid waste management &	NO	N.A	N.A
	Disposal			
13	Water Conservation, Rain water	YES	0	AS PER PCMC RULES
	harvesting			
14	Energy management	YES	0	SOLAR WATER HEATER
				SYSTEM
15	Fire Protection and fire safety	YES	0	AS PER REAMRK
	requirements			MENTIONED IN FIRE
				NOC

## Overall percentage of the work completed

Sr. No.	Particular	Percentage of work done
1.	Overall percentage of construction/development completed as per Table-A and Table-B.	15%

Cell: +91 8308679535

Email: vilasyele1986@gmail.com

Yours Faithfully

Ar. Vilas Yele CA/2011/51410

AR. VILAS J. YELE
Lic. No.: CA/2011/51410
ARCHITECTS, INTERIOR
& LANDSCAPE DESIGNER

Add: Shop No-113, Rose Icon, Pimple Saudagar, Pune-411027