

To,

M/s. Global Housing Ventures Banglow No 3, Bharat Nagar Gymkhana Road Dombivali East

Subject: Certificate of Percentage of Completion of Construction Work of "NEW SHIVNERI DARSHAN CO.OP H.SO.Ltd.Maha RERA Registration Number [______] situated on the Plot bearing S No.: 96/2(P) At Village- Kalyan, Tal- Kalyan, Dist-Thane. demarcated by its boundaries towards

North - Remaining part of S.no 96 H.no 2

South - S.no 107

East - 18M .W D.P Road

West - S.no 96 H.no 1/2

admeasuring area 836.43 sq.mtr. area being developed by M/s. Global Housing ventures

Sir.

I Mr Dilip Madhukar Dalvi (**Architect**) has undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the "NEW SHIVNERI DARSHAN CO.OP H.SO.LTD" situated on the Plot bearing S.No.: 96/2(p) At Village- Kalyan, Tal- Kalyan, Dist-Thane. Plot admeasuring area 836.43 sq.mtr area being developed by M/s. Global Housing ventures

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Mr Dilip Madhukar Dalvi of D.M Dalvi & Associates as Architect;
- (ii) Mr. A. R. KHASNIS as Structural Consultant




- (iii) MEP Consultant (Not yet appointed)
- (iv) Site Supervisor (Not yet appointed)

Based on Site Inspection, with respect to the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of work done for the Building of the Real Estate Project as registered vide number _____ under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Sr.	Task/Activity	Percentage of
No.		work done
1	Excavation	0%
2	Number of Plinth	0 %
3	Number of Podiums	-
4	Stilt Floor	0%
5	Number of Slabs of Super Structure (Slabs)	0%
6	Internal Walls	0%
	Internal Plaster	
	Floorings within flats/premises	
	Doors and windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises, Electrical	0%
	Fittings within the Flat/Premises	•
8	Staircases, Lifts Well and lobbies at each Floor level	0%
	connecting Staircases, Lifts work	
	Overhead work & Underground Water Tanks work	
9	The External plumbing work	0%
	External plaster and elevation work	



completion of Terraces with waterproofing of the	
Building/Wing	
Installation of lifts, water pumps, fire fighting fittings and	0%
equipment as per CFO NOC, Electrical fittings to Common	
Areas, electro mechanical Equipment, Compliance to	
conditions of environment/CRZ NOC, Finishing to	
entrance lobby/s, plinth protection, paving of areas	
appurtenant to building/wing, compound wall and all	
other requirements as may be required to Obtain	
Occupation/ Completion Certificate.	
	Building/Wing Installation of lifts, water pumps, fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro mechanical Equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to Obtain

<u>Table B</u>

<u>Internal & External Development Works</u>

Sr.	Common Areas and	Proposed	Percentage	Details			
No.	Facilities, Amenities	(Yes/No)	of work				
			done	·			
1	Internal Roads & Footpaths	Yes	0%	Work yet not started			
2	Water Supply	Yes	0%	Work yet not started			
3	Sewerage (chamber, Lines, Septic	Yes	0%	Work yet not started			
	Tank, STP)						
4	Storm Water Drains	Yes	0%	Work yet not started			
5	Landscaping & Tree Planting	Yes	0%	Work yet not started			
6	Street Lighting	Yes	0%	Work yet not started			
7	Community Buildings	No	0 %	•			
8	Treatment and disposal of swage	Yes	0%	Work yet not started			
·	and Sullage Water			•			
9	Solid Waste Management and Disposal	Yes	0%	Work yet not started			



10	Water Conservation, Rain Water	Yes	0%	Work yet not started
	harvesting			
11	Energy management	Yes	0%	Work yet not started
12	Fire Protection and Fire safety	Yes	0%	Work yet not started
	requirements			
13	Electrical Meter Room, Sub	Yes	0%	Work yet not started
	Station, Receiving station			
14	Aggregate Area of Recreational	Yes	0%	Work yet not started
	Open Space			
15	Open Parking	Yes	0%	Work yet not started
16	Specify if any further facility is			
	Provided (other than above			
	mentioned)			

Yours Faithfully,

For D.M.Dalvi & Associates

(D.M Dalvi)

License No. CA- 76/2398