

101, WEST VIEW, A - 2, SECTOR - II. SHANTI NAGAR. MIRA ROAD (E), DIST. THANE - 401 107. TEL: 2811 1447 Email: mhatreavinash@yahoo.com

## FORM 1 ARCHITECT CERTIFICATE

Date: 31.12.2019

To,
M/S. UNIQUE SHANTI DEVELOPERS LLP
Harsh Plaza, 1<sup>st</sup> Floor, Opp. Sector - 2,
100ft. Road, Mira Road (East),
Dist. Thane – 401 107.

Subject: Certificate of Percentage of Completion of Construction Work of Two No. of Building i.e. Building Type A (Wing A) and Building Type B (Wing B), of the Project known as "UNIQUE IVANA" situated on the Land bearing Survey No.111Hissa No. 8pt. & 9, Survey No. 121Hissa No. 3 ofVillageGhodbunderdemarcated by its boundaries (latitude and longitude of the end points)videLayoutPlanto the North P.S. & P.G. RES. NO. 324,to the SouthS. No. 121, to the East S. No. 120,to the West S. No. 111, Village Ghodbunder, Taluka &District Thane, PIN 401 107, area admeasuring5336.00 sq.mt being developed by M/S. UNIQUE SHANTI DEVELOPERS LLP.

I Mr. AvinashMhatrehave undertaken assignment as Architect ofcertifying Percentage of Completion of Construction WorkTwo number of Buildingi.e. Building Type A (Wing A) and Building Type B (Wing B), of the Project known as "UNIQUE IVANA" situated on the Land bearing Survey No. 111 Hissa No. 8pt. & 9, Survey No. 121 Hissa No. 3 of Village Ghodbunder, Taluka&District Thane, PIN 401107, admeasuring5336.00sq.mtrs.area being developed by M/S. UNIQUE SHANTI DEVELOPERS LLP.

Following technical professionals are appointed by Owner / Promoter: -

- (i) Shri. AvinashMhatre as Architect
- (ii) M/s. Pro-Tech Consultants as Structural Consultant
- (iii) Shri. Ashim Boseas Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number under Maha RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



101, WEST VIEW, A - 2, SECTOR - II, SHANTI NAGAR, MIRA ROAD (E), DIST. THANE - 401 107. TEL: 2811 1447 Email: mhatreavinash@yahoo.com

## TABLE - A BUILDING TYPE - A, (WING - A)

Sr. No.	Tasks / Activity	Percentageof done	work
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	0%	
3	0 number of Podium	Not Applica	ble
4	Stilt Floor	0%	
5	17 numbers of Slabs of Super Structure	0 %	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire lighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	

## TABLE - A BUILDING TYPE - B, (WING - B)

Sr. No.	Tasks / Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	0%	
3	0 number of Podium	Not Applicable	
4	Stilt Floor	0%	
5	17 numbers of Slabs of Super Structure	0 %	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire lighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other	0%	
	requirements as may be required to Obtain Occupation /Completion Certificate		



101, WEST VIEW, A - 2, SECTOR - II, SHANTI NAGAR. MIRA ROAD (E), DIST. THANE - 401 107. TEL : 2811 1447 Email : mhatreavinash@yahoo.com

TABLE - B

## Internal/External Development Works in Respect of the entire Registered Phase

S. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details	
1.	Internal Roads & Footpaths	No	0%	Already existing	
2.	Water Supply	Yes	0%	To be provided by MBMC.	
3.	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0%	To be completed before Occupation Certificate	
4.	Storm Water Drains	Yes	0%	To be completed before Occupation Certificate	
5.	Landscaping & Tree Planting	Yes	0%	To be completed before Occupation Certificate	
6.	Street Lighting	Yes	-	Already Existing	
7.	Community Building	No	0%	Not Applicable	
8.	Treatment and disposal of sewage and sullage water	Yes	0%	To be connected to MBMC STP	
9.	Solid Waste Management And Disposal	Yes	0%	To be connected to MBMC STP	
10.	Water Conservation, Rain water Harvesting	Yes	0%	To be completed before Occupation Certificate	
11.	Energy Management	Yes	0%	To be completed before Occupation Certificate	
12.	Fire protection and fire safety requirements	Yes	0%	To be completed before Occupation Certificate	
13.	Electrical meter room, sub-station, receiving station	Yes	0%	To be completed before Occupation Certificate	
14.	Others (Option to Add more)	No	-	-	

Yours faithfully

**AVINASH MHATRE** 

Architect

License No. CA/75/1274