R. P. ASUNDARIA A R C H I T E C T

Date: 17-09-2019

236, 2nd Floor, AVIOR, Nirmal Galaxy, Near Deep Mandir Cinema, L.B.S. Marg, Mulund (West), Mumbai - 400 080. Tel. : 2567 9979

FORM-1

ARCHITECT'S CERTIFICATE

To
Balaji Associate
C. A. to Owner Yashaswini CHS Ltd.
1501\1502 Excel plaza, 90 Feet Road,
Pant Nagar, Near Durga Parmeshwari Mandir,
Ghatkopar (East) Mumbai -400077.

Sub: Certificate of Cost Incurred for Development of Yashaswini Co-op Hsg soc. Ltd Redevelopment Project for Construction of 1 building, situated on the Plot bearing C.T.S. No. 569-A of Village Chembur, Mumbai – 400 079, demarcated by its boundaries (19.068038° N latitude and 72.901482° E longitude in the center of the Plot) Existing Pestam Sagar road No. 2 to the North, 9.15 Mtr. Wide road to the East, CTS No. 569-B to the South, C.T.S. No. 572 to the West of village Chembur, Taluka Kurla, Mumbai Suburban District, Mumbai – 400 079 admeasuring 533.90 sq. mtrs area being developed by Balaji Associate C. A. to Owner

Sir,

- I, Ramji P. Asundria have undertaken assignment of certifying Estimated Cost for the Yashaswini Co-op Hsg soc. Ltd Redevelopment Project for Construction of 1 building, situated on the Plot bearing C.T.S. No. 569-A of village Chembur, Taluka Kurla, Mumbai Suburban District, Mumbai 400 079 admeasuring 533.90 sq. mtrs area being developed by Balaji Associate C. A. to Owner
- 1. Following technical professionals are appointed by Promoter:-
 - (i) R. P. Asundria as Architect
 - (ii) M/s. Paras Consultants as Structural Consultant
 - (iii) Shri Raju K. Nareja Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number P51900007376 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

R. P. ASUNDARIA A R C H I T E C T

236, 2nd Floor, AVIOR, Nirmal Galaxy, Near Deep Mandir Cinema, L.B.S. Marg, Mulund (West), Mumbai - 400 080. Tel. : 2567 9979

Table A Yashaswini Co-Op Hsg. Soc Ltd.

Sr. No.	No. of Task/Activity	Percentage of work done	
1	Excavation	100%	
2	1 Number of Plinth	100%	
3	0 number of Podiums	0%	
4	1 Stilt Floor	100%	
5	13 number of Slabs of Super Structure	53%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate.	0%	
11.	Overall Percentage of Completion of the Work Done for the Entire Building	25%	

236, 2nd Floor, AVIOR, Nirmal Galaxy, Near Deep Mandir Cinema, L.B.S. Marg, Mulund (West), Mumbai - 400 080. Tel.: 2567 9979

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

S.No.	Common Areas and facilities, amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Foot paths	N.A.	N.A.	-
2	Water Supply	Yes	0	Work yet to start.
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0	Work yet to start.
4	Storm Water Drains	Yes	0	Work yet to start.
5	Landscaping & Tree Planting	Yes	0	Work yet to start.
6	Street Lighting	N.A.	N.A.	•
7	Community Buildings	N.A.	N.A.	•
8	Treatment and disposal of sewage and sullage water	N.A.	N.A.	-
9	Solid Waste management & Disposal	N.A.	N.A.	
10	Water conservation, Rain water harvesting	Yes	0	Work yet to start.
11	Energy management	No.	N.A.	•
12	Fire protection and fire safety requirements	Yes.	0	Work yet to start.
13	Electrical meter room, sub- station, receiving station	Yes	0	Work yet to start.
14	Others (Option to Add more) Bore well & Temporary Electrical Connection for Lift	Yes	0	Work yet to start

Yours faithfully

Signature & Name of Architect

R. P. Asundaria

(License No-CA/98/23287