

ANIRUDDHA VAIDYA & ASSOCIATES And S 0.4900 17. \$200.8 Centilitied to regard sation a ARCHITECTS, TOWN PLANNERS & INTERIOR DESIGNERS

4. Dalfaprasad, 1206, B/7. Off. J. M. Road, Shivajinagar, Pline 411004 Tel. / Fax : 2553 0420, 2553 0430 Email : archvaidya@gmail.com Web : www.archvaidya.com

FORM1 [seeRegulation3]

ARCHITECT'SCERTIFICATE

(To be submitted at the time of Registration of Ongoing Projectand for withdrawal of Money from Designated Account)

Date:07.06.2017

To M/S. MATRIX DEVELOPERS PVT LTD. Pune.

Subject:Certificate of Percentage of Completion of Construction Work of 3Wing(s) of the Forest TrailsAthashri -B2(Sector R26-B2A, B2B, B2C) of the Project [MahaRERARegistration Number] situated on the Sector No.R-26, Survey No 16/1 and others demarcated by its boundaries Latitude 18°30'41"N, Longitude 73°44'02.76"E, By G4, G4 A, OS 13 to the East, By part of G 61 and beyond that 12.0 mtown ship road to the West, by G 61 to the North, G 61 and portion of 12.0 m township road to the South of Division-Pune, Village – Mouje Bhugaon, Taluka – Mulshi, District – Pune 411042 admeasuring 9913.274 sq. mts. Areabeing developed by M/S. MATRIX DEVELOPERS PVT LTD

Sir.

IRadhika A.Vaidya haveundertakenassignmentasArchitect/LicensedSurveyorof certifying Percentage of Completion of Construction Work of 3 Wing(s) of theForest Trails Athashri –B2 (Sector R26-B2A, B2B, B2C) of the Project [MahaRERARegistration Number] situated on the Sector No.R-26, Survey No 16/1 and others demarcated by its boundaries Latitude18° 30'41"NLongitude73°44'02.76"E, By G4,G4 A,OS 13 to the East, By part of G 61 and beyond that 12.0 mtown ship road to the West, by G 61 to the North, G 61 and portion of 12.0 m township road to the Southof Division - Pune Village -MoujeBhugaon, Taluka - Mulshi, District-Pune 411042 admeasuring 9913.274 sq.mts. Areabeing developed by M/S. MATRIX DEVELOPERS PVT LTD

- 1. Followingtechnical professionals are appointed by Owner/ Promoter:-
 - (i) Ar. Radhika A. Vaidya as L.S. / Architect;
 - (ii) JW consultants LLP asStructuralConsultant
 - (iii) Aquamate consultants PVt.Ltd_asMEPConsultant
 - (iv) Shashank Saraf asSiteSupervisor.

 $Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid\ Real Estate Project\ , lcertify\ that as on\ the date of this certificate\ , the Percentage of$

Workdoneforeachofthebuilding/WingoftheRealEstateProjectasregisteredvide number under MahaRERAis as per table A herein below. The percentageoftheworkexecutedwithrespecttoeachoftheactivityoftheentirephase is detailed in Table B.

Table A

Forest TrailsAthashri - B2 (Sector R26-B2A)

(tobepreparedseparately foreachBuilding/Wingof theProject)

Sr.N o	Tasks /Activity Excavation	Perce ntage Ofwo rk done 90%
2	Plinth	0%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls;Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases,Lifts Wells andLobbies ateach Floorlevel connectingStaircases andLifts, OverheadandUndergroundWater Tanks	0%
9	The external plumbingandexternal plaster, elevation, completion of terraces withwater proofing of the Building/Wing	0%

10 Installationof

0%

lifts,waterpumps,FireFightingFittingAndEquipmentasperCFONOC,Elec tricalfittingsto Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall and all other requirements as may be required to ObtainOccupation / Completion Certificate

Table A

Forest TrailsAthashri - B2 (Sector R26-B2B)

(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	90%
	·	•
2	Plinth	0%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls,Internal Plaster, Floorings within Flats/Premises, Doors andWindows toeachofthe Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%

10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions ofenvironment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall andallotherrequirementsasmaybe requiredto	0%
	ObtainOccupation /Completion Certificate	

Table A

Forest TrailsAthashri - B2(Sector R26-B2C)
(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks / Activity	Percentage Of work done
1	Excavation	90%
2	Plinth	0%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls,Internal Plaster, Floorings within Flats/Premises, Doors andWindows toeachofthe Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%
		11

10

Installation of lifts, water pumps, Fire Fighting
Fitting And Equipment as per CFO NOC, Electrical
fittings to Common Areas, electro, mechanical
equipment, Compliance to conditions
ofenvironment/CRZ NOC, Finishing to entrance
lobby/s, plinth protection, paving of areas
appurtenant to Building/Wing, CompoundWall
andallotherrequirementsasmaybe requiredto
ObtainOccupation/Completion Certificate

0%

$\underline{Internal\&ExternalDevelopmentWorksinRespect of the entire Registered Phas}$

e

S.No	CommonareasandFacilities, Amenities	Proposed (Yes/No)	Percentageof Workdone	Details
1.	InternalRoads&Foothpaths	Yes	0%	
2.	WaterSupply	Yes	90%	
3.	Sewerage(chamber,lines, SepticTank,STP)	Yes	0%	
4.	StormWaterDrains	Yes	0%	
5.	Landscaping&TreePlanting	Yes	0%	
6.	StreetLighting	Yes .	60%	
7.	CommunityBuildings	Yes	80%	
8.	Treatmentanddisposalof sewageand sullagewater	Yes	0%	
9.	SolidWaste management& Disposal	Yes	0%	
10.	Water conservation, Rain water harvesting	Yes	0%	
11.	Energy management	No	0%	
12.	Fireprotectionandfiresafety requirements	Yes	0%	
13.	Electricalmeterroom,sub- station, receivingstation	Yeş	0%	
14	Others(Optionto Addmore)		<u> </u>	

YoursFaithfully _-

For Aniruddha Vaidya & Associates

AR.RADHIKA VAIDYA

L.S/ Architect

License No CA/85/8968