

ANIRUDDHA VAIDYA & ASSOCIATES

An ISO 9001: 2008 Certified Organisation

ARCHITECTS. TOWN PLANNERS & INTERIOR DESIGNERS

4, Dattaprasad, 1206, B/7, Off. J. M. Road, Shivajinagar. Pune 411004 Tel. / Fax : 2553 0420. 2553 0430 Email : archvaidya@gmail.com Web : www.archvaidya.com FORM1 [seeRegulation3]

ARCHITECT'SCERTIFICATE

(To be submitted atthe time of Registration of Ongoing Projectandfor withdrawal of Money from Designated Account)

Date:26.03.2018

To M/S. MATRIX DEVELOPERS PVT LTD. Pune.

Subject: Certificate of Percentage of Completion of Construction Work of 3Wing(s) of the Forest Trails Athashri -B2 (Sector R26-B2A, B2B, B2C) of the Project [Maha RERA Registration Number P52100000029] situated on the Sector No.R-26, Survey No 16/1 and others demarcated by its boundaries Latitude 18°30'41"N, Longitude 73°44'02.76"E, By G4, G4 A, OS 13 to the East, By part of G 61 and beyond that 12.0 mtown ship road to the West, by G 61 to the North, G 61 and portion of 12.0 m township road to the South of Division-Pune, Village-Mouje Bhugaon, Taluka-Mulshi, District-Pune 412115 admeasuring 9913.274 sq.mts. Areabeing developed by M/S. MATRIX DEVELOPERS PVT LTD

Sir,

I Radhika A. Vaidya have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion of ConstructionWork of 3 Wing(s) of the Forest Trails Athashri – B2(Sector R26-B2A, B2B, B2C) of the Project [Maha RERA Registration NumberP52100000029] situated on the Sector No.R-26, Survey No 16/1 and others demarcated by its boundaries Latitude18⁰ 30'41"NLongitude73⁰44'02.76"E, By G4,G4 A,OS 13 to the East, By part of G 61 andbeyond that 12.0 mtown ship road to the West, by G 61 to the North, G 61 and portion of 12.0 m township road to the Southof Division - Pune Village -MoujeBhugaon, Taluka - Mulshi, District-Pune 412115admeasuring 9913.274sq.mts.Areabeing developedby M/S. MATRIX DEVELOPERS PVT LTD

- 1. Following technical professionals are appointed by Owner/ Promoter:-
 - (i) Ar. Radhika A. Vaidya as L.S. / Architect;
 - (ii) JW consultants LLP as Structural Consultant
 - (iii) Aquamate consultants PVt. Ltd_as MEP Consultant
 - (iv) Shashank Saraf as Site Supervisor.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number under Maha RERA is as

per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Forest TrailsAthashri - B2(Sector R26-B2A)

(To be prepared separately for each Building/Wing of the Project)

Sr. No		Percentage Of work
1	Excavation	done 100%
2	Plinth	75%
3	Number of Podiums	0%
4 .	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the Building/Win	0% ig
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanica equipment, Compliance to conditions of of areas appurtenated entrance lobby/s, plinth protection, paving of areas appurtenated Building/Wing, CompoundWall and all other requirements as may be required to Obtain Occupation / Completion Certificate] g

Table A

Forest TrailsAthashri - B2(Sector R26-B2B)
(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	100%
2	Plinth	45%
3	Number of Podiums	0%
4.	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls,Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the Building/Wing	0%
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	0%

Table A

Forest TrailsAthashri - B2(Sector R26-B2C) (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	100%
2	Plinth	70%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors andWindows toeachofthe Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of of order of conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall and allother requirements as may be required to Obtain Occupation / Completion Certificate	0%

Internal & External Development Works in Respect of the entire Registered Phase

S.No	CommonareasandFacilities, Amenities	Proposed (Yes/No)	Percentageof Workdone	Details
1.	InternalRoads&Foothpaths	Yes	0%	
2.	WaterSupply	Yes	90%	
3.	Sewerage(chamber,lines, SepticTank,STP)	Yes	0%	
4.	StormWaterDrains	Yes	0%	THE RESIDENCE OF
5.	Landscaping&TreePlanting	Yes	0%	
6.	StreetLighting	Yes	60%	
7.	CommunityBuildings	NO	-	NA
8.	Treatmentanddisposalof sewageand sullagewater	Yes	0%	PROPERTY OF STREET
9.	SolidWaste management& Disposal	Yes	0%	
10.	Water conservation, Rain water harvesting	Yes	0%	
11.	Energy management	NO		NA
12.	Fireprotectionandfiresafety requirements	Yes	0%	
13.	Electricalmeterroom,sub- station, receivingstation	Yes	10%	
14.	Guest rooms	Yes	0%	
15.	Card and Carrom	Yes	0%	
16.	Physiotherapy room	Yes	0%	
17.	Resident manager office	Yes	0%	
18.	Multipurpose hall	Yes	0%	
19.	Dining	Yes	0%	
20.	Library	Yes	0%	
21.	Space for doctor	Yes	0%	

YoursFaithfully For Aniruddha Vaidya & Associates

AR.RADHIKA VAIDYA

L.S/ Architect

License No CA/85/8968



ANIRUDDHA VAIDYA & ASSOCIATES

An ISO 9001: 2008 Certified Organisation ARCHITECTS, TOWN PLANNERS & INTERIOR DESIGNERS

4, Dattaprasad, 1206, B/7. Off. J. M. Road, Shivajinagar, Pune 411004 Tel. / Fax : 2553 0420. 2553 0430 Email : archvaldya@gmail.com Web : www.archvaldya.com

FORM1 [seeRegulation3]

ARCHITECT'SCERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date:28.12.2017

To

M/S. MATRIX DEVELOPERS PVT LTD.

Pune.

Subject: Certificate of Percentage of Completion of Construction Work of 3Wing(s) of the Forest Trails Athashri -B2 (Sector R26-B2A, B2B, B2C) of the Project[MahaRERA Registration Number P52100000029] situated on the Sector No.R-26,Survey No 16/1 and othersdemarcated by its boundaries Latitude18°30'41"N, Longitude73°44'02.76"E, By G4,G4 A,OS 13 to the East, By part of G 61 and beyond that 12.0 mtown ship road to the West,by G 61 to the North,G 61 and portion of 12.0 m township road to the South of Division-Pune, Village-Mouje Bhugaon, Taluka- Mulshi, District-Pune 412115 admeasuring 9913.274 sq.mts. Area being developed byM/S. MATRIX DEVELOPERS PVT LTD

Sir.

I Radhika A. Vaidya have under taken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion of ConstructionWork of 3 Wing(s) of the Forest Trails Athashri -B2(Sector R26-B2A, B2B, B2C) of the Project [MahaRERA Registration NumberP52100000029] situated on the Sector No.R-26, Survey No 16/1 and othersdemarcated by its boundaries Latitude18° 30'41"NLongitude73°44'02.76"E, By G4,G4 A,OS 13 to the East, By part of G 61 and beyond that 12.0 mtown ship road to the West, by G 61 to the North, G 61 and portion of 12.0 m township road to the South of Division - Pune Village - Mouje Bhugaon, Taluka - Mulshi, District-Pune 412115 admeasuring 9913.274sq.mts.Area being developed by M/S. MATRIX DEVELOPERS PVT LTD

- 1. Following technical professionals are appointed by Owner/ Promoter:-
 - (i) Ar. Radhika A. Vaidya asL.S. / Architect;
 - (ii) JW consultants LLP asStructuralConsultant
 - (iii) Aquamate consultants PVt. Ltd_as MEP Consultant
 - (iv) Shashank Saraf as SiteSupervisor.

1



Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Workdoneforeachofthebuilding/WingoftheRealEstateProjectasregisteredvide number under MahaRERA is as per table A herein below. The percentageoftheworkexecutedwithrespecttoeachoftheactivityoftheentirephase is detailedinTable B.

Table A

Forest TrailsAthashri - B2(Sector R26-B2A)

(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	90%
2	Plinth	40%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls,Internal Plaster, Floorings within Flats/Premises, Doors andWindows toeachofthe Flat/Premises	0%
7	SanitaryFittings withinthe Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases,Lifts Wells andLobbies ateach Floorlevel connectingStaircases andLifts, OverheadandUndergroundWater Tanks	0%
9	The external plumbingandexternal plaster, elevation, completion of the Building/Wing	0%
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFONOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of of of of the complex of the compl	0%

CompoundWall and all other requirements as may be required to Obtain Occupation / Completion Certificate

Table A

Forest TrailsAthashri - B2 (Sector R26-B2B)

(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	100%
2	Plinth	30%
3	Number of Podiums	ο%
4	Stilt Floor	Ο%
5	Number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0 %
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions ofenvironment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall and allother requirements as may be required to Obtain Occupation / Completion Certificate	0 %

Table A

Forest TrailsAthashri - B2(Sector R26-B2C)

(to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks /Activity	Percentage Of work done
1	Excavation	100%
2	Plinth	35%
3	Number of Podiums	0%
4	Stilt Floor	0%
5	Number of Slabs of Super Structure	0%
6	Internal walls,Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%
10	Installation of lifts, water pumps, Fire Fighting Fitting And Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of of of areas appurtenant to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall and allother requirements as may be required to ObtainOccupation / Completion Certificate	0%

<u>Internal & External Development Works in Respect of the entire Registered</u> <u>Phase</u>

S.No	CommonareasandFacilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	InternalRoads&Foothpaths	Yes	0%	
2.	WaterSupply	Yes	0%	
3.	Sewerage(chamber,lines, SepticTank,STP)	Yes	0%	
4.	StormWaterDrains	Yes	0%	
5.	Landscaping &TreePlanting	Yes	0%	
6.	Street Lighting	Yes	0%	
7.	Community Buildings	NO	_	NA
8.	Treatmentanddisposalof sewageand sullagewater	Yes	0%	
9.	SolidWaste management& Disposal	Yes	0%	
10.	Water conservation, Rain water harvesting	Yes	0%	
11.	Energy management	NO	ELF	NA
12.	Fire protection and fire safety requirements	Yes	0%	<u></u>
13.	Electrical meter room, substation, receiving station	Yes	0%	
14.	Guest rooms	Yes	0%	
1 5.	Card and Carrom	Yes	0%	
16.	Physiotherapy room	Yes	0%	
<u>1</u> 7.	Resident manager office	Yes	0%	·
18.	Multipurpose hall	Yes	0%	·
19.	Dining	Yes	0%	
20.	Library	Yes	0%	·····
21.	Space for doctor	Yes	0%	

YoursFaithfully For Aniruddha Vaidya & Associates

AR.RADHIKA VAIDYA

L.S/ Architect

License No CA/85/8968