202, Padmanabh, Plot No. 33, Road No. 4, Pandurang Wadi, Goregaon (E) Mumbai - 63

FORM 1

ARCHITECT'S CERTIFICATE

Date: 15th July 2019

То

The Sumer Radius Realty Pvt. Ltd. 220, Commerce House, 140 N M Road, Fort, Mumbai 400023.

Subject: Certificate of Percentage of Completion of Construction Work as on 30th June, 2018 of Six No. of Building(s)/Wing(s) of the Phase 1 of the Project Avenue 54 [Maharera Regn No. P51800007149] situated on the Plot bearing C.N. No/CTS No./Survey no./ Final Plot no CTS No. 401, 402, 415 to 438, demarcated by its boundaries (latitude and longitude of the end points) CTS 374 & 375 to the North, St Theresas Convent High School to the South, 18.30 Hasanabad Road to the East, 27.45 mtr wid S V Road to the West of Division Konkan village Bandra taluka Andheri District Mumbai Suburban PIN 400054 admeasuring 19339.24 sq.mts. area being developed by Sumer Radius Realty Pvt. Ltd.

Sir,

I/ We Ar. Girish Chaudhari have undertaken assignment as **Architect** of certifying Percentage of Completion of Construction Work of the **Six** Building(s)/Wing(s) of the **Phase 1** of the Project, situated on the plot bearing C.N. No/CTS No./Survey no./ Final Plot no **CTS No. 401, 402, 415 to 438** of Division **Konkan** village **Bandra** taluka **Andheri** District **Mumbai Suburban** PIN **400054** admeasuring **19339.24** sq.mts. area being developed by **Sumer Radius Realty Pvt. Ltd.**

- 1. Following technical professionals are appointed by Owner / Promoter:-
 - (i) M/s/Shri/Smt Access Design Studio as Architect
 - (ii) M/s /Shri / Smt Mahimtura Consultants Pvt Ltd as Structural Consultant
 - (iii) M/s /Shri / Smt S.N.Joshi Consultants Pvt Ltd as MEP Consultant
 - (iv) M/s /Shri / Smt Ganesh Vaidyanathan as Site Supervisor
 - (v) M/s/Shri/Smt Ellora Project Consultants Pvt. Ltd. as Architect / L.S.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number P51800007149 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

AR. GIRISH CHAUDHARI

ANNEXURE 1 - TABLE A

Project Avenue 54

Installation of equipment a Areas, electric conditions of entrance lob appurtenant other require Occupation /	9 The external completion (/ Wing	8 Staircases, L connecting s Undergroun	7 Sanitary Fitt Electrical Fit	6 Internal Wa Premises Do Premises	number of S	5 number of S	number of s	4 number of Stilt Floor	3 number of Podium(s)		number of Plinth	number of I	2 number of I	1 Excavation	Sr. No. Tasks / Activity		
Installation of lifts, water pumps, Fire fighting fittings and equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, Plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	Staircases, Lift Wells & Lobbies at each floor level connecting staircases and Lifts, Overhead and Underground Water Tanks	Sanitary Fittings within the Flat / Premises Electrical Fittings within the Flat / Premises	Internal Walls, Internal Plaster Floorings within Flats / Premises Doors and Windows to each of the Flat Premises	number of Slabs of Super Structure - % Completion	number of Slabs of Super Structure	number of Stilt Floor - % Completion	number of Stilt Floor	Podium(s)	number of Plinth - % Completion	Plinth	number of Basement(s) - % Completion	number of Basement(s)		ivity	BUILDING No. :	
0	0	0	0	0	0	13	NA C	0	0	0	0	0 (0	0 0	Percentage of	Tower 1A	
0	0	0	0	0	0	23	N C	0 0	0	0	н.	0 4	2 0	work done (%)	Percentage of	Tower 1	
0	0	0	0	0	0	23	N 0	0	0	0 +	ى د	4 C	نا د	work done (%)	Percentage of	Tower 1C	
0	0	47%	0	1%	32%) OO	1	0	0 0	100	100	4 2	DOL	work done (%)	Percentage of	Tower 2	
0	0	19%	0	0	0	0	д	0 (0 0	در د	75%	4	100	work done (%)	Percentage of	Tower 3	
0	0	0	0	0	0	NA	0	0 0	0		0	4	100	work done (%)	Percentage of	Tower 4	



FORM - 1 ANNEXURE 2 - TABLE B

Internal & External Development Works in respect of the entire Registered Phase

Avenue 54

r. No.	COMMON AREAS AND FACILITIES,								
	AMENITIES	Proposed (Yes / No)	Percentage of Work Done (%)	Details					
1	Internal Roads & Footpaths	No	0%						
2	Water supply	Yes	0%	NA					
3	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	0%	common for phase 1 & 2 common for phase 1 & 2					
4	Storm Water Drains	Yes	0%	Francisco de la constanta de l					
5	Landscaping & Tree Planting	Yes	0%	common for phase 1 & 2					
6	Street Lighting	No	0%	common for phase 1 & 2					
7	Community Buildings	No	0%	NA NA					
8	Treatment & Disposal of Sewage & Sullage Water	Yes	0%	NA common for phase 1 & 2					
9	Solid Waste Management & Disposal	Yes	0%	common for phase 1 & 2					
10	Water Conservation, Rain water harvesting	Yes	0%	RWH Tanks					
11	Energy Management	No	0%						
12	Fire Protection & Fire Safety Requirements	Yes	0%	NA common for phase 1 & 2					
13	Electrical Meter Room, Sub-Station, Receiving Station	Yes	0%	No Receiving Station					
14	Aggregate area of recreational open space	Yes	0%	common for phase 1 & 2					
15	Open Parking	No	0%	51.6					
16	Sculpture	Yes	0%	NA NA					
17	Outdoor kids play area with play equipments	Yes	0%	common for phase 1 & 2 common for phase 1 & 2					
18	Multipurpose path	Yes	0%						
19	Reflexology path	Yes	0%	common for phase 1 & 2					
20	Senior Citizen Area	Yes	0%	common for phase 1 & 2					
21	Climbing Wall	Yes	0%	common for phase 1 & 2					
22	Fountain Play	Yes	0%	common for phase 1 & 2					
23	Amphitheatre/Tiered Seating	Yes	0%	common for phase 1 & 2					
24	Multipurpose Lawn	Yes	0%	common for phase 1 & 2					

