

Form-1

(See regulations 3)

ARCHITECT CERTIFICATE

Date: 01/04/2021

To,

High Seas Propertis Pvt.Ltd Through,

Mr. Atul H. MundadaB

16/1, Parvati Chamber, Sangam Press Road,

Off Karve Road, Kothrud, Pune -411038

Subject: Certificate of Percentage of Completion of construction work B [MahaRERA Registration Number] situated on the Plot bearing C.N. No/CTS No./Survey no./ Final Plot no S.NO- 45/2+46/1(P)+46/2 village Sus taluka Mulshi District Pune PIN 411021 demarcated by its boundaries (latitude and longitude of the end points)

North East A 18° 33' 17.68" N, 73° 45' 48.24" E

South East B 18° 33' 16.36" N, 73° 45' 47.94" E

South West C 18° 33' 16.54" N, 73° 45' 46.86" E

North West D 18° 33' 17.66" N, 73° 45' 46.98" E

North: 9.00 M.W. Internal Road

South: Wing A7-A8

East: 9.00 M.W. Internal Road

West: Open Space

o.N 02 of Division Pune village Sus, Taluka Mulshi, District Pune PIN_411021 admeasuring 1659.97 sq.mts. gross plot area being developed by High Seas Properties Pvt. Ltd.

Ref: MahaRERA Registration Number P52100019366

Sir,

I Mr. Milind Saraf, Proprietor of Subha Architects have undertaken assignment as Architect / Licensed Surveyor of certifying Percentage of Completion of Construction Work being work of the D5 Building situated on the plot bearing C.N. No/CTS No./Survey no./ Final Plot no S.NO- 45/2+46/1(P)+46/2 village Sus taluka Mulshi District Pune PIN 411021 admeasuring plot 1659.97sq.mts. plot area being developed by High Seas Properties Pvt. Ltd.



Following technical professionals are appointed by owner/ promoter:

(i) M/s/Shri/Smt Mr Milnd Saraf, Proprietor of Subha Architects,

12B,S.No.06, Hissa No.1/7, 3rd Floor, Varsha Airavat Bldg,

Opp. Bata Showroom, Baner, Pune 411045.

as L.S. / Architect

(ii M/s/Shri/Smt Sunil Mutalik & Associates

1349/1350 Shukrawar Peth, Arthshilpa, Third Floor,

Above Hotel Ganaraj, Bajirao Road, Pune 2 Phone- 24476705,

as Structural Consultant

(iii) M/s/Shri/Smt Consolidated Consultants & Engineers Pvt. Ltd.

5/6, Venkateshwara tower, 1st floor,

bharti vidhyapeth katraj, pune -411 046-tel.no-020-24378704

as MEP Consultant

(iv) M/s/Shri/Smt Mangesh S. Jagtap

Flat No. 102, Nirman Sankalp Apt. Ganeshmala , Pune - 411030.

as Site Supervisor

Based on site inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I Certify that as on the date of this certificate,

The Percentage of work done for each of the Building / wing of the Real Estate Project as registered vide number P52100019366 under MahaRERA is as per table A Herein Below,

The Percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B

Yours Faithfully

Subha Architects

Ar. Milind Saraf

CA/97/22139





Table A:

Sr. No. (I):	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of the Certificate) (3)	
1.	Excavation	95%	
2.	Basements (if any) and Number of Plinth	50%	
3.	Podiums (if any)	50%	
4.	Stilt Floor		
5.	Number of Slabs and Super Structure	42%	
6.	Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises		
7.	Sanitary Fittings within the Flat/Premises	-	
8.	Staircases, Lifts Wells and lobbies at each Floor Level Overhead and Underground Water Tanks	-	
9.	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	-	
10.	Installation of Lifts. water pumps, Electrical Fittings to common Areas, Electro Mechanical Equipment, Compliance to condition of environment, finishing to entrance lobby/s, Plinth Protections, Paving of Areas appurtenant to Building /Wing, Compound wall and all other requirements as may be required to obtain Occupation. Completion Certificate	-	



TABLE-B

Common Areas (Internal and External Development Works) in respect of the Registered Project:

D5 Building

Sr. No.	Common areas and Facilities	Proposed	Percentage of	Details
(1)	(2)	(Yes/ No)	Actual Work Done (As on date of the	
		(3)	Certificate) (4)	(5)
1.	Internal Roads & Footpaths	YES	85%	Work In Progress
2.	Water Supply	YES	75%	Work In Progress
3.	Sewerage (Chamber, lines, Septic Tank, STP).	YES		Work In Progress
4.	Strom Water Drains	YES	95%	Work In Progress
5.	Landscaping & Tree Planting	YES	80%	Work In Progress
6.	Street Lighting	YES	90%	Work In Progress
7.	Community Buildings	YES	100%	Completed
8.	Treatment and disposal of sewage and sullage water.	YES	95%	Work In Progress
9.	Solid Waste Management & Disposal	YES	90%	Work In Progress
10.	Water conservation/Rain water harvesting	YES	80%	Work In Progress
11.	Energy management	YES	80%	Work In Progress
12.	Fire protection and Fire safety requirements	YES	60%	Work In Progress
13.	Electrical meter room, sub-station, receiving station.	YES		Work In Progress
14.	Others (Option to Add more).		-	