VINAY PATIL & ASSOCIATES

ARCHITECTS • INTERIOR DESIGNERS • GOVT. APPROVED VALUERS

104, NAVNATH PRASAD, OPP. GHANTALI MANDIR, NAUPADA, THANE - 400 601.

E m s | | A d d r e s | : v p a s s o @ r e d | f f m a | | | . c o m

PHONE : (0): 2544 8389 (R): 2583 0395 (M): 98890 34169

FORM 1

(see Regulation 3)

ARCHITECT'S CERTIFICATE

Date: 10th OCT, 2019.

To,

M/s, New India Construction.

706, 7th Floor, Simran Plaza, 3rd/4th Road Junction, Khar (W) - 400052.

Subject: Certificate of Percentage of Completion of Construction Work of 3 No. of Building(s) / 2 Wing(s) of the NASAM DARUL - AMAAN Phase 1 of the Project (MahaRERA Registration Number.), situated on the Plot bearing C.N. No/CTS No./Survey No./Final Plot No. 154/1 demarcated by its boundaries (latitude and longitude of the end points) 19°09′09.6″N to the North ---- to the South 73°02′09.1″E to the East ---- to the West of Division Kokan Village Shil Taluka Thane District Thane PIN 400612 admeasuring 7890.00 sq.mts. area being developed by M/s. New India Construction.

Sir.

I/We Mr. Vinay R. Patil have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion of Construction Work of the _3_Building(s)/__Wing(s) of the _- Phase of the Project, situated on the plot bearing C.N. No/CTS No/Survey No./Final Plot No.154/1 of Division Kokan village Shil taluka Thane District Thane PIN 400612 admeasuring 7890.00 sq.mts. area being developed by M/s. New India Construction.

Following technical professionals are appointed by Owner / Promoter : -

- M/s. Vinay Patil & Associates as Architect;
- (ii) M/s. Shravani Consultant as Structure Consultants.
- (iii) M/s. Envirocon as MEP Consultant.
- (iv) Mr. Mohammed Ahmed as Site Supervisor.

Based on Site Inspection, with respect to each of the Building / Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building /Wing of the Real Estate Project as registered vide number _____under MahaRERA is as per table A in below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE - A

Building /Wing Number Bldg- ${\bf A}$ and ${\bf B}$.

Sr. No.	Tasks /Activity	Percentage of work done	
(1)	(3)	(3)	
1.	Excavation	80%	
2.	1 number of Basement(s) and Plinth	100%	
3.	number of Podiums	***	
4.	Stilt Floor	60%	
5.	8 number of Slabs of Super structure	75%	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%	
7.	Sanitary Fitting within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0%	
8.	Staircases, Lifts wells and Lobbies at each Floor level connecting Staircase and Lifts, Overhead and Underground Water Tanks.	0%	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building /Wing.	0%	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate.	0%	



TABLE - A

Building /Wing Number Bldg-C.

Sr. No.	Tasks /Activity	Percentage of work done (3) 0%	
(1)	(3)		
1.	Excavation		
2.	1 number of Basement(s) and Plinth	0%	
3.	number of Podiums	0%	
4.	Stilt Floor	0%	
5.	8 number of Slabs of Super structure	0%	
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%	
7.	Sanitary Fitting within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0%	
8.	Staircases, Lifts wells and Lobbies at each Floor level connecting Staircase and Lifts,	0%	
9.	Overhead and Underground Water Tanks. The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building /Wing.	0%	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance		
	to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate.	0%	

An (marine)

 $\underline{TABLE-B}$ Internal and External Development Works in respect of the entire Registered Phase.

S.No.	Common areas and	Proposed	Percentage of	Details
	Facilities, Amenities	(Yes/No)	Work done	
(1)	(2)	(3)	(4)	(5)
1.	Internal Roads & Foot -	NO		
	Paths.			
2.	Water Supply	YES	0%	Not Executed
3.	Sewerage (chamber,	YES	0%	Not Executed
	lines, Septic Tank, STP)			
4.	Storm Water Drains	YES	0%	Not Executed
5.	Landscaping & Tree	YES	0%	Not Executed
	Planting			
6.	Street Lighting	NO		N.A.
7.	Community Building	NO		N.A.
8.	Treatment and disposal			
	of sewage and sullage	NO		N.A.
	water.			
9.	Solid Waste	NO		N.A.
2560	management & disposal.			
10.	Water conservation,	YES	0%	Not Executed
277	Rain water harvesting.			
11.	Energy management	YES	0%:	Not Executed
12.	Fire protection and fire	NO	*****	Not Executed
	safety requirements.			
13.	Electrical meter room,	YES	0%	Not Executed
	sub - station, receiving			
	station.			
14.	Other (Option to Add			
	more).			

Yours Faithfully,

MR, VINAY R. PATIL (License No. CA-87/10566)