Annexure A

FORM 1

[see Regulation 3]

ARCHITECT'S CERTIFICATE (To be submitted at the time of Registration of Project, Quarterly Progress Reporting and for

withdrawal of Money from Designated Account)

To, Date: 05.12.22.

Shri. Rajkumar B. Soni,

Partner of M/s. Shreenathji Infracon Build Pvt. Ltd.,

C.A. to Gundecha C.H.S.L

210 – 211, Shah Arcade 3, Sun Rise Tower, Rani Sati Road,

Near Passport Office, Malad (E), Mumbai – 400 097.

Subject: Certificate of Percentage of Completion of Construction Work of <u>Gundecha C.H.S.L</u> having **MahaRERA Registration Number** <u>applied for</u> (Only Applicable after project Registration) being developed by <u>M/s. Shreenathji Infracon Build Pvt. Ltd.</u>

Sir,

I, Divyesh H. Parekh, have undertaken assignment as Licensed Surveyor of certifying Percentage of Completion of Construction Work of <u>Gundecha C.H.S.L</u> having MahaRERA Registration Number <u>applied for being developed by *M/s. Shreenathji Infracon Build Pvt. Ltd.*</u>

Based on Site Inspection, with respect to Layout / each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE-ASingle building is proposed.

Sr.	Tasks / Activity	Percentage of Actual Work Done	
No.	(2)	(As on 05.12.2022)	
(1)		(3)	
1.	Excavation	0% Completed	
2.	Basements (if any)	NA	
3.	Podiums (1)	0% Completed	
4.	Plinth	0% Completed	
5.	Stilt Floor	0 Slabs Completed	
6.	Slabs of Super Structure	0% Completed	
7.	Internal walls, Internal Plaster, Floorings,	0% Completed	
	Door and windows within Flats/Premises		

8.	Sanitary Fittings within theFlat/Premises	0% Completed	
9.	Staircases, Lifts Wells and Lobbies at each	0% Completed	
	Floor level, Overhead and Underground Water		
	Tanks		
10.	External plumbing and external plaster,	0% Completed	
	elevation, completion of terraces with		
	waterproofing of the Building/Wing.		
11.	Installation of Lifts, water pumps, Fire Fighting	0% Completed	
	Fittings and Equipment as per CFO NOC,		
	Electrical fittings, mechanical equipment,		
	compliance to conditions of environment/CRZ		
	NOC, Finishing to entrance lobby/s, plinth		
	protection, paving of areas appurtenant to		
	Building/Wing, Compound Wall and all other		
	requirements as may be required to complete		
	project as per specifications in agreement of		
	Sale.		
	Any other activities.		

TABLE-B Common Areas (Internal and External Development Works) in respect of the entire Registered Phase / Project Number

Sr.	Common areas and	Proposed	Percentage of Actual Work	Details
No	Facilities	(Yes / No)	Done (As on 05.12.2022)	(5)
(1)	(2)	(3)	(4)	
1.	Internal Roads & Footpaths.	No		
2.	Water Supply	Yes	0% Completed	
3.	Sewerage (Chamber, lines, Septic Tank, STP).	No		
4.	Storm Water Drains	Yes	0% Completed	
5.	Landscaping & Tree Planting	Yes	0% Completed	
6.	Street Lighting	No		
7.	Community Buildings	No		
8.	Treatment and disposal of sewage and sullage water.	No		
9.	Solid Waste management and Disposal	Yes	0% Completed	
10.	Water conservation / Rain water harvesting	Yes	0% Completed	

11.	Energy Management	No		
12.	Fire protection and Fire Safety	Yes	0% Completed	
	requirements			
13.	Electrical meter room, sub -	No		
	station, receiving station.			
14.	Others (Option to Add			
	more).			

Yours faithfully,

Licensed Surveyor
(DIVYESH H. PAREKH) (P/444/LS)

Agreed and Accepted by:

Shri. Rajkumar B. Soni,

Partner of M/s. Shreenathji Infracon Build Pvt. Ltd.,

Date: 05.12.2022