

akruti consu

ARCHITECTS
 ENGINEERS
 INTERIOR DESIGN

Ref: - 9519/ B.P.K.19/2015-16 / 324 /2018

Date :- 30/06/2018

To.

M/s. Arihant Enterprises

Arihant City, Near Sai Baba Temple, Kalyan-Bhiwandi Road, Temghar, Bhiwandi, Thane- 421 302.

Sub :- Certificate of Percentage of Completion of Construction Work of Building No.A. B, C, D, D1, D2, F, H, H1 & H2 situated on the Plot bearing S.No.116/1(pt), 116/ 2(pt), 118/7, 118/9, 118/11 (pt), 119/1(pt), 119/1(pt), 119/2 (pt), 119/2 (pt), 119/4 & 119/8 (pt) demarcated by its boundaries adj. Bhadvade Shiv to the North30 m. w. D. P. Road to the South 60 m. w. D. P. Road to the East adj. S.No. 112 114,118 to the West of Division - Kokan village - Temghar Taluka - Bhiwandi District-Thane PIN- 421302 admeasuring- 30727.25 Sq.mts. area being developed by M/s. Arihant Enterprises.

Ref: - MahaRERA Registration No.P51700010884

Sir / Madam,

I Ar. A.V. Desai have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the aforesaid development bearing the subject Project Details.

- 1. Following technical professionals are appointed by Owner / Promoter :-
 - M/s akruti consultants

(Architect)

· M/s. Tech Line

(Structural Consultant)

 M/s. Mantras Green Resources Ltd. M/s. Om Sai Electricals

(MEP Consultant)

M/s. Shri Ram Vardayani Plumbing Works M/s Mahavir Fire Consultants and Agency

M/s Balaji Construction

(Site Supervisor)

M/s S.B.Enterprises

M/s Meakvel Construction

Based on Site Inspection, with respect of the Building aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Building is as per Table - A, attached along with. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table - B. as per attachment.

This certificate is issued on the request of the client in accordance With MahaRERA Regulations 2017, Part -II Dated 24 th April 2017.

Yours Faithfully

For :- M/s. akruti consultants

Architect: A. V. DESA Regd. No.: CA/94/17923

Attachments :- Table - A and Table - B

1. Table - A :- Bldg - A,B,C,D,D1,D2, F,H,H1 & H2 MahaRERA Registration No. P51700010884

Sr. No	Task / Activity	Percentage of work done % (3)			
(1.)	(2)	Bldg A,B,D1,D2 H,H1& H2	Bldg C	Bldg D	Bldg. -F
1.	Excavation	100	100	100	100
2.a	Number of Basement	NA	NA	NA	NA
2.b	Number of Plinth	100	100	100	100
3.	Number of Podium	NA	NA	NA	NA
4.	Stilt Floor	100	0	85	85
5.	Number of Slabs of Super Structure (A,B,D,D1,D2, F-13th Nos, C-5th Nos.,H,H1,H2 - 8 th Nos.)	100	10	100	100
6.	Internal Walls, Internal Plaster, Flooring Within Flats / Premises Doors and Windows to each of the Flat / premises.	100	0	50	40
7.	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat/Premises.	100	0	0	0
	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	100	0	0	0
	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the Building	100	0	70	15
	Installation of Lifts Water pumps, Fire Fighting Fitting and Equipment as per CFO NOC, Electrical fitting to Common Areas, electromechanical equipment, Compliance to	9.00 cein	and you	The same	2000
	conditions of environment /CRZ NOC, Finishing to entrance lobby/s, Plinth protection, Paving of areas appurtenant to building /Wing Compound Wall and all other requirements as may be required to obtain occupation Completion Certificate	95	0	0	0

2. Table - B:- Internal & External Development Works in Respect of the entire Registered Phase

S. No.	Common areas and Facilities, Amenities (2)	Proposed (Yes/No) (3)	%Work done (4)	Details (5)
1.	Internal Roads & Footpaths	Yes	95	Work Completed
2.	Water Supply	Yes	85	Work in Progress
3.	Sewerage (chamber, Lines, Septic Tank, STP)	Yes	80	Work in Progress
4.	Storm Water Drains	Yes	75	Work in Progress
5.	Landscaping & Tree Planting	Yes	65	Work in Progress
6.	Street Lighting	Yes	80	Work in Progress
7.	Community Buildings	Yes	25	Work in Progress
8.	Treatments and disposal of sewage and sullage, water	Yes	0	Not Started
9,	Solid Waste management & Disposal	Yes	5	Work in Progress
10.	Water Conservation, Rainwater harvesting	Yes	75	Work in Progress
11.	Energy management	Yes	75	Work in Progress
12	Fire protection and fire safety requirements	Yes	75	Work in Progress
13.	Electrical Meter Room, substation, receiving station	Yes	75	Work in Progress

For:- M/s. akruti consultants

Architect: A. V. DESAI Regd. No.: CA/94/17923