AR. MANAN DEDHIA (B.Arch)

2/10, Jay Mahavir, R.B.Mehta Road, Ghatkopar - East, Mumbai - 77

manandedhia25@gmail.com

+91 9820680448



FORM 1

ARCHITECT'S CERTIFICATE

Date: 30/06/2017

Kalyani Enterprise Kalpesh Patel (Partner) 208/602, Anita Kutir, Pantnagar, Ghatkoper (E), Mumbai: 400075

Subject: Certificate of Percentage of Completion of Construction Work of Bhavani Heights, No. of Building 01 with 2 wings of the Project [MahaRERA Registration Number] situated on the Plot bearing C.N. No/CTS No./Survey no./ Final Plot no 99/4 demarcated by its boundaries (latitude and longitude of the end points) Survey No. 99/6 & 99/3 to the North, Survey No. 98/5 & 100 to the South, Survey No. 98/3 & 15 m Wide Road to the East and Survey No. 95 & 30 m wide road to the West of Division Kokan, village Badlapur Shirgaon taluka Ambarnath District Thane PIN 421503 admeasuring 4480 sq.mts. area being developed by Kalpesh Patel (Partner).

Sir,

I Manan Dedhia have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the Bhavani Height Building with A and B wing of the Project, situated on the plot bearing C.N. No/CTS No./Survey no./ Final Plot no 99/4 demarcated by its boundaries (latitude and longitude of the end points) Survey No. 99/6 & 99/3 to the North, Survey No. 98/5 & 100 to the South, Survey No. 98/3 & 15 m Wide Road to the East and Survey No. 95 & 30 m wide road to the West of Division Kokan, village Badlapur Shirgaon taluka Ambarnath District Thane PIN 421503 admeasuring 4480 sq.mts. area being developed by Kalpesh Patel (Partner).

- 1. Following technical professionals are appointed by Owner / Promoter :-
 - M/s/Shri/Smt Manan Dedhia as L.S. / Architect;
 - (ii) M/s/Shri/Smt Hiren Shah as Structural Consultant
 - (iii) M/s/Shri/Smt None as MEP Consultant
 - (iv) M/s/Shri/Smt Ravindra Bankar as Site Supervisor



Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number _____ under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

(A Wing of the Project)

Sr. No Tasks /Activity		Percentage of work done	
1	Excavation	100%	
2	2 number of Basement(s) and Plinth	100%	
3	0 number of Podiums	0%	
4	Stilt Floor	0%	
5	13 number of Slabs of Super Structure	23%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises		
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	20%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	, e e e e	

Table A

(B Wing of the Project)

Sr. No Tasks /Activity		Percentage of work done	
1	Excavation	0%	
2	2 number of Basement(s) and Plinth	0%	
3	0 number of Podiums	0%	
4	Stilt Floor	0%	
5	13 number of Slabs of Super Structure	0%	
7	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises		
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate 0%		



TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

S.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Foothpaths	No	NA	
2.	Water Supply	Yes	0%	Yet To Start
3.	Sewarage (chamber, lines, Septic Tank , STP)	Yes	0%	Yet To Start
4.	Storm Water Drains	Yes	0%	Yet To Start
5.	Landscaping & Tree Planting	Yes	0%	Yet To Start
6.	Street Lighting	No	NA	NA
7.	Community Buildings	No	NA	NA
8.	Treatment and disposal of sewage and sullage water	Yes	0%	Yet To Start
9.	Solid waste Management & Disposal	No	NA	NA
10.	Water conservation & Rain water Harvesting	Yes	0%	Yet To Start
11.	Energy Management	Yes	0%	Yet To Start
12.	Fire Protection & Fire Safety Requirement	Yes	0%	Yet To Start
13.	Electrical Room, Sub-station, receiving station	Yes	0%	Yet To Start
14.	Others (Option To Add more			

Yours Faithfully



