

## Annexure A FORM 1 ARCHITECT'S CERTIFICATE

Date: 15-10-2023

To, La Arihant Builders And Developers, Survey No - 4/1, 4/2, Village Kasgaon, Karjat Badlapur Highway, Badlapur East - 421503

**Subject:** Certificate of Percentage of Completion of Construction work as on **30-09-2023** of **La Arihant Heritage** having MahaRERA Registration Number. **P51700003423** being developed by the **La Arihant Builders And Developers**.

Sir,

I/We Structulis Consultants Pvt. Ltd. have undertaken assignment as Architects/Licensed Surveyorof certifying Percentage of Completion of Construction work of La Arihant Heritage the building having MahaRERA Registration Number.P51700003423 being developed by the La Arihant Builders And Developers.

- . M/s Structilis Consultant Pvt. Ltd as an Architect;
- · M/s Adharsila Consultants Structural Consultant;
- Shri Manojkumar Nanhelal Patel as Site Supervisor

Based on Site Inspection, with respect to Layout/each of the Building /Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building / wing of the Real Estate Project under MahaRERA is as registered as per **Table - A** herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.





Table A Wing A and B

Sr.No	Task/Activity	Percentage of Work Done (30-09-2023)	
(1)	(2)	(3)	
1.	Excavation	100%	
2.	Number of Basement(s)	NA	
3.	Number of Plinth	100%	
4.	Number of Podium	NA	
5.	Stilt Floor	100%	
6.	Slabs of Super Structure	100%	
7.	Internal walls, Internal Plaster Floorings, Doors and Windows within Flat/Premises	100%	
8.	Sanitary Fittings within the Flat/Premises.	100%	
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water tanks.	100%	
10.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%	
11.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall protection and all other requirements as may be required to complete project as per specification in agreement of sale. Any other activities.	90%	





Table A Wing C and D

Sr.No	Task/Activity	Percentage of Work Done (30-09-2023)
(1)	(2)	(3)
1.	Excavation	100%
2.	Number of Basement(s)	NA
3.	Number of Plinth	100%
4.	Number of Podium	NA
5.	Stilt Floor-	100%
6.	Slabs of Super Structure	100%
7	Internal walls, Internal Plaster Floorings, Doors and Windows within Flat/Premises	100%
8.	Sanitary Fittings within the Flat/Premises. 1009	
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water tanks.	80%
10.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
11.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall protection and all other requirements as may be required to complete project as per specification in agreement of sale. Any other activities.	90%






Table A Wing E and J

Sr.No	Task/Activity	Percentage of Work Done (30-09-2023)
(1)	(2)	(3)
1	Excavation	100%
2.	Number of Basement(s)	NA
3.	Number of Plinth	100%
4.	Number of Podium	NA
5.	Stilt Floor	100%
6.	Slabs of Super Structure	100%
7.	Internal walls, Internal Plaster Floorings, Doors and Windows within Flat/Premises	. 75%
8.	Sanitary Fittings within the Flat/Premises.	0%
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water tanks.	0%
10.	external plumbing and external plaster, elevation, appletion of terraces with waterproofing of the ding/Wing.	
11.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall protection and all other requirements as may be required to complete project as per specification in agreement of sale. Any other activities.	0%





Table A Wing F and G

Sr.No	Task/Activity	Percentage of Work Done (30-09-2023)	
(1)	(2)	(3)	
1.	Excavation	100%	
2.	Number of Basement(s)	NA	
3.	Number of Plinth	100%	
4.	Number of Podium	NA	
5.	Stilt Floor	NA	
6.	Slabs of Super Structure	100%	
7.	Internal walls, Internal Plaster Floorings, Doors and Windows within Flat/Premises	100%	
8.	Sanitary Fittings within the Flat/Premises.	100%	
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water tanks.	100%	
10.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%	
11.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC. Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall protection and all other requirements as may be required to complete project as per specification in agreement of sale. Any other activities.	100%	





Table A Wing H and I

Sr.No	Task/Activity	Percentage of Work Done (30-09-2023)	
(1)	(2)	(3)	
1.	Excavation	100%	
2.	Number of Basement(s)	NA	
3.	Number of Plinth	100%	
4	Number of Podium	100%	
5.	Stilt Floor	NA	
6.	Slabs of Super Structure	100%	
7.	Internal walls, Internal Plaster Floorings, Doors and Windows within Flat/Premises	100%	
8.	Sanitary Fittings within the Flat/Premises.	100%	
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water tanks.	100%	
10.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%	
11.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall protection and all other requirements as may be required to complete project as per specification in agreement of sale. Any other activities.	100%	





TABLE-B

Common Area (Internal and External Development Works) for

1	La Ari	hant Heritage		
Sr. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work Done (30-09-2023)	Details
(1)	(2)	(3)	(4)	(5)
1,	Internal Roads & Footpaths	Yes/No	70%	NA
2.	Water Supply	Yes/No	100%	NA
3.	Sewerage (chamber, lines, Septic Tank, STP)	Yes/No	80%	,NA
4.	Storm Water Drains	Yes/No	100%	NA
5.	Landscaping & Tree Planting	Yes/No	80%	NA
6.	Street Lighting	Yes/No	90%	NA
7.	Community Buildings	Yes/No	80%	NA
8.	Treatment and disposal of sewage and sullage water.	Yes/No	70%	NA
9.	Solid Waste Management & Disposal	No	0%	NA
10.	Water Conversation & Rain Water Harvesting	No	0%	NA
11.	Energy Management	No	0%	NA
12.	Fire Protection and fire safety requirements	No	0%	NA
13.	Electrical metre room, sub- station, receiving station.	Yes	100%	NA
14.	Others (options to add more)	No	0%	NA

Yours Faithfully,

bodd or and the change of the

Ar. Girish Thakare

Agreed ad Accepted by:

PARTNER/AUTHORISED SIGNATOR Signature of Promoter

La Arihant Builders AndDevelopers

Date: