



DESTINATION

ARCHITECTURE INTERIOR DESIGNS

Table A
Project - GOLDEN VANN

2) Building No - WING A2

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	0%
2	0 Basement and 1 Plinth	0%
3	0 Podiums	0%
4	Stilt Floor	0%
5	8 Slabs of Super Structure (0 slabs constructed out of 8)	0%
6	Internal walls	0%
	Internal Plaster	0%
	Floorings within Flats/Premises	0%
	Doors to each of the Flat/Premises	0%
	Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat/Premises	0%
	Electrical Fittings within the Flat/Premises	0%
8	Staircases (R.C.C. WORK)	0%
	Lifts Wells (R.C.C. WORK)	0%
	Lobbies (R.C.C. WORK)	0%
	Overhead Water Tanks (R.C.C. WORK)	0%
	Underground Water Tanks (R.C.C. WORK)	0%
9	External plumbing	0%
	External plaster	0%
	Elevation	0%
	Completion of terraces with waterproofing	0%
10	Installation of lifts	0%
	Installation of water pumps	0%
	Fire Fighting Fittings and Equipment as per CFO NOC	0%
	Electrical fittings to Common Areas	0%
	Electro mechanical equipment	0%
	Compliance to conditions of environment /CRZ NOC	N.A.
	Finishing to entrance lobby/s	0%
	Plinth protection	0%
	Paving of areas appurtenant to Building/Wing	0%
	Compound Wall	0%
	All other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Handwritten signature/initials

