

Nirmitee Eminence, 4 th Floor, 1175/1, Erandawane, Near Mehendale Garage, Pune 411 004.

FORM 1

ARCHITECT'S CERTIFICATE

To Belvalkar housing Company, Pune 411 004 Date: 16/03/2018

Subject: Certificate of Percentage of Completion of Construction Work of SARITA VAIBHAV B9 & B10 Building of the Project SARITA VAIBHAV B9 & B10, RERA Registration No. (Applied for) Situated on the Plot bearing Survey no. 119/1 (parts) +119/2 (parts) Final Plot no: 544 (part) demarcated by its boundaries

18.29'39" / 73.49'56" to the North

18.29'37" / 73.49'57" to the South

18.29'38"/73.49'57" to the East

18.29'38"/73.49'56" to the West

Of Division Pune village Parvati Taluka Haveli, District Pune PIN 411004 admeasuring 1466.23 sq.mts area being developed by Belvalkar housing company

I Mr. Ajit Belvalkar have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the B9 & B10 Building of the Project Sarita Vaibhav situated on the plot bearing Survey no. 119/1 (parts) +119/2 (parts) / Final Plot no 544 of Division Pune, Village Parvati, taluka Haveli, District Pune Pin 411 004, admeasuring 1466.23 Sq,mts. are being developed by Belvalkar housing company.

Following technical professionals are appointed by Owner/Promoter:-

M/s/ Shri Vikas Achalkar - as L.S./

as L.S./Architect;

M/s J+W consultants -

as Structural Consultant

M/s Mcclin consultants

as MEP Consultant

Mr. Vivek Chavan

as Site Supervisor



Nirmitee Eminence, 4 th Floor, 1175/1, Erandawane, Near Mehendale Garage,

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number..... (Applied) under RERA is as per table A herein below. The percentage of the work executed with respect to each of the major activity of the building / wing and overall percentage of work done with respect to each building/ wing is detailed in the Table B

Table A

BUILDING: SARITA VAIBHAV B9 & B10

Sr. No.	Task / Activity	Percentage of Work done
A.1	Excavation	100%
A.2	Basement and Plinth	100%
A.3	Podium	-
A.4	Stilt Floor	100%
A.5	Super Structure	15%
A.6	Internal Walls, Internal Plaster, Flooring within flats/premises, Doors & windows to each of the Flat/Premises	0%
A.7	Sanitary fittings within Flats/Premises, electrical Fittings within Flat/Premises	0%
A.8	Staircase, Lifts well, and lobbies at each floor level connecting staircase and lifts Overhead and Underground water tanks	0%
A.9	External Plumbing, ext, plaster, painting, elevation, completion of terraces with waterproofing of the building/wing	0%
A.10	Installation of lift, water pumps, fire fighting, fittings and equipment as per CFO, NOC, Electrical fittings to common areas, electro, mechanical equipment. Compliance to condition of environment/CRZ NOC, finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall and all other requirements as may be required to obtain occupation/ completion certificate	0%



Nirmitee Eminence, 4 th Floor, 1175/1, Erandawane, Near Mehendale Garage, Pune 411 004.

Table B

Internal & External development works in respect of the entire registered phase.

Sr. No.	Task / Activity	Percentage of Work done
B.1	Internal Roads & Footpaths	25%
B.2	Water Supply	75%
B.3	Sewerage (chamber, lines, septic tank, STP)	0%
B.4	Storm water line	0%
B.5	Landscaping & Tree plantation	0%
B.6	Street Lighting	50%
B.7	Community Buildings	0%
B.8	Treatment and disposal of sewage and sullage water	0%
B.9	Solid waste management & disposal	0%
B.10	Water conservation, rain water harvesting	0%
B.11	Energy Management	0%
B.12	Fire Protection and fire safety requirements	0%
B.13	Electrical meter room, substation, receiving station	0%

Yours Faithfully

Signature

AR. AJIT BELVALKAR (License NO96/20368)