

#### FORM 1

### ARCHITECT S CERTIFICATE

Date:- 08th Nov.2021

To,

M/s. Mangaldeep Associates & Developers,
Through Partners Mr. Chandan Nathani & Mrs. Meher Nathani,
Sr. No. 61/1 (P),
Rahatani, Pune - 411017.

Subject: Certificate of Percentage of Completion of Construction Work of 2 Buildings (A & B) of the Project "Vaishnave Classic' [MahaRERA Registration Number (applied for)] situated on the Survey No. 61/1 (P) demarcated by its boundaries

to the North - Road width 18m,

to the South - Survey No. 61(P),

to the East - Survey No. 61(P),

to the West - Survey No. 60(P).

of Division Pune, Village Rahatani, Taluka Haveli, District Pune, PIN 411017 admeasuring 2148.90 sq.mts. area being developed by M/s. Mangaldeep Associates & Developers.

Sir,

We, M/s. Unusual Spaces (Sachin Sutar) have undertaken assignment as Architect / Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 2 Buildings (A & B) of the Project "Vaishnave Classic' situated on the Survey No. 61/1 (P) of Division Pune, Village Rahatani, Taluka Haveli, District Pune, PIN 411017 admeasuring 2148.90 sq.mts. area being developed by M/s. Mangaldeep Associates & Developers.

- 1. Following technical professionals are appointed by Owner / Promoter :-
- (i) Shri. Hemant Parag Chopada as Structural Consultant;
- (ii) M/s. RK Enterprises as MEP Consultant;
- (iii) Shri. Vinod Singh as Site Supervisor.

Based on Site Inspection, with respect to each of the Building of the aforesaid Real Estate Project, we certify that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered *vide* number (applied for) under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

# TABLE-A

## A Wing

| Sr. No. | Tasks /Activity  | Percentage of work done |  |
|---------|--|-------------------------|--|
| 1.      | Excavation   | 100 %                   |  |
| 2.      | 0 Basement and 1 Plinth  | 100 %                   |  |
| 3.      | 0 number of Podiums  | NA                      |  |
| 4.      | Stilt Floor  | 100 %                   |  |
| 5.      | 7 number of Slabs of Super Structure   | 100 %                   |  |
| 6.      | Internal Walls, Internal Plaster, Flooring within Flats / Premises, Doors and Windows to each of the Flat / Premises.          | 100 %                   |  |
| 7.      | Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises.                                  | 100 %                   |  |
| 8.      | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks. | 100 %                   |  |
| 9.      | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing        | 100 %                   |  |
| 10.     |  |                         |  |

### **B** Wing

| Sr. No. | Tasks /Activity  | Percentage of work done |  |  |
|---------|--|-------------------------|--|--|
| 1.      | Excavation   | 100 %                   |  |  |
| 2.      | 0 Basement and 1 Plinth  |                         |  |  |
| 3.      | 0 number of Podiums  | 100 %<br>NA             |  |  |
| 4.      | Stilt Floor  | 100 %                   |  |  |
| 5.      | 9 number of Slabs of Super Structure   | 100 %                   |  |  |
| 6.      | Internal Walls, Internal Plaster, Flooring within Flats / Premises, Doors and Windows to each of the Flat / Premises.  | 100 %                   |  |  |
| 7.      | Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises.  | 100 %                   |  |  |
| 8.      | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.   | 100 %                   |  |  |
| 9.      | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing  | 100 %                   |  |  |
| 10.     | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building / Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate. | 100 %                   |  |  |

**TABLE-B**Internal and External Development Works in respect of the entire Registered Phase.

| Sr.<br>No. | Common areas and Facilities,<br>Amenities             | Proposed<br>(Yes/No) | Percentage of<br>Work done | Details                       |
|------------|---|----------------------|----------------------------|-------------------------------|
| 1)         | Internal Roads & Footpaths                            | Yes                  | 100%                       | As per Consultant             |
| 2)         | Water Supply  | Yes                  | 100%                       | Provided                      |
| 3)         | Sewerage (chamber, lines,<br>Septic Tank ,STP)        | Yes                  | 100%                       | Provided                      |
| 4)         | Storm Water Drains                                    | Yes                  | 100%                       | Provided                      |
| 5)         | Landscaping & Tree Planting.                          | Yes                  | 100%                       | Provided                      |
| 6)         | Street Lighting                                       | Yes                  | 100%                       | As per Consultant             |
| 7)         | Community Buildings                                   | No                   | NA                         | NA                            |
| 8)         | Treatment and disposal of sewage and sullage water    | No                   | NA                         | NA                            |
| 9)         | Solid Waste management & Disposal                     | No                   | NA                         | NA                            |
| 10)        | Water conservation & Rain water harvesting            | Yes                  | 100%                       | As per Consultant             |
| 11)        | Energy management                                     | Yes                  | 100%                       | Solar Water Heating<br>System |
| 12)        | Fire protection and fire safety requirements          | Yes                  | 100%                       | As per Fire NOC               |
| 13)        | Electrical meter room, sub-station, receiving station | Yes                  | 100%                       | As per Consultant             |

CA/95 (CA/95) \* 18039 \*

Yours Faithfully,

Ar. SACHIN SUTAR CA/95/18039