

FORM1 [seeRegulation3]

ARCHITECT'SCERTIFICATE

(To be submitted atthe time of Registration of Ongoing Projectandfor withdrawal of Money from Designated Account)

Date:10-10-2023

To Paranjape Schemes (Construction) Ltd. Pune.

Subject: Certificate of Percentage of Completion of Construction Work of Blue Ridge -THE LOFTS , Plot Bearing / CTS / Survey / Final Plot No.: Survey No.119 Part to 125 plus 15 4 Part to 160 plus 160/2 to 171 plus 173, Plot No.1 at Hinjavadi (CT), Mulshi, Pune, 411057 ;oftheProjecthaving MahaRERARegistration Number P52100000060 being developedby Paranjape Schemes (Construction) Ltd. Pune.

Sir,

IAr. Aniruddha Vaidyahaveundertakenassignmentas Architect/Licensed Surveyor of certifying Percentage of Completion of Construction Work of of Blue Ridge -THE LOFTS , Plot Bearing / CTS / Survey / Final Plot No.: Survey No.119 Part to 125 plus 154Part to 160 plus 160/2 to 171 plus 173, Plot No.1 at Hinjavadi (CT), Mulshi, Pune, 41 1057; the Project having Maha RERA Registration Number P52100000060 being developed by Paranjape Schemes (Construction) Ltd. Pune.

Aniruddha Vaidya & Associates

Architects, Town Planners & Interior Designers 4, Dattaprasad, 1206, B/7, Off J. M. Road, Shivajinagar, Pune 411004 enquiry@avaarchitects.in

- 4, Dattaprasad, 1206, B/7, Off
- enquiry@avaarchitects.in www.avaarchitects.in
- www.avaarchitects.in 020 2553 0420

BasedonSiteInspection,withrespecttoeachoftheBuilding/Wingoftheaforesaid
RealEstateProject,Icertify thatason thedateofthiscertificate, thePercentageof
Workdoneforeachofthebuilding/WingoftheRealEstateProjectasregisteredunderMahaRE
RAis as per table A herein below. The
percentageoftheworkexecutedwithrespecttoeachoftheactivityoftheentirephase is
detailedinTable B.

TABLEA

Sr.No	Tasks /Activity	Percentage ofwork done of "The Loft"
1	Excavation	100%
2	Basement	100%
3	Podiums	99%
4	Stilt floor	100%
5	Slabs of Super Structure	100%
6	Internal walls,Internal Plaster, Floorings , Doors andWindows within Flat/Premises	100%
7	SanitaryFittings withinthe Flat/Premises	98%
8	Staircases,Lifts Wells andLobbies ateach Floorlevel ,OverheadandUndergroundWater Tanks	99%
9	The external plumbingandexternal plaster, elevation,completionofterraces withwater proofing of the Building/Wing	100%

10	Installationof lifts,waterpumps,FireFightingFittingsandEquipmentasperCFONOC,Electricalfittings,m echanical equipment, Compliance to conditions ofenvironment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall andallotherrequirementsasmaybe requiredto complete projectas per specifications in agreement of sale. Any other activities.	95%
11	Overall percentage of completion of the work done for the entire building/wing.	99.30%

TABLE B



S. No	Common areas and	Proposed	Percentageof	Details
	Facilities, Amenities	(Yes/No)	Workdone	
1	Internal Roads	Yes	95%	(Footpath only)
	&Foothpaths			
2	Water Supply	Yes	100%	
3	Sewerage (chamber,	Yes	100%	(No septic Tank)
	lines, Septic Tank ,STP)			
4	Storm Water Drains	Yes	100%	
5	Landscaping &Tree Planting	Yes	95%	
6	StreetLighting	Yes	90%	
7	Community Buildings	No		
8	Treatment and	Yes	100%	STP
	disposal of sewage and			
	sullage water SolidWaste			
9	<u> </u>	Yes	100%	
	management&			
10	Disposal	Yes	100%	
10	Water conservation,	res	100%	
11	Rain water harvesting	No		
12	Energy management	Yes	100%	· · · · · · · · · · · · · · · · · · ·
12	Fire protection and fire safety	163	10070	
	requirements			
13	Electrical meter room,	Yes	100%	
13	sub-station, receiving	103	10070	
	station			
14	Aggregate Area of Recreational open space.	Yes	0%	
15	Open parking	Yes	100%	
16	Club house	No		
17	Swimming pool	Yes	100%	

Yours Faithfully For Aniruddha Vaidya & Associates





