

## FORM1 [seeRegulation3]

## ARCHITECT'SCERTIFICATE

(To be submitted at the time of Registration of Ongoing Projectand for withdrawal of Money from Designated Account)

Date: 26-07-2023

To

Paranjape Schemes (Construction) Ltd.

Subject: Certificate of Percentage of Completion of Construction Work of Blue Ridge -THE LOFTS , Plot Bearing / CTS / Survey / Final Plot No.: Survey No.119 Part to 125 plus 154 Part to 160 plus 160/2 to 171 plus 173, Plot No.1 at Hinjavadi (CT), Mulshi, Pune, 411057 ;oftheProjecthaving MahaRERARegistration NumberP52100000060being developedbyParanjape Schemes (Construction) Ltd. Pune.

Sir,

IAr. Aniruddha Vaidyahaveundertakenassignmentas Architect/Licensed Surveyor of certifyingPercentage of Completion of ConstructionWork of of Blue Ridge -THE LOFTS , Plot Bearing / CTS / Survey / Final Plot No.: Survey No.119 Part to 125 plus 15 4Part to 160 plus 160/2 to 171 plus 173, Plot No.1 at Hinjavadi (CT), Mulshi, Pune, 4110 57; the Project having Maha RERA Registration Number P52100000060 being developed by Paranjape Schemes (Construction) Ltd. Pune.

## Aniruddha Vaidya & Associates

Architects, Town Planners & Interior Designers 4, Dattaprasad, 1206, B/7, Off J. M. Road, Shivajinagar, Pune 411004 enquiry@avaarchitects.in

- 4, Dattaprasad, 1206, B/7, Off
- n enquiry@avaarchitects.in 🐧 www.avaarchitects.in
- www.avaarchitects.in 020 2553 0420

BasedonSiteInspection,withrespecttoeachoftheBuilding/Wingoftheaforesaid
RealEstateProject,Icertify thatason thedateofthiscertificate, thePercentageof
Workdoneforeachofthebuilding/WingoftheRealEstateProjectasregisteredunderMahaRE
RAis as per table A herein below. The
percentageoftheworkexecutedwithrespecttoeachoftheactivityoftheentirephase is
detailedinTable B.

## TABLEA

Sr.No	Tasks /Activity	Percentage ofwork done of "The Loft"		
1	Excavation	100%		
2	Basement	100%		
3	Podiums	95%		
4	Stilt floor	100%		
5	Slabs of Super Structure	100%		
6	Internal walls,Internal Plaster, Floorings , Doors andWindows within Flat/Premises			
7	SanitaryFittings withinthe Flat/Premises			
8	Staircases,Lifts Wells andLobbies ateach Floorlevel ,OverheadandUndergroundWater Tanks	98%		
9	The external plumbingandexternal plaster, elevation,completionofterraceswithwaterproofingof the Building/Wing			
10	Installationof lifts,waterpumps,FireFightingFittingsandEquipmentasperCFONOC,Electricalfittings, mechanical equipment, Compliance to conditions ofenvironment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, CompoundWall and allother requirements as may be required to complete projectas per specifications in agreement of sale. Any other activities.			
11	Overall percentage of completion of the work done for the entire building/wing.	98.40%		

S. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentageof Workdone	Details
1	Internal Roads &Foothpaths	Yes	90%	(Footpath only)
2	Water Supply	Yes	100%	
3	Sewerage (chamber, lines, Septic Tank ,STP)	Yes	100%	(No septic Tank)
4	Storm Water Drains	Yes	100%	
5	Landscaping &Tree Planting	Yes	90%	
6	StreetLighting	Yes	80%	
7	Community Buildings	No	**	
8	Treatment and disposal of sewage and sullage water	Yes	100%	STP
9	SolidWaste management& Disposal	Yes	100%	
10	Water conservation, Rain water harvesting	Yes	100%	
11	Energy management	No	-	-
12	Fire protection and fire safety requirements	Yes	100%	
13	Electrical meter room, sub-station, receiving station	Yes	100%	
14	Aggregate Area of Recreational open space.	Yes	0%	
15	Open parking	Yes	75%	
16	Club house	No	**	
17	Swimming pool	Yes	90%	

Yours Faithfully For Aniruddha Vaidya & Associates

AR.RADHIKA VAIDYA L.S/ Architect

License No CA/85/8968

signature of Promoter

Date:

'P17 (UO'