ANIL M. KULKARNI

Architect

2, Namaskar Apartments, 1204/13 Deccan Gymkhana, Pune-411004 Phone No.020 25535507, Mobile- 94220 01902 E.Mail ID- anil_m_kulkarni@yahoo.com

FORM 1

ARCHITECT'S CERTIFICATE

Date: 26.05.2017

To

The Pegasus Properties Pvt. Ltd. at Plot No. R1/1, R1/2, R1/3, R1/4 at Rajiv Gandhi Infotech Park, Phase-III, Hinjewadi, Pune. 411057.

Subject: Certificate of Percentage of Completion of Construction Work of Symphony – WingB1 & B2 of the 1st Phase of the Project [MahaRERA Registration Number] situated on the Plot bearing Plot no R1/1, R1/2, R1/3, R1/4 demarcated by its boundaries (latitude and longitude of the end points) as below

- 1. 18° 34'36" & 73° 40'50" to the North.
- 2. 18° 34'24" & 73° 19'41" to the South.
- 3. 18° 34'48" & 73° 41'16" to the East.
- 4. 18° 34'45" & 73° 40'48" & 18° 34'24" & 73° 40'47" to the West of Rajiv Gandhi Info tech Park, Phase 3, village Man & Bhoir Wadi, taluka Mulshi, District Pune. PIN 411057, admeasuring 10,100.78 sq. mts as part of total plot 5,60,000.0 sq.mts. area being developed by M/s Pegasus Properties Pvt. Ltd.

Sir,
I Mr. Anil Madhusudan Kulkarni have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of Symphony—Wing B1 &B2 of the 1st Phase of the Project, situated on the plot no. R1/1, R1/2, R1/3, R1/4 of Rajiv Gandhi Infotech Park, Phase 3, Man & Bhoir Wadi taluka Mulshi, District Pune. PIN 411057 admeasuring 10,100.78 sq. mts as part of total plot 5,60,000.0 sq.mts area being developed by M/s Pegasus properties Pvt. Ltd.

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Shri Anil Madhusudan Kulkarni as Architect
- (ii) M/s J.W. Consultants Pvt.Ltd. as Structural Consultant
- (iii) M/s. Unicorn Consultants, as MEP Consultant
- (iv) Shri Milind Kadam as Site-In-Charge

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for Symphony-Wing B1 & B2 of the Real Estate Project as registered vide number - under MahaRERA is as per

table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

| Sr. No | Tasks /Activity | Percentage of work done Symphony - Wing | |
|-----------|---|--|------|
| | | | |
| | | B1 | B2 |
| 1 | Excavation | 100% | 100% |
| 2 | Completion of Plinth | 30% | 100% |
| 3 | Lower Basement | 0% | 100% |
| 4 | Upper Basement | 0% | 100% |
| 5 | 14 number of Slabs of Super Structure | | |
| | Ground floor slab | 0% | 25% |
| | 1sr floor slab | 0% | 0% |
| | 2nd floor slab | 0% | 0% |
| | 3rd floor slab | 0% | 0% |
| | 4th floor slab | 0% | 0% |
| | 5th floor slab | 0% | 0% |
| | 6th floor slab | 0% | 0% |
| | 7th floor slab | 0% | 0% |
| | 8th floor slab | 0% | 0% |
| | 9th floor slab | 0% | 0% |
| | 10th floor slab | 0% | 0% |
| | 11th floor slab | 0% | 0% |
| | 12th floor slab | 0% | 0% |
| | 13th floor slab | 0% | 0% |
| 6 | Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises | 0% | 0% |
| 7 | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises | 0% | 0% |
| 8 | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks | 0% | 0% |
| 9 | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing, | 0% | 0% |
| 10 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, rnechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as rnay be required to Obtain Occupation /Completion Certificate | 0% | 0% |

TABLE-B
Internal & External Development Works in Respect of the entire Registered Phase

| No | Common areas and Facilities, Amenities | Proposed (Yes/No) | Percentage of Work done | Details | |
|-----|---|----------------------|-------------------------------|---|--|
| 1. | Internal Roads & Footpaths | Yes | 0% | Concrete road | |
| 2, | Water Supply | Yes | 0% | M.I.D.C. | |
| 3. | Sewerage (chamber, lines, Septic Tank, STP) | Yes | 0% | STP to be installed | |
| 4. | Storm Water Drains | Yes | 0% | RCC Pipe with Inspection chamber | |
| 5 | Landscaping & Tree Planting | Yes | 0% | Native species preferred | |
| 6. | Street Lighting | Yes | 0% | Combination of solar and grid street lights | |
| 7. | Community Buildings | Yes | 0% | Club house for Indoor games | |
| 8. | Treatment and disposal of sewage and sullage water | Yes | 0% | STP treated water to be used for landscaping | |
| 9. | Solid Waste management & Disposal | No | 0% | OWC to be provided for biodegradable waste, dry waste to be collected by Swatch | |
| 10. | Water conservation, Rain water harvesting | Yes | 0% | Low flow fixtures and RWH pits | |
| 11. | Energy management | Yes | 0% | LED lights in common area | |
| 12. | Fire protection and fire safety requirements | Yes | 0% | FF Tank, hose reel, sprinklers | |
| 13. | Electrical meter room, sub-station, receiving station | Yes | 0% | Meter room provided for each building wing | |
| 14. | Others (Option to Add more) | | 0% | | |

Yours Faithfully

AR. ANIL M. KULKARNI Architects & Designers Reg. No. CA/85/8999