Office No 201, 2nd Floor, Konark Icon, Magarpatta-Kharadi Road, Magarpatta, Hadapsar, Pune - 411028 8888004700 | 8805419700 | 8805619700 | www.atitadmulwar.com | E-Mail :- office@atitadmulwar.com



FORM 1

[see Regulation 3]

ARCHITECT'S CERTIFICATE

Date: 26.10.2023

To, Mr. Eknath Maliba Beldare & Others Sr. No. 46, Hissa No. 09, At. Abmegaon Budruk, Tal. Haveli, Dist. Pune.

Subject: Certificate of Percentage of completion of Construction Work of A wing having MahaRERA Registration Number **P52100015858** (Only Applicable after project Registration) being developed by Mr. Eknath Maliba Beldare & Others.

Sir,

I Atit Admulwar have undertaken assignment as Architect /Licensed Surveyor of certifying percentage of Completion of Construction Work of A wing having MahaRERA Registration Number **P52100015858** only Applicable after project Registration, being developed by Mr. Eknath Maliba Beldare & Others.

Based on Site Inspection, with respect to Layout/ each of the Building/Wing of the aforesaid Real Estate Project. I certify that as on the date of this certificate, the Percentage of work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

ATIT ADMULWA CA / 2008 / 41887

TABLE-ABuilding Number A

Sr. No. (1)	Tasks / Activity (2)	Percentage of Actual Work Done (As on date of the Certificate) (3)
1.	Excavation	100%
2.	Basements (if any)	100%
3.	Podiums (if any)	100%
4.	Plinth	100%
5.	Stilt Floor	100%
6.	Slabs of Super Structure	95%
7.	Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises	80%
8.	Sanitary Fittings within the flat/premises	10%
9.	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	60%
10.	External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	60%
11.	Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFT NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing. Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities.	5%

1 6/2

TABLE-B

Common Areas (Internal and External Development Works) in respect of the Registered
Phase / Project Number

	Pflasi	e / Project Nun	ibei	
Sr.	Common areas and facilities	Proposed	Percentage of	Details
No.	(2)	(Yes /No)	Actual Work	(5)
(1)	V 100	(3)	Done	
			(As on date of the	
			Certificate)	
			(4)	
1.	Internal Roads & Footpaths	yes	-	-
2.	Water Supply	yes	-	-
3.	Sewerage (Chamber, lines, Septic Tank, STP).	yes	-	-
4.	Storm Water Drains	yes	-	-
5.	Landscaping & Tree Planting	yes	-	٠.
6.	Street Lighting	yes	-	
7.	Community Buildings	yes	-	-
8.	Treatment and disposal of sewage and sullage water.	yes	-	
9.	Solid Waste management & Disposal	yes	-	-
10.	Water conservation / Rain water harvesting	yes	-	-
11.	Energy management	yes	-	-
12.	Fire protection and fire safety requirements	yes	-	-
13.	Electrical meter room, substation, receiving station.	yes	-	-
14.	Others (Open Parking.	yes	-	-

ATIT ADMULWAR
CA / 2008 / 41887

Agreed and Accepted by:

Signature of Promoter

Name:- Venkateshwara Construction

Date:

JOB NO:- AA - 241 Profarma/ Rera:- 302

PROJECT: - Sr. No. Sr. No. 46, Hissa No. 09, At. Abmegaon Budruk, Tal. Haveli, Dist. Pune.

OWNER NAME: - Mr. Eknath Maliba Beldare & Others

RERA Certificate.	Rs. 5000/-
Goods & Services Tax 18.00%	Rs. 900/-
Total Amount	Rs. 5,900/-
Rs Five Thousand Nine Hundred Rs Only.	116. 6,000

ATIT ADMULWAR