

### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

#### KARNATAKA REAL ESTATE REGULATORY AUTHORITY

Real Estate ( Regulation& Development ) Rules , 2017)

ARCHITECT'S CERTIFICATE

FORM NO 5- FOR COMPLETED PROJECT

Date: 18.01.2024

RERA NO.: PRM/KA/RERA/1251/446/PR/200226/003311

Project Name: UNITED HIGHLANDS

Promoter Name: UNITED INFRASTRUCTURES

To
The UNITED INFRASTRUCTURES
Sy No.326 and 327, Ammani Bellandur Khane,
Thubarahalli Extn. Road, VarthurHobli,
Bangalore-560087

Subject: Certificate of Completion of Registered Project Construction of UNITED HIGHLANDS on the Plot bearing no Sy No.326 and 327, Ammani Bellandur Khane, Thubarahalli Extn. Road, VarthurHobli, Bangalore-560087.

Sir,

This Certificate is issued in accordance with the Provisions of the Real Estate ( Regulation and Development ) Act, 2016 read with the Karnataka Real Estate ( Regulation and Development ) Rules , 2017.

I Have verified the sanctioned drawing . The work is as per the sanctioned drawing given by the competent palnning Authority with sanctioned Drawing No

I/We Yukti Architects have undertaken assignment as Architect/Engineer of certifying Percentage of Completion of Construction Work of the United Highlands 6 Blocks of the Project, situated on the plot bearing C.N. No./CTS No./Survey no./Final Plot No.326 and 327 Ammani Bellandur Khane village, Thubarahalli Extn Road, VarthurHobli, Bangalore PIN-560087. Admeasuring 12040sq.mts. area beingdeveloped byUnited Infrastructures as per the approvedplan.

Admeasuring 12040sqmts., area being developed by UNITED INFRASTRUCTURES

1. Following technical professionals are appointed by owner / Promoter:-

- (i) M/s /shri/smtSmtYukti Consultants as L.S /Architect;
- (ii) M/s /shri/ Smt Yukti Consultants as structural Consultant
- (iii) M/s /shri/Smt \_\_\_\_NA\_\_\_as MEP Consultant
- (iV) M/s /shri/SmtYukti Consultants as site Supervisor





### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1 148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

Based on the site inspection by Me/we dated 18.01.2024 with respect to each of the Building/wing of the aforesaid Real Estate Project , I Certify that as on the date of issue of this certificate , the work is completed and the occupancy certificate is issued by the planning Authority vide Occupancy certificate Letter No BBMP/ADT/MDP/O.C.NO.20/2022-23 DATED 29.07.2023 also the necessary certificate as specified in the completion format has also been obtained by the promoter based on this and as per site inspection for each of the building /wing of the Real Estate Project as registered vide numberPRM/KA/RERA/1251/446/PR/200226/003311under KRERA is as per table A herein below . The Percentage of the work executed with respect to each of the activity of the entire phase is detailed below.

## Table A Building /Wing NumberA (A1,A2,A3,A4, A5 and A6)work progress mentioned as below.

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1_number of Basement(s) and Plinth	100%
3	NA number of Podiums	NA
4	Stilt Floor	100%
5	5 number completed out of 5 Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
3	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%



### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

	Installation of lifts, water pumps, Fire Fighting Fittings and	100%
	Equipment as per CFO NOC, Electrical fittings to Common Areas,	
	electro, mechanical equipment, compliance to conditions of	
_	environment/CRZ NOC, Finishing to entrance lobby/s, plinth	
	protection, paving of areas appurtenant to Building/Wing,	
10	Compound Wall and all other requirements as may be required to	
	Obtain Occupation/Completion Certificate	

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1_number of Basement(s) andPlinth	100%
3	NA Number of Podiums	NA
4	Stilt Floor	100%
5	5 number of slabs completed out of 5 Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to	100%
	Obtain Occupation/Completion Certificate	





### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1 148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

### Building/WingNumber A3

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	One Number of Stilt floor and Plinth	100%
3	Number of Podiums	NA
4	Stilt Floor	100%
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100
2	One number of Basement(s) and Plinth	100%



### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

3	Number of Podiums	NA
4	Stilt Floor	100%
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100
2	One number of Basement(s) and Plinth	100
3	NA number of Podiums	NA
4	Stilt Floor	100
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%



### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	One number of Basement and Plinth	100%
3	NA number of Podiums	NA
1	Stilt Floor	100%
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
3	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
)	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%



### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

3	Number of Podiums	NA
4	Stilt Floor	100%
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100
2	One number of Basement(s) and Plinth	100
3	NA number of Podiums	NA
1	Stilt Floor	100
5	5 number of Slabs of SuperStructure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%



### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

	Installation of lifts, water pumps, Fire Fighting Fittings and	100%
	Equipment as per CFO NOC, Electrical fittings to Common Areas,	
	electro, mechanical equipment, compliance to conditions of	
	environment/CRZ NOC, Finishing to entrance lobby/s, plinth	
	protection, paving of areas appurtenant to Building/Wing,	
10	Compound Wall and all other requirements as may be required to	
	Obtain Occupation/Completion Certificate	

**Table-B**Internal and External Development Works in respect of the entire Registered Phase/Project.

Sl.No	Common areas and Facilities/ Amenities	Proposed (Yes/No)	Percentage of work done	Details
1	Internal Roads & Footpaths	No	100%	
2	Water Supply	No	100%	
3	Sewerage (Chamber, lines, Septic Tank STP)	Yes	100%	
4	Storm Water Drains	Yes	100%	
5	Landscaping & Tree Planting	Yes	100%	
6	Street Lighting	Yes	100%	
7	Community Buildings	Yes	100%	
8	Treatment and Disposal of sewage and sullage water	Yes	100%	
9	Solid Waste management & Disposal	Yes	100%	
10	Water conservation, Rain water harvesting	Yes	100%	
11	Energy Management	No	NA	
12	Fire protection and fire safety requirements	No	NA	
13	Electrical meter room, sub – station, receiving station	Yes	100%	
14	Others (Add more option)	No	NA	





### ARCHITECTS, ENGINEERS, AND INTERIORS.

#1148, 2nd Floor, 22nd Cross, B.S.K 2ndSTAGE, BANGALORE. - 560070 DATE:

Any other facility/ amenity which has been proposed in Agreement of Sale

SI. No	Facilities/ Amenities	Percentage of work done	Details
1	Park Jogging track, play area	100%	
2			
3			
4			

Yours Faithfully,

SIVA KUMAR. V, B.E., BCC/BL-3.6/E-0336/21-22

No. 82, 1st Floor, 21st Main, B.S.K. II Stage, Bangalore - 560 070.

Place: Bangalore Date: 18/01/2024

\*Note: The same Engineer is responsible for the completion of Project. In case of Change in the Engineer, approval needs to be taken from the Authority.