Date: 04/12/2017

FORM 1 ARCHITECT'S CERTIFICATE

(For Withdrawal of Money from Designated Account)

To, Shri Ninath Bhausaheb Shingade Flat no.1801/1901, Plot no 23 B & C, Sector- 6, Nerul, Navi Mumbai- 400706

Subject: Certificate of Percentage of Completion of Construction Work of 7 No.s of Buildings of the 1st Phase of the Project [P52000009416] situated on the Plot bearing Survey No. 26/5 Demarcated by its boundaries. (Latitude and longitude of the end Points) (73 9 44.91-19 4 22.89, 73 9 41.37-19 4 26.60, 73 9 46.97-19 4 26.56, 73 9 43.87-19 4 25.45, 73 9 41.98-19 4 22.30, 73 9 38.96 -19 4 21.94, 73 9 40.42 - 19 4 24.37) Height 26.20 Mtrs ABOVE GROUND LEVEL, So that the top of the proposed structure when erected shall not exceed 26.82mtrs. (Site elevation) +26.20 Mtrs (height of the structure) i.e 53.02Mtrs ABOVE MEAN SEA LEVEL of Division, village-Chindhran, Taluka-Panvel, District –Raigad, PIN-410206 admeasuring 11198.02 sq.mts area being developed by M/s Konnark Developers.

Sir.

I/Mr. Suhas Gokhale have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 7 Building(s)/—Out of which building no-01, 02, 03 & 06 has three wings and building no-04, 05 & 07 has two wings of the project. Situated on the plot bearing Survey No. 26/5 of village Chindhran taluka Panvel District Raigad PIN 410206 admeasuring 11198.02 sq.mts. area being developed by Shri Ninath Bhausaheb Shingade for M/s Konnark Developers.

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Mr.Suhas Gokhale as Architects and Planner as L.S. / Architect;

- (ii) M/s. Vinit Consultant as Structural Consultant
- (iii) M/s Consolidated Consultant Pvt. Ltd. as MEP Consultant
- (iv) M/s Vilas Waghmare as Site Supervisor.

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered *vide* number P52000009416 under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE-A

Sr. No.	Tasks /Activity	Percentage of
	·	work done
1.	Excavation	100%
2.	Nil number of Basement(s) and Plinth	1
3.	Nil number of Podiums	0%
4.	Stilt Floor	100%
5.	4 number of Slabs of Super Structure	100%
6.	Internal Walls	70%
	Internal Plaster	0%
	Doors and Windows to each of the Flat/Premises.	0%
	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	25%
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	50%
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation /Completion Certificate	0%
10.		0%

Architect & Urban planner

TABLE-A

Sr. No.	Number - 02 Tasks /Activity	Percentag
		e of work
		done
1.	Excavation	100%
2.	Nil number of Basement(s) and 1 No. of Plinth	1
3.	Nil number of Podiums	0%
4.	Stilt Floor	100%
5.	4 number of Slabs of Super Structure	100%
6.	a) Internal Walls	100%
	b) Internal Plaster	100%
	c) Floorings within Flats/Premises	Nil
	d) Doors and Windows to each of the Flat/Premises	10%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	25%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	50%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation /Completion Certificate	0%

Architect & Urban planner

0%

TABLE-A

Sr. No.	Tasks /Activity	Percentage of
DI. 110.	Tuoko / Tuok / T	work done
1.	Excavation	100%
2.	Nil number of Basement(s) and Plinth	1
3.	Nil number of Podiums	0%
4.	Stilt Floor	100%
5.	4 number of Slabs of Super Structure	100%
6.	a) Internal Walls	100%
	b) Internal Plaster	100%
	c) Floorings within Flats/Premises	0%
	d) Doors and Windows to each of the Flat/Premises	10%
7.	Sanitary Fittings within the Flat/Premises, Electrical	25%
	Fittings within the Flat/Premises.	
8.	Staircases, Lifts Wells and Lobbies at each Floor level	90%
	connecting Staircases and Lifts, Overhead and	
	Underground Water Tanks	
9.	The external plumbing and external plaster, elevation,	0%
	completion of terraces with waterproofing of the	
	Building/Wing.	
		00/

Occupation /Completion Certificate TABLE-A

Installation of lifts, water pumps, Fire Fighting Fittings

and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain

Building Number - 04

10.

Building Number - 04				
Sr. No.	Tasks /Activity	Percentage of		
		work done		
1.	Excavation	100%		
2.	Nil number of Basement(s) and Plinth	1		
3.	Nil number of Podiums	0%		
4.	Stilt Floor	100%		
5.	4 number of Slabs of Super Structure	100%		
6.	a) Internal Walls	100%		
	b) Internal Plaster	100%		
	c) Floorings within Flats/Premises	100%		
	d) Doors and Windows to each of the Flat/Premises	10%		
7.	Sanitary Fittings within the Flat/Premises, Electrical			
	Fittings within the Flat/Premises.	25%		

Architect & Urban planner

8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	80%
	Underground Water Tanks	
9.	The external plumbing and external plaster, elevation,	
	completion of terraces with waterproofing of the	50%
	Building/Wing.	
10.	Installation of lifts, water pumps, Fire Fighting Fittings	
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	0%
	Finishing to entrance lobby/s, plinth protection, paving of	
	areas appurtenant to Building/Wing, Compound Wall and	
	all other requirements as may be required to obtain	
	Occupation /Completion Certificate	

TABLE-A

Sr. No.	Tasks /Activity	Percentage of
		work done
1.	Excavation	100%
2.	Nil number of Basement(s) and Plinth	1
3.	Nil number of Podiums	0%
4.	Stilt Floor	100%
5.	4 number of Slabs of Super Structure	100%
6.	a) Internal Walls	100%
	b) Internal Plaster	100%
	c) Floorings within Flats/Premises	85%
	d) Doors and Windows to each of the Flat/Premises	10%
7.	Sanitary Fittings within the Flat/Premises, Electrical	25%
	Fittings within the Flat/Premises.	
8.	Staircases, Lifts Wells and Lobbies at each Floor level	
	connecting Staircases and Lifts, Overhead and	80%
	Underground Water Tanks	
9.	The external plumbing and external plaster, elevation,	
	completion of terraces with waterproofing of the	50%
	Building/Wing.	
10.	Installation of lifts, water pumps, Fire Fighting Fittings	
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	0%
	Finishing to entrance lobby/s, plinth protection, paving of	
	areas appurtenant to Building/Wing, Compound Wall and	
	all other requirements as may be required to obtain	
	Occupation /Completion Certificate	

TABLE-A

Building Number - 06 Percentage of Tasks /Activity Sr. No. work done 100% Excavation 1. 1 Nil number of Basement(s) and Plinth 2. 0% Nil number of Podiums 3. 25% Stilt Floor 4. 0% 4 number of Slabs of Super Structure 5. 0% a) Internal Walls 6. 0% b) Internal Plaster 0% c) Floorings within Flats/Premises 0% d) Doors and Windows to each of the Flat/Premises Sanitary Fittings within the Flat/Premises, Electrical 0% 7. Fittings within the Flat/Premises. Staircases, Lifts Wells and Lobbies at each Floor level 8. 0% connecting Staircases and Lifts, Overhead and Underground Water Tanks The external plumbing and external plaster, elevation, 9. completion of terraces with waterproofing of the 0% Building/Wing. Installation of lifts, water pumps, Fire Fighting Fittings 10. and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, 0% Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation /Completion Certificate

TABLE-A

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	Nil number of Basement(s) and Plinth	100%
3.	Nil number of Podiums	0%
4.	Stilt Floor	25%
5.	4 number of Slabs of Super Structure	0%
6.	a) Internal Walls	0%
	b) Internal Plaster	0%
	c) Floorings within Flats/Premises	0%

Architect & Urban planner

	D.D	0%
	d) Doors and Windows to each of the Flat/Premises	
7.	Sanitary Fittings within the Flat/Premises, Electrical	0%
	Fittings within the Flat/Premises.	
8.	Staircases, Lifts Wells and Lobbies at each Floor level	
ľ	connecting Staircases and Lifts, Overhead and	0%
	Underground Water Tanks	
9.	The external plumbing and external plaster, elevation,	
	completion of terraces with waterproofing of the	0%
	Building/Wing.	
10.	Installation of lifts, water pumps, Fire Fighting Fittings	
	and Equipment as per CFO NOC, Electrical fittings to	
	Common Areas, electro, mechanical equipment,	
	Compliance to conditions of environment /CRZ NOC,	0%
	Finishing to entrance lobby/s, plinth protection, paving of	
	areas appurtenant to Building/Wing, Compound Wall and	
	all other requirements as may be required to obtain	
	Occupation /Completion Certificate	

TABLE-B Internal and External Development Works in respect of the entire Registered Phase.

S.No	Common areas and Facilities ,Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Foothpaths.	Yes	0%	Work under process
2.	Water Supply	Yes	0%	Regularized after occupancy certificate
3.	Sewarage (chamber, lines, Septic Tank, STP).	Yes	0%	Work under progress
4.	Storm Water Drains	Yes	0%	Work under progress
5.	Landscaping& Tree Planting.	Yes	0%	Tree will be provided as per RERA
6.	Street Lighting	Yes	0%	Not required
7.	Community Buildings	No	0%	Not required
8.	Treatment and disposal of sewage and sullage water.	Yes	0%	Work under progress

Architect & Urban planner

9.	Solid Waste management & Disposal.	Yes	0%	Work under progress
10.	Water conservation, Rain water harvesting.	Yes	0%	Work under progress
11.	Energy management	Yes	0%	Work under progress
12.	Fire protection and fire safety requirements	No	Not Applicable	Not required
13.	Electrical meter room, sub-station, receiving station.	Yes	0%	Work under progress
14.	Others (Option to Add more).		Nil	

NOTE-

- 1. The said certificate is issued based on Earthquake stability certificate issued by the Authorised Registered Structure engineer.
- 2. Authorized MEP Consultant Report as the scrutiny of S.W Drainage system water supply, (O.H & U.G tank), Rain water harvesting, sewerage treatment plant for sewerage.
- 3. The certificate is issued based on the site inspection and as per the approved plan. In regard to the quality of the material used and as to stability of the building the architect shall not be held liable or responsible as the same does not fall under the ambit of Architect scope of work.

Yours Faithfully,

Ar. SUHAS GOKHALE (License No. CA/82/6917)

SUHAS R. GOKHALE

Consultant - Urban Planning 5/46,artist Village, Sector - 08 S. M. Pandit Road, CBD Belapur, Navi Mumbai - 400 614